

# **FINAL REPORT**

IPRH Mine Coal Fire December 2005

30<sup>th</sup> December 2005



# Panel Of Inquiry:

Ian Quail

Romeo Prezioso

Production Manager
Mine Operations/Fire Service Co-ordinator
Mine Planning / Engineering
2x12 C Roster H&S Rep.

Martin Raun Peter Chisholm

# TABLE OF CONTENTS

- 1: EXECUTIVE SUMMARY
- 2: PRECAUTIONS TAKEN PRIOR TO THE FIRE
- 3: PROBABLE CAUSE
- 4: **CONSEQUENCES** 
  - 4.1 Safety of Personnel4.2 Plant Damage

  - 4.3 Lost Revenue

# 5: FINDINGS

- 5.1. Emergency Response Protocol
- 5.2. Water Supply
- 5.3. CFA

# **6: <u>RECOMMENDATIONS</u>**

- 6.1. Improve Emergency Response
- 6.2. Improve Fire Fighting Ability
- 6.3. Fire Threat Reduction

# 7: ACTION PLAN

#### **APPENDIX 1 – PHOTOGRAPH HAZELWOOD MINE FIRES**

#### **APPENDIX 2 – WEATHER LOGS**

2A – December 29 2005

2B – December 30 2005

2C – January 1<sup>st</sup> 2006

#### APPENDIX 3 – FIRE REPORT SHEETS

Thursday December 29th 2005 Friday December 30th 2005

#### **APPENDIX 4- COMMUNICATIONS**

#### APPENDIX 5- INTERVIEWED WITNESS STATEMENTS

- 1. Peter Barr and Phil Glover -- CFA
- 2. Tony Basile –MINE OPERATOR
- 3. John Beamish MINE OPERATOR
- 4. Ron Bernardi MINE OPERATOR
- 5. Rod Fleming MINE SHIFT MANAGER
- 6. John O'Bryan MINE F/SERVICE SUPERVISOR

#### <u>APPENDIX 6 – WITNESS STATEMENTS</u>

- 7. Luke Alexander OPERATOR STATION
- 8. Bill Bakker MINE F/SERVICE
- 9. Ron Bennett –STATION
- 10. Peter Brimblecombe MINE MAINT ELECTRICAL ENGINEER
- 11. Russel Camier MINE MAINT MECHANICAL ENGINEER
- 12. Paul Connolly MINE OPERATOR
- 13. Geoff Crisp MINE OPERATOR
- 14. Joe Dickason MINE OPERATOR
- 15. John Janiw MINE OPERATOR
- 16. Stan Kemsley MINE MAINT MECHANICAL ENGINEER
- 17. Nick Koumis MINE OPERATOR
- 18. T. Koostra MINE OPERATOR
- 19. Kevin Lovett MINE SHIFT MANAGER
- 20. Terry McDonald MINE SURVEYOR
- 21. Scott Meadows MINE OPERATOR
- 22. John Morgan MINE F/SERVICE
- 23. Tim Nolan MINE OPERATOR
- 24. Shaun O'Neill MINE SHIFT SUPERVISOR
- 25. Bill Pedder –MINE F/SERVICE SUPERVISOR
- 26. Ian Quail PRODUCTION MANAGER
- 27. Maurice Rice MINE OPERATOR
- 28. Gil Risk MINE OPERATOR
- 29. Daryl Ross MINE OPERATOR
- 30. Trevor Shaw MINE F/SERVICE
- 31. Peter Smith- MINE SHIFT SUPERVISOR
- 32. Lloyd Welch- MINNE OPERATOR
- 33. Shane Williams MINE OPERATOR
- 34. Ian Wood --MINE F/SERVICE

#### 1: EXECUTIVE SUMMARY

At around 3pm on Friday 30<sup>th</sup> December 2005 a major fire had established itself in the South East corner of the Hazelwood Mine fanned by strong NW winds of 35kph gusting up to 70kph and a temperature of 40 Deg C. Fire conditions were extreme.

The fire took hold on the worked out Coal batters between levels 3-5 in the South East Field (SEF), extending down onto the Operational level of D24 which was supplying coal to E/Brix from 7 level.

Whilst on routine patrol and attending to various conveyor faults the C-Roster mine operators (roadrunners) spotted smoke on the South East corner of the mine. (Some 2km away).

Upon closer investigation it appeared to be a fire originating from an old fire hole area between the levels 3 and 5. This coal face is some 30 metres in height and difficult to reach.

F/service were notified via radio immediately, and in turn the fire tanker was dispatched.

With the prevailing weather conditions and as a precautionary measure the tanker was left at the "Ridge Area" a further 5-10mins away from its normal location at the control centre. A fire had started at the "Ridge Area" 2 days prior and had re-ignited a small grass fire from the previous day. Although extinguished this fire still managed to spot and create other smaller fires within its vicinity, which was later discovered to be burning inside the trunk of a tree.

With tanker en-route and fire service personnel on the way from M520 beltshift, the road runners were re-directed to West field conveyors to assist with a conveyor fault due to the urgency of low coal stocks.

The weather at this stage continued to worsen, with the temperature reaching a high of 42 Degrees Celsius, winds averaging 35km/hr gusting at 70km/hr in a North Westerly direction. (See Appendix 2 Report 2B)

With tanker approaching and with fire in sight it was evident to the fire services personnel that the fire was spreading quickly and outside assistance would be required.

The CFA were notified immediately and message broadcast over the open radio channel for all non-essential operational personnel to assist with fire fighting.

CFA, RTL and mine personnel responded quickly but due to Xmas/new year holiday period, personnel numbers were very limited at first.

Calls were then made to employees at home or on leave and gradually fire crews and relief crews were established.

Attempts were made to fight the fire with a helicopter (Water Bomber) but after the third attempt this proved to be futile and was called off. (See appendix 1 Mine Fire Photos)

CFA Fire crews along with IPRH personnel continued to fight the fire for the rest of the day and into the night with the main objective being containment.

The weather conditions for Saturday were still unfavourable (See Appendix 2 Report 2C) and with the fire fighting resources well established the fire was contained but still required rotation of Fire Crews over the next 3 days. By late Saturday the fire fighters managed to contain the fire within a designated area until it was fully extinguished. The CFA withdrew their resources at 1515 hrs on Sunday 1 January 2006, after 48 hrs fire fighting.

Due to an ongoing fire in the states Region 10 (Stradbroke) CFA crews from the Latrobe Valley who are familiar with Coal Mine Fires could not attend and CFA crews from the states Region 8 Western district were sourced. These crews although very competent on fighting bush and scrub fires appeared a little unsure and hesitant at how to attack a coal fire.

At its peak, approx 100 men were fire fighting (50 CFA, 50 Mine, Station and RTL) as well as 15 CFA fire trucks and 4 IPRH/RTL Fire tankers.

Crane mounted monitors were very successful in fighting fires especially in the high coal batters. They proved to be a vital asset although difficult to initially set up and get running they enable fire-fighting crews to attack the fire high up in the coalface and allow access to some areas, which were restricted to fire tankers due to narrow coal benches.

Plant damage was minimal with 6.6kv cable burnt and various percolating hoses either burnt or damaged.

Fire fighting continued for the next 3 days from the initial outbreak and mopping up exercises extended for a further 4 days by IPRH employees.

Although extensive the fire did not threaten the Operational Faces of the West Field impacting only on the coal supply to E/Brix. This was quickly overcome with the use of Haul trucks road loading until the fire was extinguished and minor repair to plant completed.

E/Brix dredger dug coal supply resumed on the 3/1/06 with de-commissioning of M241 and M20's series coal conveyors starting on the 4/1/06.

IPRH employees are to be commended for their efforts in responding and fighting the fire over a prolonged period.

#### 2: PRECAUTIONS TAKEN PRIOR TO THE FIRE

- Annual fire training to all Mine Personnel and relevant contractors had been carried out and completed by late DEC 2005.
- Completion of Annual Fire Mitigation works, slashing, grazing layout, and mulch mowing was 90% complete.
- Inspection and monitoring of "slip on" fire tankers is occurring on a fortnightly basis during the fire season.

- Visual inventory of fire fighting equipment was completed before the fire season.
- All maintenance had been carried out on all critical fire service pumps and major pipelines prior to the fire season.
- Mobile water tanker units are available and provision made for additional back-up mobile water supplies during days of extreme weather conditions.

#### 3: PROBABLE CAUSE

A Fire Hole on the worked out Coal batters between levels 3-5 in the SEF proved to be the probable cause of the ignition. The fire hole, a known hot spot, was fanned by strong NW winds and extreme temperature..

#### 4: CONSEQUENCES

#### 4.1 Safety of Personnel

The most important outcome regarding the fire was that it was fought in a safe manner and that as a consequence there were no serious injuries apart a few minor first aid treatment injuries. i.e. dust in eyes-fatigue and two CFA Fire Fighters were taken to hospital suffering fatigue.

#### 4.2 Plant Damage

D24 conveyor power cables – minor electrical damage Numerous Percolating were either burnt or damaged during the fire.

#### 4.3 Lost Revenue

There was no loss of coal supply to Hazelwood Power Station resulting from the fire. Revenue Losses incurred were Coal supply loss to E/Brix and requirement for road carting for three days at approx

Costs associated with fighting the fire –Supplies, Equipment and Additional Personnel and overtime are estimated at

#### 5: FINDINGS

# 5.1 Emergency Response Protocol

Initial delays and lack of communication between the CFA commander and IPRH incident controller led to confusion amongst the fire fighting crews in the early stages of the fire fight—this was quickly resolved within the first few hours of the emergency.

Support over a prolonged period was maintained and in line with the IPRH Emergency response plan.

The Emergency Control Point was set up at the Mine Control Centre which for a small event would be sufficient. In this case there were too many distractions with the day to day operations and the Emergency Control Point should have been set up away from the Control Centre.

Senior management, media, employees and Government were kept regularly updated via emails from the Mining Director.- see Appendix 4.

Overall the Emergency Response Plan worked well.

#### 5.2 Water Supply

Water supply was reliable and ample within the designated fire area, although further consideration should be given to ease of access, location and reliability of water supply in other worked out sections of the mine, specifically the northeastern batters of the mine.

#### **5.3 CFA**

CFA response was quick, effective and well organised.

Comments from many of the witness statements referred to inexperience of CFA in fighting coal fires – mainly attributed to the Region 8 volunteers, who many had never seen a coal mine.

#### 6: RECOMMENDATIONS

#### 6.1 Improve Emergency Response Procedures

#### 6:1.1 Emergency Control Point

The Emergency Control Point is to be set up away from the Mine Control Centre. Suitable locations are Mine Training Centre, or Fire Service Office.

#### 6:1.2 Radio Communications

A fully equipped multi-channel communications system currently exists within the mine but is still creating confusion amongst many operators. To be reviewed and updated if required and additional training for employees. Also an open channel should be investigated such that all responding can hear what is going on.

#### 6:1.3 Communications with the CFA

Communications with the CFA whilst they are on site is via a mobile phone which creates difficulty for those at the fire front. As part of the communications review, evaluate if an open channel could be used by all CFA and IPRH personnel.

## 6.2 Improve Fire Fighting Ability

#### 6:2.1 Vehicle Access

All access roads internal to the mine and on the perimeter should at all times be kept clear for emergency use and accessible to all fire fighting plant.

#### 6:2.2 Crane Monitors

Review of exist crane monitors to be conducted with the possibility of Improving or upgrading their current use and function. Requirement to have sufficient crane monitors to reach from top of coal to base of coal faces (worst case) which can be fitted to any crane.

#### 6:2:3 Soaker Hoses

Investigate the possibility of canvas soaker hoses which could be layed down the length of batters and used as soaker hoses assisting fire fighting crews prior or during a fire emergency.

#### 6:2:4 Mobile Tankers - "Slip On" Tank - Mercedes

The small "slip on" tanker experienced various problems throughout the fire emergency breaking down on numerous occasions and frustrating fire crews. Although very effective when in operation it cannot undergo any further maintenance and will require replacing in the very near future.

The water pressure of the larger Mobile Fire Tanker normally stationed at the Control Centre was incapable of reaching the high batter faces. Existing pump to be reviewed and upgraded accordingly.

#### 6:2.5 Mutual Aid Arrangements

Due to the propensity of a coal mine fire to last for several days, and the need for additional resources once all IPRH resources have been used, mutual aid agreements need to be up to date. Specifically assistance from Loy Yang B should be included in the Emergency Response procedures.

# 6:2.6 Training of CFA

Increased awareness training of CFA incident controllers for fighting a coal fire. Specifically need to brief neighboring regions (8,9 &10) who will be used when during a prolonged event.

#### 6:2.7 Mutual Teams

Discuss with the CFA of setting up mutual teams consisting of CFA and IPRH resources. The aim is to ensure familiarity of the fire fighting crews and ensure site conditions and safety issues are well understood by those who are not familiar.

#### 6:2.8 Use of Helicopter

The use of the helicopter dumping water on the fire proved to make the situation worse and spread the fire due to fine coal dust present along the coal faces. Discuss with the CFA and advise the use of a helicopter is no good on a coal fire.

#### 6.3 Fire Threat Reduction

#### 6:3.1 Clay Covered Batters / Worked Out Coal Batters

Where ever practically possible fire break zones extending down the full depth of each batter may be utilised such that the length of exposed coal in any one batter is not greater than 500m. These zones can be in the form of metalled vehicle access ramps or clay covering a minimum of 8m wide.

# 6:3.2 Improved Fire Training

Develop a Fire Training Facility with the capacity to annually train all IPRH Mine employees, Mine Alliance partners and contractors in practical fire fighting. This facility could also be utilised by CFA officials for training of their members.

## 7: ACTION PLAN

The recommendations are to be reviewed by management and agreed recommendations will be implemented.

For each action and "Opportunity for Improvement" will be raised in Paradigm.

An appropriate IPRH manager will be assigned responsibility for the implementation of the required action. Agreed deadlines for completion will be set.


The Safety Management Audit Committee (SMAC) will monitor progress on the implementation of the agreed actions.


# **APPENDIX 1 – Mine Fire Photos**




# **APPENDIX 2 – Weather Logs**


# Weather Report 2A – Thursday 29<sup>th</sup> December 2005










# Weather Report 2B – Friday 30<sup>th</sup> December 2005









# Weather Report 2c –Saturday 31st December 2005







# <u>APPENDIX 3 – Fire Report Sheets</u>

# Thursday December 29th 2005 - Appendix 3A

			LIAZELIA/OV	D POWER	COLOURED Original Section Records GREEN Displicate Contracts/Fire Engineer FIRK Tiplicate C.F.A.
				REPORT FORM	<b>A</b> 0852
4 EXE	almanii	sion: 1//ss/	DISCOVERED BY:		TIME ATTENDED:
DAY	DATE:	TANK DAY TAKARAT	HIS/HER CONTACT	No.	TIME EXTINGUISHED:
DIS	COVES	YALARM TIME A LALL FIRE SERVIC	ESÆMERGENCY SI	ERVICES NOTIFIED AT	HAS TIME COMPLETED:
-	Tennesteries	LOCATION Item No. or Nos. Plant item			
	1	Gredger No. Brig.	9   Control Room	Building	17 Store
-	8	2 Conveyor No. Frame/Unit No.	10 Transformer N	0.	18 Workshap
-	WHERE WAS	3 Raw Coal Bunker 4 Crusher/Transfer House	11 Power Pole N 12 Ancillary Insta	2. Line No.	19 Machinary/Plant Room
	24E	5 Station Bunker		liation, Open Cut	20 Mess Room/Canteen/Kitchen 21 On or Near Roadway
	-	6 Boiler Plant No.	14 Auxiliary Fuel	Installation	22 Vehicle or Mobile Plant
le		7 Turbine/Generator Plant No. 8 Electrical Annexe/Cable Chamber	15 Transmission I 16 Office	Facility	23 IGREOCOMOTIVE
O.	90	MATERIAL Item No or Nos Description			24 OTHER (SPECIFY)
PELIMINARY FIRE REPORT	WHAT WAS BUPINING	ON FIRE	Antistrania de espeia de grande de la france	Name and the second of the sec	
BR:	WHA BUS	25 Coal/PF 27 Cabling 28 Briquettes 28 Betting 3	29   Oil, Flam. Liq. 30   Gas	31 Rubbish 32 Furnishing	33 Elect Equip   35 Grass/Scrub   34 Lagging/Insulation   36 Other (Specify)
25	i ii	PROBABLE Item No. or Nos Description		1 az i vumannığ	34 Lagging/Insulation 36 Other (Specify)
NAF	WHAT WAS THE PROBABLE CAUSE	CAUSE // /			and the state of t
×	WA	37   Hot Work (Welding, Cutting, Grinding)   38   Friction Brake (Vehicle, Loco, Conv. Drum)	41 Friction (B)	H/Machinery Rubbing)	45 Smoking 46 Sparks from Boiler
RE	VH/AT IOBA	39 Hot Engine of Exhaust	43 Electrical F	ault (Short/Arcing/Overload	47 Unknown
a.	7 5	t 90 Conabsed of Seized Meaning	4.6 - 5.05000000000	NO E CONTRACTOR CONTRACTOR	AR Other (Opening
	THE	DEXTINGUISHED Number of HP. Personnel At No. of CFA Personnel attent	tending rise: 55 Jina fires:	No. of Contract En	ergency Services personel attending fire
	1	two, or construction and annear	and are a mer drag	visation's name: 🕾 🛒	
	↓ DAM	AGE? Yes No De			
	1	and a state of the contract of the state of	- L		
e de company de la company e	This	Section of Recort Completed by	57.57.66.57		Contact No.
	WHIC	Section of Report Completed by And Section of Report Completed by	ING FACTOR OF M	ORE THAN ONE CAUSE	Contact No.
<b>*****</b>	WHI(	Section of Report Completed by H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect F	ING FACTOR: (IF M	berately Set etc.)	EXPLAIN)
	WHI0 49 50 51	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect P Human Inaction (Insulficient Precautions, Spill Equipment Meffunction (Seized of Collabased B	ING FACTOR (IF M Plant Operation, Deli Not Removed, Poor earing, Control Failu	berately Set etc.) Housekeeping, Poor Maint re, Short Circuit etc.)	EXPLAIN)
	WHI0 49 50 51 52	Section of Report Completed by  CH OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect Fituman Inaction (Insufficient Precautions, Spill Fupipment Melfunction (Seized or Collapsed Bi Dosign (Engine Exhaust Loco Brakes, Coal Duat	ING FACTOR: (IF M lant Operation, Deli Not Removed, Poor earing, Control Falls Ignited by Heat from	berately Set etc.) Housekeeping, Poor Maint re, Short Circuit etc.) Light Pixtures etc.)	EXPLAIN)
	WHIC 49 50 51 52 53	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect F Human Inaction (Insufficient Precautions, Spill Guipment Matfunction (Seized or Collapsed B, Oseign (Engine Exhaust Loco Brakes, Cost Dust Severomental (High Winds, Rain, Lighthing, S)	ING FACTOR: (IF M lant Operation, Deli Not Removed, Poor earing, Control Falls Ignited by Heat from	berately Set etc.) Housekeeping, Poor Maint re, Short Circuit etc.) Light Pixtures etc.)	EXPLAIN)
39.T	WHIC 49 50 51 52 53	Section of Report Completed by  CH OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect Fituman Inaction (Insufficient Precautions, Spill Fupipment Melfunction (Seized or Collapsed Bi Dosign (Engine Exhaust Loco Brakes, Coal Duat	ING FACTOR: (IF M lant Operation, Deli Not Removed, Poor earing, Control Falls Ignited by Heat from	berately Set etc.) Housekeeping, Poor Maint re, Short Circuit etc.) Light Pixtures etc.)	EXPLAIN)
EPORT	WHI6 49 50 51 52 53 Item	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, Incorrect F Human Inaction (Insufficient Precessions, Spill Equipment Melfunction (Seized of Collapsed B Design (Engine Exhaust Loco Brakes, Coal Dust Environmental (High Winds, Rain, Lightning, S) No. Details: 1/4/2/2/24	ING FACTOR: (IF M lant Operation, Deli Not Removed, Poor earing, Control Falls Ignited by Heat from	Derstely Set etc.) Housekeeping, Poor Maint re, Short Circuit etc.) Light Foxtures etc.) tion in Briquettes etc.)	EXPLAIN) enance etc;
Y REPORT	WHILE 49 50 51 52 53 Item	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect F Human Inaction (Insufficient Precessions, Spili Equipment Metfunction (Seized of Cofabrised B Design (Engine Exhaust, Loco Brakes, Coal Dust Existronmental (High Winds, Rain, Lightning, S) No. Details: Law (March 1)  WAS THE FIRE EXTINGUISHED	ING FACTOR: (IF M lant Operation, Deli Not Removed, Poor earing, Control Falls Ignited by Heat from	Derstely Set etc.) Housekeeping, Poor Maint re, Short Circuit etc.) Light Foxtures etc.) tion in Briquettes etc.)	EXPLAIN)
	######################################	Section of Report Completed by  CH OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect Fituman Inaction (Insufficient Precautions, Spill Futuman Inaction (Seized or Collaboration of Collaboration (Insufficient Programmental (High Winds, Rain, Lightning, Sp. No. 2 Details: LANGEROWS  WAS THE FIRE EXTINGUISHED  CK LIST (Tick)	ING FACTOR: (IF M lant Operation, Deli Not Removed, Poor earing, Control Falls Ignited by Heat from	Derstely Set etc.) Housekseping, Poor Mainte, Short Circuit etc.) Light Fotures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E	EXPLAIN) enance etc.;  ###################################
	WHIGH	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Maffunction (Seized of Collapsed B Design (Engine Exhaust Loco Brakes, Cost Dust Environmental (High Winds, Rain, Lightning, S)  No. Details: LAA COCCA  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Guipp Suitable, Type, Quantity, Location?	ING FACTOR: (IF M l'ant Operation, Del Not Removed, Poor asting, Control Falla Igniled by Heat from contaneous, Combus	Derstelly Set etc.) Housekeeping, Poor Mainte, Short Circuit etc.) Light Fixtures etc.) tion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours	EXPLAN) enance etc.)  ESPLAND  STIMATE (APPROXIMATION ONLY)
	HOW CHE Fire I	Section of Report Completed by  CH OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect F fluman Inaction (Insulficient Precautions, Spili Equipment Melfunction (Seized or Collapsed B Design (Engine Exhaust Loco Brakes, Coal Dust Environmental (High Winds, Rain, Lightning, S) No.   Details: LANCHOLOW  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) quip, Suitable, Type, Quantity, Location?  quip, Replaced, Reset, Refurbished?  Sprilate People Notified	ING FACTOR: (IF M l'ant Operation, Del Not Removed, Poor asting, Control Falla Igniled by Heat from contaneous, Combus	Derstely Set etc.) Housekseping, Poor Mainte, Short Circuit etc.) Light Fotures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E	EXPLAIN)  enance et.)  Estate  Stimate (APPROXIMATION ONLY)
SUPERVISORY REPORT	HOW  CHE Fire I Approx	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Maffunction (Seized of Collapsed B Design (Engine Exhaust Loco Brakes, Cost Dust Environmental (High Winds, Rain, Lightning, S) No. Details:  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Guipp, Suitable, Type, Quantity, Location? Guip, Suitable, Type, Quantity, Location? Spilite People Notified gency Procedures Followed	ING FACTOR: (IF M l'ant Operation, Del Not Removed, Poor asting, Control Falla Igniled by Heat from contaneous, Combus	perately Set etc.) Housekeeping, Poor Maintre, Short Circuit etc.) Light Folkures etc.) tion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Pitart Hot, Expended Suppression f Restoration Materials	EXPLAIN)  enance et.)  Estate  Stimate (APPROXIMATION ONLY)
	HOW  CHE Fire I Approx	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, Incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Meffunction, (Seized of Cofdapsed B Design (Engine Exhaust, Loco Brakes, Coal Dust Environmental (High Winds, Rain, Lightning, S) No. Details:  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Equip, Suitable, Type, Quantity, Location? Guip Replaced, Reset, Refurbished? Spirite People Notified gency Procedures Followed Report Forwarded	ING FACTOR: (IF M l'ant Operation, Del Not Removed, Poor asting, Control Falla Igniled by Heat from contaneous, Combus	perately Set etc.) Housekaseping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Hot, Expended Suppression I Ressoration Materials Ressoration Manhours	enance etc.)  SERVER (APPROXIMATION ONLY)  Meterials
	HOW  CHE Fire I Approx	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Maffunction (Seized of Collapsed B Design (Engine Exhaust Loco Brakes, Cost Dust Environmental (High Winds, Rain, Lightning, S) No. Details:  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Guipp, Suitable, Type, Quantity, Location? Guip, Suitable, Type, Quantity, Location? Spilite People Notified gency Procedures Followed	ING FACTOR: (IF M l'ant Operation, Del Not Removed, Poor asting, Control Falla Igniled by Heat from contaneous, Combus	perately Set etc.) Housekeeping, Poor Maintre, Short Circuit etc.) Light Folkures etc.) tion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Pitart Hot, Expended Suppression f Restoration Materials	EXPLAIN)  enance et.)  Estate  Stimate (APPROXIMATION ONLY)
	HOW  CHE Fire I Approx	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, Incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Meffunction, (Seized of Cofdapsed B Design (Engine Exhaust, Loco Brakes, Coal Dust Environmental (High Winds, Rain, Lightning, S) No. Details:  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Equip, Suitable, Type, Quantity, Location? Guip Replaced, Reset, Refurbished? Spirite People Notified gency Procedures Followed Report Forwarded	ING FACTOR: (IF M l'ant Operation, Del Not Removed, Poor asting, Control Falla Igniled by Heat from contaneous, Combus	perately Set etc.) Housekaseping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Hot, Expended Suppression I Ressoration Materials Ressoration Manhours	enance etc.)  SERVER (APPROXIMATION ONLY)  Meterials
	HOW  CHE Fire I Approx Enter Fire F Coms	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, Incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Melfunction (Seized of Coldapsed B Design (Engine Exhaust, Loco Brakes, Coal Dust Environmental (High Winds, Rain, Lightning, S) No. Details  WAS THE FIRE EXTINGUISHED  WAS THE FIRE EXTINGUISHED  CQUIP, Suitable, Type, Quantity, Location?  Quip, Replaced, Reset, Refurblahed?  Spirate Feople Notified gency Procedures Followed  Report Forwarded  Inents:	ING FACTOR: (IF M Pant Operation, Det Not Removed, Poor saring, Control Falls grained by Heat from containeous Combus  YES NO	perately Set etc.) Housekaeping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Ho, Expended Suppression in Restoration Manhours Comments	enance etc.)  STIMATE (APPROXIMATION ONLY)  If State of the state of t
	WHIC 49 50 51 51 52 53 item HOW CHE Fire I Approx Emer	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, Incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Meffunction, (Seized of Coldapsed B Design (Engine Exhaust, Loco Brakes, Coal Dust Exwormental (High Winds, Rain, Lightning, S) No. Details  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Equip, Suitable, Type, Quantity, Location? Iquip, Suitable, Type, Quantity, Location? Iquip, Replaced, Reset, Refurbished? Iquip, Suitable, Type, Oluantity, Location? Iquip, Replaced, Reset, Refurbished? Iquip, Suitable, Type, Oluantity, Location? Iquip, Replaced, Reset, Refurbished? Iquip, Suitable, Type, Oluantity, Location? Iquip, Replaced, Reset, Refurbished? Iquip, Suitable, Type, Oluantity, Location? Iquip, Replaced, Reset, Refurbished? Iquip, Suitable, Type, Oluantity, Location? Iquip, Replaced, Reset, Refurbished? Iquip, Suitable, Type, Oluantity, Location? Iquip, Replaced, Reset, Refurbished? Iquip, Suitable, Type, Oluantity, Location? Iquip, Replaced, Reset, Refurbished? Iquip, Replaced, Reset, Refurbished.	ING FACTOR: (IF M Pant Operation, Det Not Removed, Poor saring, Control Falls grained by Heat from containeous Combus  YES NO	perately Set etc.) Housekaseping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Ho. Expended Suppression in Manhours Comments  Phorie Name	enance etc.)  STIMATE (APPROXIMATION ONLY)  Its Adjectab  Date 71/2 1/3
SUPERVISORY	WHIC 49 50 51 51 52 53 Item HOW CHE Fire I Approx Emeri	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect F Human Inaction (Hot Work, Smoking, incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Maffunction (Seized of Collapsed B Design (Engine Exhaust Loco Brakes, Cost Dust Environmental (High Winds, Rain, Lightning, S)  No. Details: LANGUSHED  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Guip Suitable, Type, Quantity, Location? Guip Replaced, Reset, Refurbished?  priate Paople Notified gency Procedures Followed Report Forwarded Inents:  PONSIBLE OFFICER Title  UAL COSTS  PORT WO No	ING FACTOR: (IF M Pant Operation, Det Not Removed, Poor saring, Control Falls grained by Heat from containeous Combus  YES NO	perately Set etc.) Housekaseping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Ho. Expended Suppression in Manhours Comments  Phorie Name	enance etc.)  STIMATE (APPROXIMATION ONLY)  If State of the state of t
SUPERVISORY	HOW  CHE Fire I Approx Emes Fire F Coms  RES LABC	Section of Report Completed by  CH OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, Incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Meffunction (Seized of Coldapsed B Design (Engine Exhaust, Loco Brakes, Coal Dust Environmental (High Winds, Rain, Lightning, S) No. Details  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Equip. Suitable, Type, Quantity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Quantity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Ouenfity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Re	ING FACTOR: (IF M Pant Operation, Det Not Removed, Poor saring, Control Falls grained by Heat from containeous Combus  YES NO	perately Set etc.) Housekaseping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Ho. Expended Suppression in Manhours Comments  Phorie Name	enance etc.)  STIMATE (APPROXIMATION ONLY)  Its Adjectab  Date 71/2 1/3
SUPERVISORY	HOW  CHE Fire I Approx  RES  ACA  ACA  LABE MATI	Section of Report Completed by ASS A CONTRIBUT Human Action (Hot Work, Smoking, Incorrect Phuman Inaction (Insufficient Precautions, Spill Flumen Inaction (Insufficient Section (Insuf	ING FACTOR: (IF M Pant Operation, Det Not Removed, Poor saring, Control Falls grained by Heat from containeous Combus  YES NO	perately Set etc.) Housekaseping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Ho. Expended Suppression in Manhours Comments  Phorie Name	enance etc.)  STIMATE (APPROXIMATION ONLY)  Its Adjectab  Date 71/2 1/3
REPORT SUPERVISORY	HOW  CHE Fire I Fire I Coms  RES  ACT PASS LABA MATI PLAN PRO	Section of Report Completed by  CH OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Melfunction (Seized of Collapsed B Design (Engine Exhaust Loco Brakes, Coat Dust Environmental (High Winds, Rain, Lightning, S) No. Details  WAS THE FIRE EXTINGUISHED  WAS THE FIRE EXTINGUISHED  CQUIP, Suitable, Type, Quantity, Location?  Iquip, Su	ING FACTOR: (IF M Pant Operation, Det Not Removed, Poor saring, Control Falls grained by Heat from containeous Combus  YES NO	perately Set etc.) Housekaseping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Ho. Expended Suppression in Manhours Comments  Phorie Name	enance etc.)  STIMATE (APPROXIMATION ONLY)  Its Adjectab  Date 71/2 1/3
REPORT SUPERVISORY	HOW  HOW  HOW  CHE Fire I Approx  ACT  ACT  LABC  LABC  MATT  PLAN  TOTA	Section of Report Completed by Assaction of Report Completed by Assaction of THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, Incorrect Prumen Inaction (Insufficient Precautions, Spiliticular of Complete Processing) (Engine Exhaust Loco Brakes, Coal Duat Environmental (High Winds, Rain, Lightning, S) No.   Details: Landward Coal Details: Landward Coal Duat Environmental (High Winds, Rain, Lightning, S) No.   WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Equip, Suitable, Type, Quantity, Location? Guip Replaced, Reset, Refurbished? Spilite People Notified gency Procedures Followed deport Forwarded ments:  PONSIBLE OFFICER Title  UAL COSTS FORT W/O NO DUR  BIALS IT DUCTION	ING FACTOR: (IF M Pant Operation, Det Not Removed, Poor saring, Control Falls grained by Heat from containeous Combus  YES NO	perately Set etc.) Housekaseping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Ho. Expended Suppression in Manhours Comments  Phorie Name	enance etc.)  STIMATE (APPROXIMATION ONLY)  Its Adjectab  Date 71/2 1/3
REPORT SUPERVISORY	HOW HOW HOW HOW HOW CHE Fire I Approx Emer Emer Emer LABG MATT PASS LABG MATT PRO TOTA	Section of Report Completed by  CH OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, Incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Meffunction, (Seized of Coldapsed B Design (Engine Exhaust, Loco Brakes, Coal Dust Environmental (High Winds, Rain, Lightning, S) No. Details  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Equip. Suitable, Type, Quantity, Location? Iquip. Suitable, Type, Quantity, Location? Iquip. Suitable, Type, Quantity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Oluentity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Quantity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Oluentity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Oluentity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Replaced, Reset, Refurbished? Iquip. Replaced, Reset, Refurbished? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Quantity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Quantity, Location? Iquip. Replaced, Reset, Refurbished? Iquip.	ING FACTOR: (IF M Pant Operation, Det Not Removed, Poor saring, Control Falls grained by Heat from containeous Combus  YES NO	perately Set etc.) Housekaseping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Ho. Expended Suppression in Manhours Comments  Phorie Name	enance etc.)  STIMATE (APPROXIMATION ONLY)  Its Adjectab  Date 71/2 1/3
SUPERVISORY	HOW HOW HOW HOW HOW CHE Fire I Approx Emer Emer Emer LABG MATT PASS LABG MATT PRO TOTA	Section of Report Completed by  H OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, incorrect F Human Inaction (Hot Work, Smoking, incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Malfunction (Seized of Collapsed B Design (Engine Exhaust Loco Brakes, Cost Dust Environmental (High Winds, Rain, Lightning, S)  No. Details: LAAAAAAAA  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Guip Suitable, Type, Quantity, Location? Guip Replaced, Reset, Refurbished?  printe People Notified gency Procedures Followed Report Forwarded Inents:  PONSIBLE OFFICER Title  UAL COSTS  PORT W/O NO  DUR  EHRALS  IT  DUCTION  SET COMPLETION DATE	ING FACTOR: (IF M Pant Operation, Det Not Removed, Poor saring, Control Falls grained by Heat from containeous Combus  YES NO	perately Set etc.) Housekaseping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Ho. Expended Suppression in Manhours Comments  Phorie Name	enance etc.)  STIMATE (APPROXIMATION ONLY)  Its Adjectab  Date 71/2 1/3
REPORT SUPERVISORY	HOW  HOW  CHE Fire I Fire I Appr Coms  ACT PASS LABCT P	Section of Report Completed by  CH OF THE FOLLOWING WAS A CONTRIBUT Human Action (Hot Work, Smoking, Incorrect F Human Inaction (Insulficient Precautions, Spili Guipment Meffunction, (Seized of Coldapsed B Design (Engine Exhaust, Loco Brakes, Coal Dust Environmental (High Winds, Rain, Lightning, S) No. Details  WAS THE FIRE EXTINGUISHED  CK LIST (Tick) Equip. Suitable, Type, Quantity, Location? Iquip. Suitable, Type, Quantity, Location? Iquip. Suitable, Type, Quantity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Oluentity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Quantity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Oluentity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Oluentity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Replaced, Reset, Refurbished? Iquip. Replaced, Reset, Refurbished? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Quantity, Location? Iquip. Replaced, Reset, Refurbished? Iquip. Suitable, Type, Quantity, Location? Iquip. Replaced, Reset, Refurbished? Iquip.	ING FACTOR: (IF M Pant Operation, Det Not Removed, Poor saring, Control Falls grained by Heat from containeous Combus  YES NO	perately Set etc.) Housekaseping, Poor Maintre, Short Circuit etc.) Light Fixtures etc.) Ion in Briquettes etc.)  PRELIMINARY COST E Suppression Manhours Vehicle/Mobile Plant Ho. Expended Suppression in Manhours Comments  Phorie Name	enance etc.)  STIMATE (APPROXIMATION ONLY)  Its Adjectab  Date 71/2 1/3

# Friday December 30th at 3:15pm2005 Appendix 3B

			COLOURED ORIGINAL Section Records GREEN Diplomate Contracts Fine Engineers Park
			ANDARD FIRE REPORT FORM A 085
Amir	A 187433 (11)	308: <u>- 1.                                  </u>	DISCOVERED BY 24/2 TIME ATTENDED
	DATE	(A)	HIS/HER CONTACT No. TIME EXTINGUISHED:
			TICES/EMERGENCY SERVICES NOTIFIED AT 15 HRS. TIME COMPLETED:
			m No., Description or Standard Plant Abreviation No.
		ALAH KAN	
		Credger No./Brig.     Conveyor No. Frame/Unit No.	9   Control Room/Building   17   Store
	ME	3 Raw Coal Bunker	11 Power Pole No. Line No. 19 Machinary/Plant Room
	WHERE WAS	4 Crusher/Trensfer House	12 Ancillary installation. Open Cut 20 Mess Room/Canteen/Kitchen
10	WE	5 Station Burker 6 Doller Plant No.	13   Ancillary Installation, Power Station   21   On or Near Roadway     14   Auxiliary Fuel Installation   22   Vehicle or Mobile Plant
-		6 Goller Plant No. 7 Turbine/Generator Plant No.	15 Transmission Facility   23   ICRLOQOMOTIVE
F		8 Electrical Annexe/Cable Chamber	16 Office 24 OTHER (SPECIFY)
8	NAS	MATERIAL   Hem No. or Nos.   Descripti ON FIRE	on
PELIMINARY FIRE REPORT	WHAT WAS BURNNE	25 Coal/PF 27 Cabling	29 Oil, Flam, Liq.   31   Rubbish   33   Elect: Equip.   38   Grass/Scrub
FIR	30	26 Briquettes 28 Belting	30 Gas 32 Furnishing 34 Lagging/Insulation 36 Other (Specif
Æ	S THE CAUSE	PROBABLE Item No. or Nos. Descripti CAUSE	
AIN	1 88 S	37 Hot Work (Welding, Cutting, Grinding)	41 Friction (Belt/Machinery Rubbing) 45 Smoking
EC	AT X	38 Friction Brake (Vehicle, Loco, Conv. Dru	ini) 42 Hot Plant Contacting Combustibles 46   Sparks from Boiler
PB	WHAT WAS PROBABLE C	39 Hot Engine or Exhaust	43   Electrical Fault (Short/Arcing/Overload)   47   Unknown
-	WH	DEXTINGUISHED Number of HP Personnel	Attending Fire: No. of Contract Emergency Services personal attending fire:
	THE	FIRE? No. of CFA Personnel affor	inding fires Name of CFA Incident Controller engine fire is their organisation's name:
distribution of the second	DAN	AGEY Yes / No 1	Description
		en et anne en seguine en anne en	
-	WHI	Section of Recort Completed by  H OF THE FOLLOWING WAS A CONTRIBE	Contact No. UTING FACTOR: (IF MORE THAN ONE CAUSE, EXPLAIN)
	49	Homan Action (Hot Work, Smoking, Incorrect	t Plant Operation, Deliberately Set etc.)
	50	Human Inaction (Insufficient Precautions, So	ill Not Removed, Poor Housekeeping, Poor Maintenance etc.) Bearing, Control Failure, Short Circuit etc.)
	52	Design (Engine Exhaust Loco Brakes, Coal Di	ist Ignifed by Heat from Light Fixtures etc.)
			Spontaneous Compustion in Briquettes etc.)
-	Hem	No Details of	
REPORT			
	HOM	WAS THE FIRE EXTINGUISHED WOLLD	
SUPERVISORY	CHE	GK LIST (Tick)	YES NO PRELIMINARY COST ESTIMATE (APPROXIMATION ONLY)
MS	Fire.	Equip. Suitable, Type, Quantity, Location?	Suppression Manhours
H	Fire	Equip: Replaced, Reset, Returbished? opriate People Notified	Vehicle/Mobile Plant Hours Expended Suppression Materials
S		gency Procedures Followed	Restoration Materials
		Report Forwarded	Z Restwation Manhours
1	Com	ments 166 Satisfa	Comments.
		· · · · · · · · · · · · · · · · · · ·	and the second s
2			
-	RES	PONSIBLE OFFICER TITLE STOPPED	Collect Phone Syr Name W O Bay Date 31/16
		UAL COSTS	FOLLOW UP ACTION FEOURED
12		SPORT WO Nº	
REPORT		EPIALS	
	PLA		
WANAGEMENT		DUCTION	
EME	TOTAL	SET COMPLETION DATE	An entire of the submitted to the submitted of the submit
AG		UAL COMPLETION DATE /	to the second se
MAN		PONSIBLE SHIFT LEADERS, NAME	
-			American desiration de la company de la comp
	1 2200		
	RES	PONSIBLE SHIFT LEADERS, SIGNATURE	PARE

# **Appendix 4 - Communications**

#### FOR INFORMATION

#### All,

- Today at approx 3pm a fire was encountered in the Mine.
- The fire is in the SEF (old part of the Mine) where Dr 24 is digging supplying EBAC.
- The fire is along the coal level for approx 100 metres.
- The CFA are in attendance fighting the fire along with IPRH and RTL employees.
- The temperature is currently 37Deg C with a SW wind of 25kph.
- The smoke will be visible across Morwell.

I will provide a further update later today.

steve

#### 8:30pm UPDATE.

- The fire will require lots of water and manpower as it is smouldering up coal faces in difficult areas to access
- The fire is over three coal faces and levels approx 60 metres high and approx 200 metres long.
- Approx 15 CFA units are on site as well as 4 IPRH/RTL water tankers
- Approx 100 men are fighting the fire (50 CFA, 50 IPRH Mine & Station & Contractors)
- The fire is under control and the smoke has eased substantially across the Morwell township
- There is no threat to loss of coal supply to Hazelwood Power Station as the fire is away from the operating faces
- Coal supply to EBAC has ceased and road carting will commence tonight
- IPRH & CFA crews will continue firefighting throughout the night
- · At this stage there is no obvious plant damage
- Several fire fighters have suffering from heat exhaustion
- The fire has attracted local and Melbourne media interest
- Senior management and Govt have been briefed

I will provide a further update tomorrow morning.

steve

#### UPDATE 0830 am 31 December 2005

All,

- Safety issues one CFA firefighter treated for heat exhaustion, several firefighters treated for smoke inhalation
- Approx 60 men (CFA, IPRH, RTL) continued fighting the fire overnight
- The fire is now subdued and contained with no visible smoke
- The fire is still smouldering and several hot spots are present on all of the three levels.
- Hot spots are still present in the coal faces which are proving hard to get torequires a cage mounted on a crane to gain access
- Five CFA units are on site with another 5 commencing at 11am
- From 11 am there will be approx 60 men fire fighting, 3 IPRH strike teams, plus 8 CFA strike teams
- Current conditions are 25deg c with no wind
- The forecast weather conditions are 42deg c with strong NW winds later in the day
- The major concern is the fire flares up when the wind pick up later in the day
- The strategy is to saturate the affected ares with as much water as possible
- The plan is to have the affected area extinguished before the wind picks up
- Plant damage is a burnt 6.6kv supply cable to Dredger 24
- Dredger coal supply to EBAC has ceased.
- Road carting to EBAC has commenced and will continue indefinitely
- There has been no loss of coal supply to Hazelwood due to the fire

I would like to praise the efforts of all personnel - IPRH, CFA who have assisted in difficult conditions

A further update will be provided later today.

Regards

steve

#### **UPDATE 5PM 31 December 2005**

#### All.

- Safety Issues several treatements for heat stress during the day
- We are now entering the "Mop Up" phase
- The fire is contained and under control with several hot spots half way up the face causing some difficulty to extinguish because of access
- Seven CFA units remain (40 men)at the front with five on standby, in addition 25 IPRH employees are at the front
- Five CFA units will remain (25 men) mopping up extinguishing hot spots during the night in addition to approx 12 IPRH employees
- CFA units from as far as Lilydale, Narre Warren, Mt Evelyn are now on site, releiving the local brigades
- Crews (CFA & IPRH) will continue wetting the area and will continue dring the night
- · Additional specialist high reach equipment has been called in to help supress the fire
- An additional crane rig is also on site to reach the fire in the batter (25 m high)
- No loss to production at Hazelwood Power station 8 units operating with prices during the day
- Road carting to EBAC continues
- Additional labour has been requested to be on standby if required from Loy Yang B as IPRH labour resources have been, and are, exhausted
- Weather conditions are 35 degC with a SE wind (different to forecast 42Deg C NW Winds)
- Concerns are for strong NW winds forecast later today.
- The plan is still to extinguish all the spot fires in the batters during the rest of today and during the night
- The effort is very time consuming and labour intensive typical of a coal fire of this type, location and size
- The resources will be reviewed tomorrow morning

I would like to thank all employees who have assisted at the coal face and support personnel for organising supplies, meals, drinks, materials, equipment, vehicles etc.

I will provide a further update tomorrow morning, after I inspect the site and receive a briefing from the CFA and IPRH personnel

Wishing you all a Happy New Year!

Regards

Steve

#### UPDATE 0700Hrs 1 January 2006

All,

- Safety Issues Nil
- Mopping up continued overnight
- Several hotspots continue to flare up when fanned by strong winds
- A westerly wind of 35kph fanned the hotspots this morning @ 0500 hrs
- Today's focus is to dig out several of the hotspots and extinguish, as they are burning into the coal face and provide the re-ignition source
- Resources in attendance are 5 CFA units (40 men) plus approx 25 IPRH resources
- Weather conditions currently 25deg C wind from the NW. Late morning we expect the wind
  to change from the SW which will help or cause. Max forecast temp is 35deg C at midday
  before the change.
- We expect the CFA activities to wind down later today if we can extinguish several of the
  hotspots as planned. We will then be on high alert with patrols and wetting of the area with
  our own resources.
- Coal supply to Hazelwood remains unaffected
- Road Carting to EBAC continues
- The CFA in conjunction with IPRH, RTL resources have done an outstanding job

Once again, a big thank you to all who have assisted, especially last night with employees giving up their New Year celebrations to assist.

I will provide a further update on progress later today.

Regards

steve

## UPDATE 1530hrs Sunday 1 January 2006

#### All,

- Safety Issues Nil
- The fire is now officially "under control" meaning it will still require constant monitoring
- The improved weather conditions have now arrived currently 18deg C SW wind and rain.
- After discussions with the CFA incident controller, the CFA will be withdrwing their resources as from 1515 Hrs
- Two hotspots approx 15 meters up the coal face remain and will continue to be supressed using monitors mounted on a crane (2 off) over th next 24-48 hrs
- Regular patrols of the area by IPRH personnel will continue

Once again, a big thanks to all employees who have assited in any way.

Regards

steve

# <u>APPENDIX 5 - INTERVIEWED WITNESS</u> <u>STATEMENTS</u>

**Investigation into Mine Fire 30 December 2005** 

# **Interview of Witness Statement**

Panel Members: R.Prezioso, M.Raun

Name: Peter Barr and Phil Glover

Date: 13/01/2006 (Romeo and Martin)

What did you think started the fire?

Where do you think the Fire Started?

How were you made aware there was a fire?

What did you do when you were advised?

# Was the IPRH response adequate?

Difficult to communicate with / between CFA and IPRH eg Fire Bombing alert to get away water supply was our main problem and access.

Fire Bombing – was effective where direct hit but spread fire on the peripherals. Needed local knowledge.

#### Was the CFA response adequate?

CFA Units at Stradbroke that day and Churchill tanker had returned previous night, crew where exhausted.

#### Was there sufficient resources available?

Managing 2 x 4 and 4 x 4 logistics as new crews came in. Wash down of CFA vehicles after Fire Fighting. Haymen Reece hitched monitor to CFA for duplication. Adjustment of tripod and monitors.

#### Was there sufficient equipment and support available?

Guides or Pilots required to guide change – over crews in. Push button voice intercom to get in worked well until the gate shut again behind first vehicle.

## What do you think worked well?

Treat cool fires as a mop up operations so that it is technique – oriented message given to volunteers to modify training / conditions.

Brief / inductions verbally given to change over crews. Eg Cigarette's and 2m edges etc.

# What do you think could have been improved?

CFA hose damage, Access to Mine Management to answer Ministerial Question

#### Any other comments?

Control point set up earlier.

Local intimate knowledge initially would help set up and orientation of crews. Region 8 CFA firefighters were called to assist with fire and were unfamiliar with fighting coal fires. Our Region 10 CFA fire fighters had limited resources due to an ongoing fire outbreak at Stradbroke. Total of 8 CFA tankers were on site. Initial communication difficult – improved for the following 2 days. Location of command centre could have been in a more suitable location ie:F/Service control centre as apposed to Operations Control Centre.

Minor damage to Truck Tyre, which caught fire, and a emergency light melted on another truck due to the radiant heat.

Mop up work requires a lot time and patience.

Hoses were damaged due plant driving over is it possible have temporary crossings. 2 CFA firefighters taken to hospital suffering fatigue

# **Investigation into Mine Fire 30 December 2005**

# **Interview of Witness Statement**

Panel Members: R.Prezioso, I. Quail, M.Raun and P.Chisolm

Name: Tony Basile

Date: 10/1/06

# What did you think started the fire?

Hot spot in batter with clay around it

# Where do you think the Fire Started?

On side of batter between 3 and 5 level -2 terraces down from top of batter at approx 2pm

## How were you made aware there was a fire?

Patrolling along M660 with Ron Bernardi and witnessed smoke from batter

# What did you do when you were advised?.

Went over and rang Control centre attendant and requested tanker. Then notified by Control Centre attendant that tanker was on its way and re-directed to another job due to low coal stocks

#### Was the IPRH response adequate?.

Yes – The wind took control very quickly and fire spread 100m with in 30min.

#### Was the CFA response adequate?

Yes

# Was there sufficient resources available?

More than enough

#### Was there sufficient equipment and support available?

Yes

#### What do you think worked well?

IPRH employees worked together very well but was difficult to work in with CFA

#### What do you think could have been improved?

CFA made more aware of fighting coal fires and better communication between CFA and operational.

#### Any other comments?

Better communication at fire front coal face with command centre. Water coverage of the levels wasn't working well due to high winds Felt as though CFA tried to brush aside HP employees and take full control Hoses boxes at H/ends and T/ends no longer exist.

"Same level as 7 T/P access, below monitor spray that has been used in past to doves hot spot"

"Below 3 level half way down the terrace faces (3 to 5 level batter)"

"Hot spot definitely had clay around it, so it wont spread fire too far"

"Excavator has since removed the hot spot, start point"

"14.00 is approx when fire noticed while patrolling M660 conv"

Control Centre advised Tony to do another job due to Coal stocks 880 blocked chute needed to be reset, Tanker is on its way to fire.

"Hazelwood response now fine and adequate number of people and emergency trailer"

"CFA turned up 10 minutes later as fire had spread quickly"

Hazelwood personnel were told to get off Level by CFA incident controller as helicopter was coming. Hazelwood people concerned about this technique"

"Foam was not working especially in the wind and foam does not get into coal cracks"

"Hazelwood everyone did a good job of teaming and working as a team" "But CFA vs Hwood"

Communication with CFA was contradictory, they and us

CFA people where standing too close to edge of batters at times and didn't like being advised of risk.

CFA tended to be in their own group. They should be with Hwood people in teams.

"Hwood people where being brushed aside" "Militant" "Hwood people treated up as spectators"

Hose boxes should be reintroduced at H/ES, T/PS, etc as a "kick-start" for fire fighting.. Branches, hoses etc.

"I missed those fire service hoses boxes and nozzles and Y piece

# **Investigation into Mine Fire 30 December 2005**

# Record of Witness Statement

# **Interview of Witness Statement 10/1/06**

Panel Members: R.Prezioso, I. Quail, M.Raun

Name: John Beamish – (was in Control Centre)

Date: 4/1/06

# What did you think started the fire?

Old Hot spot but John was in the Control Centre at the time

# Where do you think the Fire Started?

3 level

C = C shaped terraces.

Fire not doused by flooding from above. Only the crane monitor could extinguish there. CFA pressure inadequate

# How were you made aware there was a fire?

Tony Basil and Ron Bernardi were the leading hands and made me aware by radio. – 3pm

# What did you do when you were advised?

Called for available men to assist Rod Fleming and road runners

#### Was the IPRH response adequate?

Yes

Limited amount of people @ time of initial call out because we were trying to keep dredgers digging to station

#### Was the CFA response adequate?

Yes

Yes but couldn't get in the gate, they need a pilot of their own to orientate themselves at the same time as they communicate and use their own systems and procedures.

#### Were there sufficient resources available?

Yes

Yes John needed a 'scribe' to write, answer phones, take notes, record attendance

# Was there sufficient equipment and support available?

Yes but crane sprays were not available quick enough – particularly the 2nd crane monitor. Some people were almost too keen to get stuck in without proper update status. Cars went to fire with 2 people in them rather then wait for more people.

Man slip on tanker needs up-grading / condition terrible

#### What do you think worked well?

The response of all available men. The response and concern of all IPRH personnel to help from all ranks to help keep hot spot in area and fight fires.

Radio channels too many to choose from (frequency variances)—912 didn't get through to everyone

Not sure how the 912 open channel in the mine works CFA need to have a point of contact

Leader plus 3 others would be John's recommendation as a minimum 3 Hydrant, Nozzle and Leader. No one could turn off hydrants as they are all holding hoses.

# What do you think could have been improved?

CFA Knowledge of fighting coal fires pipe coverage of area because we knew hot spot in area.

Access and pipe work too small due to EBAC supply extended.

# Any other comments?

More Team Leaders and 3 man crews update man tipper for slip on tank.

Do not need tandem drive, rather than be tempted to get bigger truck get 2. The truck is great 4x4 vehicle but the strip – on is in poor condition.

What does ext 912 do??

What links all frequencies? and what links each frequency??

Radio set – up was too complicated with different channels.

"Personality 3" "Personality 1" etc

"Conventional"

What number gets across all Chanels??

When the chips where down – everyone was really good.

# **Investigation into Mine Fire 30 December 2005**

# Interview of Witness Statement

Panel Members: R.Prezioso, M.Raun

Name: Ron Bernardi

Date: 4/1/06

## What did you think started the fire?

Hot Spot

There was only smoke contained in a small area. A fire hose was there which gave the impression that it had been attended to. We went to reset an E/S on a belt and come back by which time all hell had broken loose. Radio communication appeared to give the impression that everything was being attended to and Tanker passed us within 6-7 minutes of us seeing smoke.

#### Where do you think the Fire Started?

Half way along Eastern Face Level 3and4 - level below 7TP

# How were you made aware there was a fire?

Tony Basil and I saw the smoke and Tony reported the smoke requesting a fire tanker.

# What did you do when you were advised?

We drove one level above the fire seeking water outlets. And supplied some hoses from our Leading hand car. Assisted supervisor Brought down the emergency response trailer supplied water to personnel.

and Trailer was left to attend M241

## Was the IPRH response adequate?

Yes

# Was the CFA response adequate?

Yes except the fire bombing with Helicopter

1<sup>st</sup> Fire bombing created swirl of air – fed the fire and scattered embers.

2<sup>nd</sup> Worse

3<sup>rd</sup> Worse again

#### Were there sufficient resources available?

Yes

Ron drove around distributing equipment and supplies and saw more sufficient people, tankers etc. More 90mm hoses needed for Crane Monitor.

#### Was there sufficient equipment and support available?

Yes

Emergency Trailer was excellent but the location where it should be left will change with every fire. More "Y pieces" branches reqd.

Opened a box at H/E of M240 and full of hoses which was good

What do you think worked well?

Mine op's. The initial event was confusing but soon became organised. Control centre operator was very good at assisting me.

Ron was in on overtime, so his familiarity with the crew was low. Ron praised the efforts of this crew.

Commentary by Supervisor over Open radio for a person to calm down seemed to help and re-assure others listening in.

901 Fire Services

907 Everything

900 All IPRH

912 Open Cut

# What do you think could have been improved?

There was separate communications, Mobile hand held phone and CFA radios trying to find personnel difficult so I tended to focus solely on control centre.

However if the CFA wanted to talk to Hwood and vice – versa there was a gap in communication. On the other hand having everyone on one channel would cause other problems.

Additional Y pieces in Trailer. Overall communication worked well.

#### Any other comments?

Maybe a system with loud speakers so whole section can be contacted in mass. Better Food! Taps placed at end of canvas hoses to avoid having to go to the water pipes and turn water off and on to re-position hoses and monitors.

Camera on F/S office back to Control Centre. People got to close to the edge of batters a lot.

X912 Total Mine Open channel did not work when Ron needed to pass on a CFA alert that Fire Bombing was commencing and all personal need to get off the level. X900 is apparently the entire IPRH open channel.

(Burnt brand new hoses after Chopper bombing because it spread the fire) Initially inspection of the Fire seemed too contained in small and not threatening with tanker on its way and left to reset E/S and then returned to Fire and all hell broke loose.

Called 912 Open Channel to notify people of Chopper but it wouldn't work. Fixed camera's around site to identify Fire locations

# **Investigation into Mine Fire 30 December 2005**

# Record of Witness Statement 4/1/06

# **Interview of Witness Statement 10/1/06**

Panel Members: R.Prezioso, I. Quail, M.Raun

Name: Rod Fleming

**Date:** 4/1/06

# What did you think started the fire?

Hot spot flared on 4 levels above D24 on the batter.

# Where do you think the Fire Started? Pointed to photo

#### How were you made aware there was a fire?

Travelling to D24 lazer station with T.L. (Geoff Smith) Peter Elkington and 1 x 7 Maint. crew fitters.

#### Called 912 over radio line

Saw it, without needing an alert. Come in from stacker end approx 3pm.

# What did you do when you were advised?

Called for assistance then turn on sprays along M241, M240, and M24 (Geoff and Elky) T/end, 7T/P, then commenced organising others.

# Was the IPRH response adequate?

All available men responded – to x912. "Access to everybody"

#### Was the CFA response adequate?

Yes (except for hand over procedure)

At first instance CFA did not communicate with IPRH incident controller John O'Bryan had already called CFA. Couldn't communicate with Paul Burr. 2<sup>nd</sup> bloke was better

When noticed CFA where already in "spotter" told Rod where controller was. Rod introduced himself to controller who was at TS2. Couldn't find controller after that.

#### Was there sufficient resources available?

Yes (eventually)

Emergency Trailer was Brilliant

# Was there sufficient equipment and support available?

Yes

Because of the wind on the second day, wind strength and directions, the emergency was larger on Day 2 but easier to manage due to better communication eg. Hourly talks with CFA I.C

#### What do you think worked well?

Dedicated men – Emergency response procedure assistance from others ie: 1x7 maint. RTL. Hire crane, ESLO, Engineering, Diamond Protection, Stores, Dean Mac P/Station, Surveyors, Quail, and Rieniets.

The cranes were the key tool and 2<sup>nd</sup> day seemed like we had "practised 'and reliefs changing over and Food / Drinks

Emergency response trailers

### What do you think could have been improved?

Communication was a problem as was access and water supply however these were not insurmountable

Communication, Access, Water Supply – These problems would be an issue today too. Having any more crane monitors would have required more drivers.

# Any other comments?

Looking forward to inquiry and thanking all of their efforts

The fact that we continued to supply P/S during this emergency was in my opinion an exemplary effort. The people responsible should be very proud of their efforts. They are easily recognisable. They pride themselves in their ability to work under extreme pressure with minimal supervision. I was very impressed with all involved. My role as emergency commander was very intense however very satisfying at the end of the day.

First day difficult to find people initially due to public holidays Second day fire got worse and more dangerous due to wind change Stores required M/R'prior to releasing equipment Observers on site looking for falling material from batters.

Difficult to manage Fire and Coal Supply. Stores wanted M.R's!!! First Aid centre just evolved and was terrific.

Very intense, but very satisfying in hindsight. Observers, Zone Leaders, This fire occurred on the worst possible day with New Years and Friday.

# **Investigation into Mine Fire 30 December 2005**

# **Record of Witness Statement**

# **Interview of Witness Statement 13/1/06**

Panel Members: R.Prezioso, I. Quail, M.Raun,

Name: John O'Bryan

**Date:** 3/1/06

# What did you think started the fire?

Hot spot 3 level mid section

# Where do you think the Fire Started?

3 level mid section

'Definitely directly below the Hotspot'

#### How were you made aware there was a fire?

Radio message from F/service office

First fire was at noon, Fire Report completed.

Had to use tanker @ Noon, no water in pipe. Then they wind came.... And it flared up again.

## What did you do when you were advised?

Left M220 Tail end and headed to the ridge fire to get tanker John attended a fire at the Ridge and left tanker there had lunch went to M520 Belt Shift – 13.45 to give blokes a drink.

#### Was the IPRH response adequate?

Response was good

All people from Belt shift were called to fire. Peter Reid put blank on the pipe. The blank was on within 10 minutes. Left over from a week ago. Perhaps if Pipe was charged John would have initiated sprays from the pipe. Combination of Ridge fires wind and temperatures and the tanker volume of water would normally have sufficed. But the combination meant the fire flared up again.

#### Was the CFA response adequate?

They responded quickly 2:30 – 3pm Access from stacker end.

Delays were change overs / de-briefs

CFA is a scrub fire tactical response – hit smoulders early and kill them as you go.

But they didn't listen.

#### Was there sufficient resources available?

Yes

## Was there sufficient equipment and support available?

There seemed to have enough when required

Headers at permanent batters should remain. Existing header needs extending. D24's relocated.

#### What do you think worked well?

Crane monitors, digging out the hot spot – clay cover needs to continue. Foam slows down coal fires, A – Class foam works best if there is no wind to blow it away.

# What do you think could have been improved?

Up grade equipment tanker, crane monitors, standardise equipment (hose fittings) CFA Incident Controller was at 5 levels.

Fire Service office was perfect location to command and view. Woody's position is covered 7 days. Initiate get together of Hazelwood and CFA controllers early. CFA Incident controller was at 5 levels. Rod was at D24, protecting it with Terry McDonald.

#### Any other comments?

No command centre where you could contact both agencies to discuss plans.

Once ridge fire was extinguished tanker was left at ridgeline and returned to f/service office.

At approx 1 pm I went across to M520 b/shift activities upon arriving was called again by f/service office that hot spot had flared up – this was approx between 2 and 2:30 pm. Immediately left to get f/tanker at top of ridge. On the way to fire was noticeably spreading quickly and requested that CFA were notified. F/service crew was called off b/shift and directed to re-instate water to pipeline

F/service crew was called off b/shift and directed to re-instate water to pipeline located between levels 3and5.

Tanker was left at ridge Fire because it need regular inspections throughout morning leading up to major fire in SEF.

CFA tactics for fighting fires are for scrub fires and totally unfamiliar with coal fire and totally conditioned to fighting bushfires and not accustomed to our conditions.

51283\_\_\_ Individual Radio

From telephone x 901 – Entire Mine

X 907 – All services group

# **APPENDIX 6 – WITNESS STATEMENTS**

# **Investigation into Mine Fire 30 December 2005**

## **Record of Witness Statement**

Name: Luke Alexander

**Date:** 4/1/06

## What did you think started the fire?

Hot spot internal combustion

## Where do you think the Fire Started?

3 level

## How were you made aware there was a fire?

radio

# What did you do when you were advised?

Followed control centre instructions, which was to stay on D11 dredg & S94 to continue digging coal.

# Was the IPRH response adequate?

Yes

## Was the CFA response adequate?

Yes

## Were there sufficient resources available?

Yes

## Was there sufficient equipment and support available?

Yes

# What do you think worked well?

Teamwork between operations and CFA

## What do you think could have been improved?

More water pipes charged around open cut

## Any other comments?

I don't think the helicopter was effective enough – mobile cranes were good for fighting batter fires.

# **Investigation into Mine Fire 30 December 2005**

# **Record of Witness Statement**

Name: Bill Bakker

Date: 3/1/06

# What did you think started the fire?

Hot Spot 3 level (old M225)

# Where do you think the Fire Started?

3 level

# How were you made aware there was a fire?

Called on Radio

# What did you do when you were advised?

Manned the Cat Tanker

# Was the IPRH response adequate?

Yes

# Was the CFA response adequate?

Yes

## Were there sufficient resources available?

No

# Was there sufficient equipment and support available?

No

# What do you think worked well?

Crane Mounted monitors

## What do you think could have been improved?

The command & control

#### Any other comments?

No information to the man in the field

Name: Ron Bennett Date:04/01/2006

#### **Investigation into Mine Fire 30 December 2005**

#### Questionaire

- 1. What did you think started the fire? Hot Spot
- Where do you think the fire started? Half way along eastern face Level ¾ Level below 7 T.P
- How were you made aware there was a fire? We Tony Basille and I saw the smoke and Tony reported the smoke requesting a Fire Tanker
- 4. What did you do when you were advised? We drove one level above the fire seeking water outlets. And supplied some hoses from our L/H car. Assisted Supervisor brought down emergency trailer, supplied water to personnel.
- 5. Was the IPRH response adequate? Yes
- 6. Was the CFA response adequate? Yes except Fire bombing with Helicopter
- 7. Was there sufficient resources available? Yes
- 8. Was there sufficient equipment and support available? Yes
- What do you think worked well? Supervision, Mine Op's, the initial event was confusing but become organised soon. Control Centre operator was very good at assisting me.
- 10. What do you think could have been improved? There was separate communications Mobile / Hand Held and CFA trying to find personnel difficult so I tendered to focus solely on Control Centre
- 11. Any other comments? Maybe a system with Loud Speakers so whole section can be contacted in mass. Better Food. Taps placed at the end of canon hoses to avoid having to go to the water pipe and turn water off and on to re position Hoses or Monitors

Signed:
---------

# **Investigation into Mine Fire 30 December 2005**

# **Record of Witness Statement**

Name: Peter Brimblecombe

**Date: 3/1/06** 

### What did you think started the fire?

Don't Know

## Where do you think the Fire Started?

Above D24

#### How were you made aware there was a fire?

Saw the smoke & fire trucks later call on the mobile phone

# What did you do when you were advised?.

Went to the fire to offer support. Worked hoses on 5 level with small crew as directed

#### Was the IPRH response adequate?.

Yes in terms of manpower & equipment but not well enough controlled given the magnitude of the fire.

## Was the CFA response adequate?

Yes but not well co-ordinated in the early stages

#### Was there sufficient resources available?

Yes

## Was there sufficient equipment and support available?

Yes

# What do you think worked well?

The emergency trailers & hoses store at fire service. The water supply system met all demands.

# What do you think could have been improved?

The communications system & the speed at which the incident should have been escalated with an appropriate control structure.

## Any other comments?

The Helicopter was a waste. It is not appropriate for this type of fire. The mine personnel supporting the external resources did an excellent job. A training course for CFA on how the coal fires are best attacked & issues with working in the mines would be of value. Most have only training on wild fire & structural fires, neither of which is appropriate

## **Record of Witness Statement**

Name: Russell Camier

**Date:** 2/1/06

### What did you think started the fire?

An old fire hole in the coal face

## Where do you think the Fire Started?

2 levels above D24 in south east field

### How were you made aware there was a fire?

I saw fire from M720

## What did you do when you were advised?.

Continued to work on ensuring the conveyor kept operating

### Was the IPRH response adequate?.

Yes all IPRH employees, I saw were doing their best to fight the fire.

#### Was the CFA response adequate?

Seemed to be OK They didn't seem very provocative however.

#### Was there sufficient resources available?

Not enough 64mm hoses initially

#### Was there sufficient equipment and support available?

Yes

### What do you think worked well?

Working in groups of 2 or 3. Using monitors (trailer mounted or stand mounted) was easier to handle & safer.

## What do you think could have been improved?

There needed to be central points of contact (people clearly unidentifiable) to coordinate fire fighting at different locations.

#### Any other comments?

### **Record of Witness Statement**

Name: Paul Connolly

**Date:** 4/1/06

# What did you think started the fire?

Not known to me

## Where do you think the Fire Started?

Above D24 dredger

## How were you made aware there was a fire?

At home by phone

### What did you do when you were advised?.

Came to work as advised

### Was the IPRH response adequate?.

Yes

# Was the CFA response adequate?

Yes

# Was there sufficient resources available?

Not at the beginning

#### Was there sufficient equipment and support available?

Not at the early stages

#### What do you think worked well?

IPRH work force & effort left the CFA for dead

#### What do you think could have been improved?

To have open cut personnel advising CFA

#### Any other comments?

Use slip on Fire Tanker disused at compound, by welding skids on bottoms . Be extra spray unit at the fire area

#### **Record of Witness Statement**

Name: Geoff Crisp

Date: 5/1/06

#### What did you think started the fire?

Dont know

# Where do you think the Fire Started?

Dont Know

## How were you made aware there was a fire?

Phone call at home 31/12/05 at 5:45am

#### What did you do when you were advised?.

Came to work allocated Team Leader role

### Was the IPRH response adequate?.

Some holes in emergency response plan not filled.

### Was the CFA response adequate?

From what I saw

### Was there sufficient resources available?

Yes

#### Was there sufficient equipment and support available?

#### What do you think worked well?

Crane mounted monitors & small man tanker were great items. The water capacity of the tanker is a bit small

## What do you think could have been improved?

One crane per level ie: 3,5,7 levels would have been better. When we moved cranes fire broke out again.

#### Any other comments?

I asked for an elevated platform. I was told none were available – I drove around the power station and found 2 that would have worked. Team /leader roles not taken seriously by some people.

An aux pump fitted to large tanker to supply high pressure cannons for batter fires could be an advantage.

# **Record of Witness Statement**

Name: Joe Dickason

Date: 4/1/06

#### What did you think started the fire?

Maybe hot spot 1 level

Where do you think the Fire Started?

#### How were you made aware there was a fire?

Was informed by Rod Fleming to west bunker down because of fire

## What did you do when you were advised?.

Wet bunker

#### Was the IPRH response adequate?.

Yes

## Was the CFA response adequate?

Yes

Was there sufficient resources available?

### Was there sufficient equipment and support available?

To a dredger yes

## What do you think worked well?

cranes

#### What do you think could have been improved?

Need longer reach cranes . Monitor & list where people are. Need longer reach excavators

#### Any other comments?

Not every employee got phoned – Water bombing by helicopter worsened the fire. Otherwise the guys pulled together extremely well to get the job done.

### **Record of Witness Statement**

Name: John Janiw

**Date:** 3/1/06

### What did you think started the fire?

Spark from a hot idler or travel pads throwing sparks off drive dogs.

### Where do you think the Fire Started?

Around the 24 dredger area.

### How were you made aware there was a fire?

Initially I was told by a friend who was passing the mine on his way from traralgon to moe.

# What did you do when you were advised?.

I was on my to work (night shift) so I came in early and reported to the control centre.

#### Was the IPRH response adequate?.

Yes I believe so

#### Was the CFA response adequate?

Yes I believe so

### Was there sufficient resources available?

#### Was there sufficient equipment and support available?

Yes – Possibly another crane with a monitor at the height of the fir would have been an asset (one per level)

#### What do you think worked well?

Cranes with water monitors did a great job as high faces could not be accessed by conventional means.

#### What do you think could have been improved?

Access on some half levels were very poor at the foot of some batters with pipe off cuts & debris making crane access awkward.

#### Any other comments?

We could do with some more sprays pendant control units for the cranes as during the course of the fire we had some breakdowns which required down time of the cranes. Spare units would enable minimal down time & effective fire training.

## **Record of Witness Statement**

Name: Stan Kemsley

Date: 3/1/06

#### What did you think started the fire?

I don't know specially I was told it was due to a hot spot in the face.

#### Where do you think the Fire Started?

SEF on level above TS2 approx 300m from old conveyor pivot point

### How were you made aware there was a fire?

I saw CFA truck going past WBM offices at approx 3:30pm. Then saw smoke when I came back onto site.

### What did you do when you were advised?.

I went to the control centre and asked Rod fleming if he wanted assistance. Initially Russell Camier, Bryan Mulconey and I concentrated on having conveyors running.

#### Was the IPRH response adequate?.

It seemed to be

#### Was the CFA response adequate?

I don't know

#### Was there sufficient resources available?

When I was at the fire front they seemed to be adequate.

#### Was there sufficient equipment and support available?

When I got to the fire front there seemed to be.

### What do you think worked well?

People willingness to have a go and support each other. There didn't seem to be anybody panicking or over enthusiastic.

### What do you think could have been improved?

Better definition of teams & clearly identify team leaders & zones. More enforcement of rests. Some people wouldn't have a break.

#### Any other comments?

I believe that better / greater use of team leader identities would have been useful. This could have provided a more clearer 'chain of command'.

It should be encouraged to get people to rest when people are available. Some people wouldn't step back & rest by handing over the hose or duty they were performing. Use of cranes to extinguish fire on batter worked well.

## **Record of Witness Statement**

Name: Nick Komus

**Date:** 4/1/06

What did you think started the fire?

Where do you think the Fire Started?

### How were you made aware there was a fire?

Called at home by Supervisor Fleming

## What did you do when you were advised?.

I told Fleming I'll be there in 5 Min.

#### Was the IPRH response adequate?.

Yes

#### Was the CFA response adequate?

Don't Know

Was there sufficient resources available?

#### Was there sufficient equipment and support available?

Yes

### What do you think worked well?

It looked like every thing was under control the whole area being wetted down.

#### What do you think could have been improved?

Each level should have its own water pipes all trucks re fill points on some needed at below ground level better food than sausages.

#### Any other comments?

## **Record of Witness Statement**

Name: T Koostra

Date: 4/1/06

What did you think started the fire?

Don't Know

Where do you think the Fire Started?

As above

How were you made aware there was a fire?

When I reported for work Sunday

What did you do when you were advised?.

Fought the fire

Was the IPRH response adequate?.

Was the CFA response adequate?

Was there sufficient resources available?

Was there sufficient equipment and support available?

What do you think worked well?

What do you think could have been improved?

Some precautionary maintenance on monitors and equipment

Any other comments?

Make some attachments to empty the hoses.

## **Record of Witness Statement**

Name: Kevin Lovett

**Date:** 5/1/06

## What did you think started the fire?

Not here at the time

## Where do you think the Fire Started?

N/A

#### How were you made aware there was a fire?

Phone call (1945) on 30/12/05. R. Fleming

## What did you do when you were advised?.

Came into work

## Was the IPRH response adequate?.

Yes

## Was the CFA response adequate?

Ves

### Was there sufficient resources available?

Yes

## Was there sufficient equipment and support available?

Yes

### What do you think worked well?

Crane & ops personnel in conjunction with CFA.

## What do you think could have been improved?

Meals & rest area plus keeping a log where personnel were on levels

### Any other comments?

Name: Terry McDonald Date: 16/01/06

#### Investigation into Mine Fire 30 December 2005

#### Questionnaire

- 1. What did you think started the fire? I don't know, but have heard it was an old fire hole that flared in extreme weather conditions
- 2. Where do you think the fire started? Old Sef perm batters about 4 level
- 3. How were you made aware there was a fire? Noticed smoke while working in West Field at about 3 3.30pm Friday 30/12/05
- What did you do when you were advised? Made my way to D24 T/S M241 to ensure machine was hosed up tried to prevent EBAC coal supply from being burnt.
- 5. Was the IPRH response adequate? Yes everyone I saw worked well together
- 6. Was the CFA response adequate? To the best of their ability
- 7. Was there sufficient resources available? Yes
- 8. Was there sufficient equipment and support available? Yes but more Perm F/S pipes would have been better
- 9. What do you think worked well? Fantastic team work from IPRH / RTL people 2 x 12 1x7 RTL Managers, Office Staff all working together to fight fire.
- 10. What do you think could have been improved? Helicopter bombing was a waste of time but had to be tried. Too long b/w bombs
- 11. Any other comments? Great to see IPRH Personnel come in to help when Fire was reported on the news.

Signed:	

# **Record of Witness Statement**

Name: Scott Meadows

**Date: 3/1/06** 

## What did you think started the fire?

Hot spot so I'm told

#### Where do you think the Fire Started?

M241 level and above

### How were you made aware there was a fire?

Television

#### What did you do when you were advised?.

I was called to fight fire

#### Was the IPRH response adequate?.

Equipment wise no.

# Was the CFA response adequate?

Wasn't here first day

#### Was there sufficient resources available?

Big tanker good for keeping dust down on roads

# Was there sufficient equipment and support available?

Cranes were good asset don't get rid of them

#### What do you think worked well?

Big tanker useless fighting fires no pressure in monitors. Graet to drive cranes cranes were an asset.

#### What do you think could have been improved?

I think we should have our fire team and CFA under our direction we do know the area & how to fight fires.

### Any other comments?

Better access & water supply to all none working areas.

## **Record of Witness Statement**

Name: John Morgan

**Date:** 3/1/06

## What did you think started the fire?

Hot spot old M225

## Where do you think the Fire Started?

Clay hot spot M225

### How were you made aware there was a fire?

Saw smoke

## What did you do when you were advised?.

Take water tanker to site

## Was the IPRH response adequate?.

No

# Was the CFA response adequate?

Poor

#### Was there sufficient resources available?

Yes

## Was there sufficient equipment and support available?

No

## What do you think worked well?

Old slip on water tanker

## What do you think could have been improved?

Better fire tankers

## Any other comments?

Listen to what staff require with equipment

### **Record of Witness Statement**

Name: Tim Nolan

**Date:** 9/1/06

#### What did you think started the fire?

Old firehole

### Where do you think the Fire Started?

Between 3 & 5 level below old firehole

#### How were you made aware there was a fire?

Noticed the fire - rang fire service to report it

#### What did you do when you were advised?.

#### Was the IPRH response adequate?.

yes

#### Was the CFA response adequate?

Good initial response but took awhile to get going after they arrived

#### Was there sufficient resources available?

Generally overall No

### Was there sufficient equipment and support available?

No

#### What do you think worked well?

Crane sprays – excellent lanzone sprays on stand – great small man trailer

### What do you think could have been improved?

CFA man management

#### Any other comments?

Water Availability – Not enough hydrants Hydrants there but un-operational (seized broken, etc) IPRH fire tanker pumps need checking Irregularly for both pressure and reliability also Labelling for operating needs to be clearer.

#### Communication

All radios need to be able to be reached using open air channel There was problems between CFA and IPRH communications at the start

### **Record of Witness Statement**

Name: Shaun O'Neill

Date: 5/1/06

#### What did you think started the fire?

Not here at the time

## Where do you think the Fire Started?

N/A

## How were you made aware there was a fire?

I received a phone call from Rod Fleming

#### What did you do when you were advised?.

I was here within 15min of phone call from Rod Fleming

## Was the IPRH response adequate?.

Very Good

### Was the CFA response adequate?

Yes except for Helicopter

#### Was there sufficient resources available?

Crane monitors need to be more accessible

## Was there sufficient equipment and support available?

Overall very good

### What do you think worked well?

IPRH employees CFA – Ore own fire service personnel small fire service sprays.

#### What do you think could have been improved?

Easier access to water on some levels meals on last N/S that CFA was involved

#### Any other comments?

Overall I was very impressed with the commitment of all involved – Emergency response bibs need to be bigger.