

6 June 2014

Chris Fox
Partner
T +61 3 9643 4116
M +61 418 270 408

Ms Justine Stansen
Principal Legal Advisor
Hazelwood Mine Fire Inquiry
20 Hazelwood Road
Morwell VIC 3460

Emily Heffernan
Senior Associate
T +61 3 9643 4208
M +61 403 921 576

Dear Madam,

Hazelwood Mine Fire Inquiry

We refer to your letter dated 2 June 2014.

As regards the first paragraph of your letter, in the discussion between you and Emily Heffernan on Saturday 24 June 2014 in relation to your letter dated 9 May 2014 and the requested witness statement from George Graham and/or others in relation to the matters set out in the attachment to that letter, Ms Heffernan advised that Mr Graham was not the most appropriate or best placed person to provide a witness statement in relation to the various matters outlined in the attachment, and that the matters would be dealt with by other witnesses.

As regards the second paragraph, you have now received the witness statement of James Faithful in relation to mine rehabilitation (paragraphs 4 – 10 of the attachment to your letter dated 9 May 2014 as replicated in paragraphs 2-8 of the attachment to your 2 June 2014 letter). At no time has it been suggested that Mr Faithful would address "*the implementation of recommendations of past reports*".

Mr Faithful is the person best placed to address the topic of mine rehabilitation, as he is the Hazelwood employee charged with primary responsibility for managing the Mine's rehabilitation program (including rehabilitation of the northern batters). Mr Faithful has a detailed understanding of the rehabilitation requirements of the approved 2009 Work Plan, the content of the 2013 Work Plan Variation application, and of the relevant construction steps and associated constraints.

The fact that Mr Faithful did not have direct involvement in the mine rehabilitation undertaken before the commencement of his employment at the Mine does not in any way detract from his suitability to respond to the Board's inquiries on rehabilitation. The majority of the matters concerned with mine rehabilitation that you have asked about do not require him to have had direct involvement in past rehabilitation, and in any event Mr Faithful has informed himself of the necessary historical information.

In relation to your suggestion that Mr Wilkinson should give this evidence, we repeat the points made above, and also note that Mr Wilkinson has only been employed at the Mine since about February 2012.

As regards the other matters contained in the attachment to your 4 June 2014 letter (Previous fires at the Mine, Hazelwood fire plans and policies, and Co-operation with external agencies in paragraphs 9-23), we

do not see the utility of further statements in relation to all these matters, having regard to the evidence and material already provided, and the comments below.

A table referring to the material and evidence which concern these matters is attached (**Attachment 1**).

In addition:

1. Our client does not consider that Mr Wilkinson is the most appropriate or best placed person to give evidence about the other matters. The topics are specialised, and in some cases highly technical, and are not matters which Mr Wilkinson is required to manage directly. Other senior mine personnel who report to Mr Wilkinson, for example Mr Dugan, Mr Faithful and Mr Prezioso, carry out the detailed day to day work and are in a better position to speak about the issues to the extent that any further evidence might be sought (as to which, see further below).

Previous fires at the Mine (paragraphs 9 – 12 of the attachment to your 2 June 2014 letter).

2. As regards paragraph 9, the difficulty is that a number of Mine personnel have been tasked over the years with implementing the many recommendations arising from previous significant fires at the Mine, in particular the fires in 2005, 2006, 2008, and 2012.
3. Our client has supplied the Board with the reports into these fires, and numerous documents which record the status of the implementation of the recommendations. A number of these are annexed to Mr Dugan's statement, including audit documents. For example, Annexure 8 to Mr Dugan's statement is a report generated by our client's Paradigm system which records the status of each of the 38 recommendations arising out of the report into the 2012 fire, and notes that 11 employees had responsibilities for actioning the recommendations.
4. As regards the recommendations arising out of the 2006 fire, these have been the subject of extensive reporting and auditing, as detailed in the documents at Annexures 3-6 of Mr Dugan's statement. We also note, in relation to the recommendations arising out of the 2005 fire, that the status of the implementation of these recommendations was dealt with in a report dated 29 June 2012 which was supplied to the Board on 9 May 2014 in response to the Summons (document 01.06).
5. In relation to the recommendations arising from the 2006 fire, we further observe that as noted in:
 - the submission by the State of Victoria (which we became aware of on Monday 2 June 2014); and
 - the witness statement of Kylie While of DSDBI (which was supplied to us on 3 June 2014),the Inspector of Mines issued an improvement notice to the Mine on 13 February 2007 requiring the Mine to comply with GHD's 20 recommendations, and that by notice dated 14 September 1997, the Inspector of Mines formally indicated that the Improvement Notice had been complied with and that the Recommendations had been implemented in accordance with the *2006 Mine Fire Action Plan* (Annexure 3 to Robert Dugan's witness statement).
6. Providing further evidence describing the implementation of all of the recommendations arising out of all the fires would be a substantial undertaking and we do not see the utility of such an exercise. On the other hand, if, there are any particular recommendations about which the Board requires further information, our client is happy to investigate that and provide it. If you still seek a witness to give evidence in relation to any particular recommendations, please advise us accordingly.

7. As regards paragraph 10, in our letter dated 3 June 2014 (supplied on 4 June 2014), we explained the position in relation to the implementation of recommendations 6 and 10 of the report into the 2008 fire.
8. As regards paragraph 11, this was not included in your letter dated 9 May 2014, and relates to a question asked of Mr Dugan on 28 May 2014. We are instructed as follows:
 - a. If by the "eastern end of the northern batters", you mean the eastern rehabilitated area, water pipes were removed to allow the batters to be re-profiled and revegetated. No risk assessment was undertaken in relation to removal of these pipes; and
 - b. If you are instead referring to the central part of the northern batters, the practice of removing degraded and leaking pipes was established prior to privatisation, and was the subject of the Richard Oliver "*Fire Risk Analysis of the Worked-Out Areas of Morwell Open Cut*" draft report in 1992 (**Attachment 2**). This Risk Assessment led to the amendments to the Mine Fire Policy and Code of Practice with respect to the worked-out areas, which were adopted by Generation Victoria in 1994 prior to privatisation. In particular the amendments relevantly included a provision that an acceptable means of fire protection on worked out batters was tanker filling points within 5 minutes travel of any part of the worked out batter.
9. As regards paragraph 12, which relates to the request made on 30 May 2014, the first of these plans (of fire services pipes as at 9 February 2014), is Annexure 11 to Mr Dugan's witness statement. The remaining plans (of pipes installed during the fire, and of total pipework at the Mine following the fire), were provided to you on 4 June 2014.

Fire Plans and Policies (paragraphs 13 – 19 of the attachment to your 2 June 2014 letter)

10. As regards paragraph 13, 14 and 15, the Codes have been put in evidence by Mr Harkins and Mr Dugan, and Mr Dugan has given evidence of his understanding that the 2013 Code is based upon the 1994 Code. Main features or differences are more properly the subject of submissions.
11. As regards paragraph 16, the original request in paragraph 18 of the attachment to your letter dated 9 May 2014 was dealt with in Mr Dugan's witness statement (see paragraph 10 and Annexure 10). As regards the additional documentation requested in paragraph 16 of your letter dated 2 June 2014, we are seeking instructions and copies from our client.
12. As regards paragraph 17, this has been dealt with in the evidence: see **Attachment 1**.
13. As regards paragraph 18, we are instructed that there is no audit by the CFA, Worksafe or DSDBI at regular intervals of Hazelwood's fire mitigation response plans and policies. However, we note that there the Victorian Workcover Authority ("**VWA**") and DSDBI conduct audits of the Mine from time to time, as detailed in the submission to the Inquiry and witness statements of the State of Victoria. In some cases, these audits may have assessed aspects of the Mine's fire mitigation and response plans or policies. For example, documentation regarding VWA audits of *Major Mining Hazard 7*, and of carbon monoxide policies throughout the fire fighting operations, has been supplied to the Board.

14. As regards paragraph 19, we are instructed that Hazelwood will continue to review its fire mitigation and response plans and policies in light of the fires within the Mine following the Inquiry, and will take into account relevant evidence, submissions and recommendations in this Inquiry.

Co-operation with External Agencies (paragraphs 20-23 of the attachment to your 2 June 2014 letter)

15. As regards paragraph 20, the involvement of CFA is dealt with in the evidence of Mr Dugan and of Mr Harkins. As to DSDBI and Worksafe, we are seeking instructions, however see paragraphs 5 and 13 above. We are instructed that Council is not involved in developing and implementing a fire risk mitigation strategy for the Mine.
16. As regards paragraph 21, we are instructed that our client has not participated in Integrated Fire Management Planning at a State level, Regional level in the Gippsland Region, or at municipal level in the City of Latrobe, although our client understands that the Central Gippsland Essential Industry Group ("CGEIG") does participate in Integrated Fire Management Planning, at least at a municipal level.
17. As regards paragraph 22, this has been dealt with in the evidence of Mr Dugan and Mr Harkins, and in our letter dated 27 May 2014.
18. In relation to paragraph 23, we are instructed that Hazelwood will continue to review the way that it works with external agencies to mitigate the risk of fire at the Mine following the Inquiry, and will take into account relevant evidence, submissions and recommendations in this Inquiry.

If, notwithstanding the foregoing, there are any remaining specific matters about which further evidence is sought, please let us know.

Experts

Our concern in relation to expert reports is that Board is properly informed by the expert evidence that it receives, and that any expert evidence to the Inquiry can be tested.

The reality is that receipt of expert evidence on highly technical matters at this late stage clearly impacts the ability for that evidence to be tested and assessed, and for it to be safely relied upon by the Board.

Yours faithfully,



Issue	Date of request	KWM comment	Other relevant materials
BACKGROUND			
1 Outline your role and responsibilities, and your relevant qualifications and experience.	9 May 2014	Witness statements of Steve Harkins, Rob Dugan, James Faithful.	
REHABILITATION OF THE MINE			
2 Describe the rehabilitation plans for the Mine from September 1996 to date, with particular focus on rehabilitation plan contained in the work plan variation approved on 11 May 2009.	9 May 2014	Witness statement of James Faithful supplied on 4 June 2014.	Relevant materials supplied with KWM's letter dated 2 May 2014: Tab 1 - MIN 5004 , including the initial rehabilitation plans Tab 6 - 2009 Work Plan Revision
3 Describe rehabilitation work done at the Mine from September 1996 to date, with particular focus on rehabilitation work done under the 2009 work plan variation.	9 May 2014	Witness statement of James Faithful supplied on 4 June 2014.	See the Environment Review Committee, Environmental Compliance and Weekly and Fortnightly Environmental Reports provided on 9 May 2014 in response to paragraph 7 of the Summons.
4 Describe future work that is required to be done under the rehabilitation plan, identifying the date by which rehabilitation of the Mine is required to be completed.	9 May 2014	Witness statement of James Faithful supplied on 4 June 2014.	Relevant materials supplied with KWM's letter dated 2 May 2014: Tab 1 - MIN 5004 , including the initial rehabilitation plans Tab 6 - 2009 Work Plan Revision
5 Explain the purpose of the \$15 million rehabilitation bond lodged by the [sic] Hazelwood under s 80 of the <i>Mineral Resources (Sustainable Development) Act 1990</i> (Vic). How was the amount of the rehabilitation bond determined?	9 May 2014	Witness statement of James Faithful supplied on 4 June 2014.	
6 Is Hazelwood currently compliant with its obligations under the rehabilitation plan? If not, identify the areas in which it is not compliant and the actions being taken to achieve compliance.	9 May 2014	Witness statement of James Faithful supplied on 4 June 2014.	See the Environment Review Committee, Environmental Compliance and Weekly and Fortnightly Environmental Reports provided on 9 May 2014 in response to paragraph 7 of the Summons.

7	Provide your views about the feasibility of bringing forward the rehabilitation of the northern part of the Mine, adjacent to the town of Morwell, to create a wider buffer zone between the Mine and the town.	9 May 2014	Witness statement of James Faithful supplied on 4 June 2014.	
8	What happens if Hazelwood has not rehabilitated the Mine to the mine regulator's satisfaction by the end of the licence period? Is the \$15 million rehabilitation bond the extent of Hazelwood's liability to rehabilitate the Mine?	9 May 2014	Witness statement of James Faithful supplied on 4 June 2014.	
PREVIOUS FIRES AT THE MINE				
9	Describe the implementation of the recommendations made in: (1) The Final Report into the IPRH Mine Coal Fire September 2005; (2) The International Power Hazelwood October 2006 Mine Fire Incident Investigation Report; (3) The international Power Hazelwood September 2008 Mine Fire Incident Investigation Report; and (4) The 11 Dredger Centre Chute Fire Incident – Final Incident Investigation Report.	9 May 2014	<p>September 2005 fire – see Stan Kemsley report entitled "Review of Specific Major Incident Recommendations" provided under the Summons (document 01.06).</p> <p>October 2006 fire – see Stan Kemsley report entitled "Review of Specific Major Incident Recommendations" provided under the Summons (document 01.06) and Appendix A of the GHD Report into September 2008 Mine Fire, being Annexure 6 to Robert Dugan's witness statement.</p> <p>September 2008 - see Stan Kemsley report entitled "Review of Specific Major Incident Recommendations" provided under the Summons (document 01.06)</p> <p>January 2012– see Paradigm report, Annexure 8 to Robert Dugan's witness statement.</p> <p>See also: - Witness statement of Robert Dugan, paragraphs 17 – 26. - As regards recommendations 6 and 10 of the 2008 Report, KWM letter dated 3 June 2014 (supplied on 4 June 2014).</p>	<p>Refer to the following documents supplied to the Board on 9 May 2014 under the Summons: 01.06, 01.07, 01.08, 01.09, 01.10, 01.11</p> <p>Refer also to tab 19 of the folders of materials supplied to the Board on 2 May 2014 (GHD Report in 2008 Mine Fire, Appendix A)</p>
10	Describe in detail what was done to implement recommendations 6 and 10 of the International Power Hazelwood September 2008 Mine Fire Incident	28 May 2014 & 2 June 2014	See King & Wood Mallesons' letter dated 3 June 2014 (supplied on 4 June 2014).	

	Investigation Report. If a risk assessment was undertaken on the non-operational areas of the Mine, in accordance with recommendation 6, provide a copy and explain how the risk assessment informed decisions taken in relation to further prevention work. If no risk assessment was undertaken on the non-operational areas of the Mine, explain why not.		See also evidence of Robert Dugan, 28/05/2014 – Tr pp.412, 413.	
11	Was any risk assessment undertaken in relation to the removal of pipes from the fire services system at the eastern end of the northern batters? If so, provide a copy and explain how the risk assessment informed the decision to remove those pipes.	28 May 2014	See King & Wood Mallesons' letter dated 6 June 2014. See also evidence of Robert Dugan, 28/05/2014 – Tr pp.405 - 406, 429 - 430.	
12	Provide copies of the site map/layout of the fire services system before and after the fires that ignited on 9 February 2014, as requested.	First requested 30 May 2014	AA plan of the fire services pipes throughout the Mine as at 9 February 2014 is Annexure 11 to the witness statement of Robert Dugan. Plans of pipework installed during the fires, and of all pipework following the fires, were provided on 4 June 2014. See also evidence of Robert Dugan, 28/05/2014 – Tr pp.405 – 408.	
HAZELWOOD FIRE PLANS AND POLICIES				
13	Outline the main features of the Fire Service Policy and Code of Practice (April 1994) (1994 Code).	9 May 2014	See KWM letter dated 6 June 2014.	
14	Outline the main features of the Mine Fire Policy and Code of Practice revised July 2013 (2013 Code).	9 May 2014	See KWM letter dated 6 June 2014	
15	Identify any differences between the 1994 Code and the 2013 Code and explain the reasons for them.	9 May 2014	See KWM letter dated 6 June 2014.	
16	Describe Hazelwood's state of compliance with its fire mitigation and response plans and policies as at 9 February 2014. <u>Attach the completed check list for season specific fire preparedness and mitigation planning for 2013-2014, including the fire breaks and slashing drawing and the annual aerial photograph of fire service spray water coverage.</u>	9 May 2014 & 2 June 2014	See KWM letter dated 6 June 2014.	

17	How does Hazelwood ensure continuity of supply of power and water to respond to a fire? As at 9 February 2014, what back up power supplies were available in the event that mains power was lost during a fire?	9 May 2014	<p>First witness statement of Steven Harkins, paragraphs 90 – 102.</p> <p>Witness statement of Robert Dugan, paragraph 33(a), and Annexure 2 (see specifically Appendix C of that report).</p> <p>See also evidence of Romeo Prezioso, 28/05/2014, Tr pp. 371-372, 377-378.</p> <p>See also evidence of James Faithful, 28/05/2014, Tr pp. 388 – 390.</p> <p>See also evidence of Steven Harkins, 27/05/2014, Tr pp. 339 - 340.</p> <p>See KWM letter dated 6 June 2014.</p>	
18	Did any agency, for example the CFA or WorkSafe, audit Hazelwood's fire mitigation and response plans and policies at regular intervals? If so, please describe the audit process and provide copies of the most recent audit report.	9 May 2014		
19	Is Hazelwood reviewing its fire mitigation and response plans and policies in light of the fires that burned at the Mine in February and March 2014? Provide your views on what aspects of these plans and policies worked well, what did not work well and what could be improved.	9 May 2014	<p>See KWM letter dated 6 June 2014.</p> <p>See also:</p> <p>First witness statement of Steven Harkins, paragraph 111.</p> <p>Second witness statement of Steven Harkins, paragraph 39.</p> <p>Witness statement of Robert Dugan, paragraphs 80 - 95.</p> <p>Evidence of Steven Harkins, 27/05/2014, Tr pp. 338 - 339.</p> <p>The evidence of Robert Dugan, 28/05/2014 – Tr pp.423, 427-428, pp 433-435.</p> <p>Evidence of Steven Harkins, 30/05/2014, Tr, p. 734.</p>	

CO-OPERATION WITH EXTERNAL AGENCIES

20	Outline the way in which Hazelwood works with CFA, Latrobe City, the Department of State Development, Business and Innovation as mine regulator, WorkSafe and any other relevant agency or body in developing and implementing a fire risk mitigation strategy for the Mine.		See KWM letter dated 6 June 2014.	
21	Does Hazelwood participate in Integrated Fire Management Planning at State level, at regional level in the Gippsland Region, or at municipal level in the City of Latrobe? If so, describe Hazelwood's participation at each level.		See KWM letter dated 6 June 2014. As regards Hazelwood's participation in the CGEIG: First witness statement of Steven Harkins, paragraph 21. Evidence of Alan Roach 29/05/14 (Tr p. 633).	See also document 18.02 supplied on 9 May 2014 under the Summons.
22	Describe the arrangements that were in place between Hazelwood and the CFA as at 9 February 2014 for responding to a fire at the Mine, including and pre-incident planning.		Witness statement of Robert Dugan paragraphs 35 – 36. First witness statement of Steven Harkins, paragraphs 14 and Annexures 1 and 2.	See the materials supplied on 2 May 2014 (tab 7) - Emergency Response Plan, Appendix 1. See also King & Wood Mallesons letter dated 27 May 2014.
23	Is Hazelwood reviewing the way it works with external agencies to mitigate the risk of fire at the Mine, in light of the fires that burnt at the Mine in February 2014 and March 2014? Provide your views on what aspects of its work with external agencies worked well, what did not work well and what could be improved.		See KWM letter dated 6 June 2014. See also the witness statement of Robert Dugan at paragraphs 78 - 95.	

Unclassified

Hazelwood Power

Owner TECHNICAL LIBRARY
Created 1/06/1992

REPORTS

REP1992/2696



Fire Risk Analysis of the Worked-Out Areas of Morwell Open Cut - Draft - June 1992

FIRE RISK ANALYSIS OF
THE WORKED-OUT AREAS OF
MORWELL OPEN CUT

PRIVATE &
CONFIDENTIAL

JUNE 1992

Richard Oliver International Pty Ltd
(ACN 006 256 908)
71 Queens Road, Melbourne Vic. 3004
Telephone: (03) 529 5122
Facsimile: (03) 521 1634

RICHARD OLIVER

12 June 1992

Mr Richard Polmear
Production Scheduling Superintendent
Morwell Open Cut
State Electricity Commission of Victoria
MORWELL

Dear Richard,

RE; FIRE RISK ANALYSIS OF MORWELL OPEN CUT

Thank you for the opportunity to undertake this project. In accordance with requirements, please find enclosed our first draft of the project report.

We would be grateful for your comments on this draft at your convenience. Please also note that this is the only copy issued to SECV.

I look forward to your response.

Yours sincerely,



CHRIS TENISWOOD

encl.

CT\SECV\SECVLTR.mg

RICHARD OLIVER INTERNATIONAL PTY. LTD.
A.C.N. 006 256 908

71 Queens Road, Melbourne 3004, Australia
Telephone: (03) 529 5122 Toll Free: 008 335 014 Fax: (03) 521 1634
Correspondence to: Box 956G, GPO Melbourne 3001

Sydney • Adelaide • Perth • Auckland • Wellington • Chicago • Singapore • London

DRAFT

**FIRE RISK ANALYSIS OF
THE WORKED-OUT AREAS OF
MORWELL OPEN CUT**

**PRIVATE &
CONFIDENTIAL**

JUNE 1992

**Richard Oliver International Pty Ltd
(ACN 006 256 908)
71 Queens Road, Melbourne Vic. 3004
Telephone: (03) 529 5122
Facsimile: (03) 521 1634**

DRAFT

EXHIBIT B
ATTACHMENT A

Page 1 of 1

TABLE OF CONTENTS

ITEM	PAGE NO.
EXECUTIVE SUMMARY	i
1. INTRODUCTION	1
1.1 Purpose of this Project	1
1.2 Scope and Assumptions	1
1.3 Background and Context	
2. METHODOLOGY	2
2.1 Definition of Risk and Risk Analysis	2
2.2 Key Risk Issues	2
2.3 Data Collection and Analysis	3
3. FINDINGS	3
3.1 Current Status of the Worked-Out Areas and Batters	3
3.2 Current Status of the Fire Protection Available to the Worked-Out Areas	5
3.3 Fire History and the Likelihood of Fires	5
3.4 Exposures and Vulnerabilities	7
3.5 Potential Consequences of Severity	8
3.6 Mandatory Requirements and Legal Liability	9
3.7 SECV Insurances	10
4. CONCLUSIONS	10
4.1 Risk of Fire in the Worked-Out Areas and Batters	10
4.2 Legal Liability	10
4.3 Policy Exemption	10
4.4 Improvement to Fire Protection	11
5. RECOMMENDATIONS	11
5.1 Fire Protection Systems	11
5.2 Fire Prevention	11
5.3 Policy Revision	12

REFERENCES

FIGURES

TABLES

APPENDICES

100

100

EXECUTIVE SUMMARY

DRAFT

1. INTRODUCTION

1.1 PURPOSE OF THIS PROJECT

This project aims to assess the fire risk of the worked-out areas of the Morwell Open Cut ("MOC") and ascertain whether an exemption from the Latrobe Valley Open Cuts Fire Protection Policy 1984 (hereinafter "LVOCFPP"), and specifically its sections 1.1.4 and 1.1.5, would be appropriate and justifiable.

1.2 SCOPE AND ASSUMPTIONS

1.2.1 Definition of the worked-out areas

The worked-out areas and batters considered in this study cover the mine area extending eastwards from No. 4 groyne and including the north-eastern and eastern batters.

1.2.2 Assumptions

Unless stated otherwise, it has been assumed in this study that the fire protection policy for the open cuts ("LVOCFPP") is appropriate and reasonable and that presently all fire protection systems at M.O.C. comply with the requirements of this policy.

1.3 BACKGROUND AND CONTEXT

With finite resources to be allocated to fire protection of the whole open cut, M.O.C. considers it best to direct these resources to protection of personnel and assets in operating areas of the cut on the basis that these represent a greater fire risk than the worked-out areas of the mine.

The fire risk of worked-out areas may perhaps be better mitigated by restricting access to worked-out areas and removing power poles from here, maintaining several charged water lines, and by upgrading fire protection systems for the cut as a whole (e.g. more tanker filling points).

2. CONCLUSIONS

2.1 Risk of Fire in the Worked-out Areas and Batters

The risk of fire in the worked-out areas is not minimal, because:

- there are about 20 fires a year in these areas.
- on average, their severity is similar to those fires in working areas of the mine in terms of usual extinction effort.
- these fires are located near key vulnerabilities, mostly in the dirty coal dump near the 200 series conveyors and around the production area in the North-East corner of the pit where a critical bore pump (M 2055) is placed. *

2.2 Legal Liability

The CFA Act overshadows LVOCFPP, imposing a stringent requirement upon M.O.C. to adhere to practicable fire prevention and control measures. LVOCFPP is practicable.

Issues of cost and cost-benefit are not relevant to M.O.C. considerations of its fire protection responsibilities. Practicability is.

2.3 Policy Exemption

Exemption from sections 1.1.4 and 1.1.5 would increase fire risk in the worked-out areas and would increase SECV, and M.O.C., liability in this regard. Presently this risk is not minimal. These issues do not support an exemption.

2.4 Improvement to Fire Protection

Our inspections and calculations indicate the present fire water service system is quite adequate for the worked-out areas, in accordance with the policy.

M.O.C. are correct in directing their thinking towards restricting vehicle access to worked-out areas, removing assets, increasing the number of tanker filling points and so on. These strategies do focus on the fire exposures of the worked-out areas.

This suggests implementation of these preventative and control measures, reinforced where necessary by addition or modification to LVOCFPP accordingly, is the appropriate strategy.

Policy development can thus proceed in line with risk reduction. *

CONFIDENTIAL
DRAFT

3. RECOMMENDATIONS

5.1 Fire Protection Systems

We would suggest the following recommendations based on this study:

- i. Undertake a detailed engineering survey of the fire water system, and include assessment of the North-East corner coal production area in this.
- ii. Update reticulation drawing and hydraulic analysis using computer modelling.
- iii. Use both old clean water tanks for fire water storage and fit a tanker filling point to these (refer Figure 14).

5.2 Fire Prevention

- i. Keep all M.O.C. fire reports on a P.C. data base for regular review. Note that we have provided the 1989-1992 data on diskette with this report.
- ii. Examine restrictions to roadways in the worked-out areas. For example, a permit system could be adopted to control access to specified roads and incorporate a check or control upon vehicle exhaust systems.
- iii. Stop dumping of dirty coal adjacent to the 200 series conveyors. Look to relocate such dumping. *
- iv. Relocate power feeders 15 and 16. We understand a relocation to near the 200 series conveyors is already proposed. *
- v. Commence a pole replacement programme for the 4, 5 and 16 power feeders, replacing timber poles with concrete ones.

5.3 Policy Revision

Suggested revisions to LVOCFPP would be:

- (i) 6 mm/hour precipitation rate seems to be based on 1964 report of 0.25 inch/hour. Check appropriateness.
- (ii) Specify number, distance, capacity requirements for Tanker Filling Points.
- (iii) Remote monitoring for fire pumps and other critical fire protection equipment, audible and visual.

1.1.4 Worked Out Batters (refer to fig 2)

As a minimum requirement worked out batters are to be protected as follows -

- . All benches are to be clay covered.
- . All berms are to be eliminated by trimming or by filling with clay such as to shed fretted coal provided that batter stability calculations indicate that neither of these options will cause batter failure.
- . Fire break zones extending down to full depth of batter should be established such that the length of exposed coal in any one batter is not greater than 500 m. These zones can be in the form of metallised vehicle access ramps, a minimum of 8 m wide or in the form of a 20 m width clay covering.
- . Alternatively, fixed spray breaks may be used, but it should be noted that water for these sprays has not been included under the maximum demand conditions, and this protection should not be considered as reliable as clay fire breaks or vehicle access ramps.
- . Figure 2 shows an example of this protection.

1.1.5 Worked Out Floor of Open Cut

The floor of the open cut is to be protected by the provision of intersecting fire break zones across the floor of the open cut in the form of clay covering. Alternatively, water treatment, regulation or fire service ponds may form the protective barrier. For the period between exposure of the floor and clay covering or the establishment of ponds, protection shall be by the provision of wetted corridors as required for working levels.

FIRE RISK ANALYSIS OF THE WORKED-OUT AREAS AND BATTERS
IN MORWELL OPEN CUT

DRAFT

1. INTRODUCTION

1.1 PURPOSE OF THIS PROJECT

This project aims to assess the fire risk of the worked-out areas of the Morwell Open Cut ("MOC") and ascertain whether an exemption from the Latrobe Valley Open Cuts Fire Protection Policy 1984 (hereinafter "LVOCFPP"), and specifically its sections 1.1.4 and 1.1.5, would be appropriate and justifiable.

1.2 SCOPE AND ASSUMPTIONS

1.2.1 Definition of the worked-out areas

The worked-out areas and batters considered in this study cover the mine area extending eastwards from No. 4 groyne and including the north-eastern and eastern batters. These areas are shown pictorially in figures 1 to 6 inclusive.

The southern batters and the "200 series" conveyors, the power lines and feeders adjacent these on 7 level, the "20 series" conveyors along the eastern batters, and grass level outside the pit are excluded from the scope of this study. Note however that any detrimental impact on these assets that could result from fire spreading from the worked-out areas is considered.



1.2.2 Assumptions

Section 1.1.4 and 1.1.5 of LVOCFPP are reprinted opposite for ready reference.

Unless stated otherwise, it has been assumed in this study that the fire protection policy for the open cuts ("LVOCFPP") is appropriate and reasonable and that presently all fire protection systems at M.O.C. comply with the requirements of this policy.

1.3 BACKGROUND AND CONTEXT

Morwell Open Cut considers that the worked-out areas of the pit may represent a low fire risk. With finite resources to be allocated to fire protection of the whole open cut, it appears best to direct these to protection of personnel and assets in operating areas of the cut on the basis that these represent greater fire risk.

- 2 -
DRAFT

The fire risk of worked-out areas may perhaps be better mitigated by restricting access to worked-out areas and removing power poles from here, maintaining several charged water lines, and by upgrading fire protection systems for the cut as a whole (e.g. more tanker filling points).

2. METHODOLOGY

Our methodology is outlined below. It should be noted that this risk analysis provides an initial appraisal only, given the timeframe for work of 19 days. Where further work would be warranted, this has been indicated.

2.1 DEFINITION OF RISK AND RISK ANALYSIS

Three elements making up the fire risk are considered, as follows:

- the likelihood of fire occurrence in worked-out areas.
- the exposure of SECV assets such as personnel, plant and equipment within the mine as well as outside its boundaries to fire or its immediate consequences, either
 - a) within the worked-out areas, or
 - b) as a result of fire spreading from or through these areas.
- the consequences of any fire in worked-out areas for
 - property/asset loss
 - personnel safety
 - liabilities to SECV or its officers
 - interruption to SECV operations
 - corporate image
 - other community impact outside the mine.

The severity of potential consequences is appraised in terms of both normal loss expectancy and maximum foreseeable loss.

2.2 KEY RISK ISSUES

In summary, the following are included in consideration:

- the mandatory requirements upon M.O.C. for fire protection and suppression.
- the history of fires at M.O.C. and their consequences, and what implications they may have for the current M.O.C. fire risk.

DRAFT

- the current status of the worked-out areas, the nature, size and location of any specific fuels or fire hazards, like exposed coal.
- the susceptibility of key assets like conveyors and pumps to fire in or from worked-out areas.
- the current status of fire protection in these areas in terms of
 - fire prevention
 - fire detection
 - fire suppression, both for extinguishment and for restricting potential spread of fire.

2.3 DATA COLLECTION AND ANALYSIS

2.3.1 Data Collection

Data collection was based largely on review of available documentation and engineering drawings (see reference), site inspections and discussions with a number of SECV personnel. These personnel are listed in Appendix 1.

2.3.2 Data Analysis

A qualitative assessment has been made of overall fire risk and the appropriateness of policy exemption.

Quantitative evaluation has been made of -

- fire reports, obtained for the period November 1989 to April 1992.
- hydraulic performance of the fire water drenching system as applicable to the worked-out areas.
- potential frequency and severity predictions of M.O.C. fire, using a Pareto simulation technique.

3. FINDINGS

3.1 CURRENT STATUS OF THE WORKED-OUT AREAS AND BATTERS

The current status of these areas is illustrated pictorially in figures 3-13 inclusive. In particular, it was noted:

- (i) there are critical assets in the worked-out areas, notably -

DRAFT

- 6.6 kV power feeder lines to bore pumps, clean water pumping station, fire pumps and the 20 series conveyors. These are generally on timber poles.
- critical artesian bores, especially
 - for M1 aquifer : M 2055 and M 3455
 - for M2 aquifer : M 3284, M 2443, M 3079, M 2979 and M 2196
- (ii) there are critical assets (key vulnerabilities) adjacent the worked-out areas, notably the 200 series production-coal conveyors and the 20 series conveyors to MPS and briquette plant. *
- (iii) there is exposed coal. From site visits and after review of an aerial photograph (scale 1:2500 approx) there appear to be several sections of the worked-out area where clay covering has not yet been applied.

Our estimates of area are:

400m x 200	=	80,000
250m x 200	=	50,000
200m x 375	=	84,375
250m x 250	=	62,500
200m x 300	=	<u>60,000</u>

TOTAL 336,875m² or around 8% of the total plan area of the worked-out areas.

- (iv) there are specific activities which could represent a fire hazard, notably -
 - traffic of vehicles without protected exhausts.
 - a coal production operation (refer figure 3), providing coal quantities equivalent to MPS requirements. Note that risk appraisal of this operation was considered as outside the terms of reference for this study.
 - a dirty coal dump near the southern pivot (refer figure 4).

TABLE 2

RICHARD OLIVER

MOBILE PLANT AVAILABLE TO ASSIST WITH
FIRE FIGHTING OPERATIONS
AT MORWELL OPEN CUT COAL MINE

Service or Organisation	Equipment Types and Numbers	Capacity (Litres) Per Unit
Morwell Open Cut Fire Service	1 x Tanker	4,500
	2 x Tanker	*Roadworks 16,000*
	Big gun monitors (Trailer mounted) 150mm dia.	7 Units
	Crane mounted monitors 150mm dia.	3 Units
Yallourn Open Cut Fire Service	3 x Tankers	4,500
	3 x Tankers	15,000
Loy Yang Open Cut Fire Service	2 x Tankers	15,000
	2 x Tankers	4,500
Morwell Essential Services	1 x Tanker	200
	1 x Pumper	900
Yallourn Essential Services	1 Pumper	900
Loy Yang Essential Services	1 x Tanker	900
	1 x Pumper	1400
CFA	Communications Bus	
CFA Morwell	1 x Tanker	3000
	1 x Pumper	1500
CFA Churchill	1 x Tanker	2000
	1 x Pumper	900
CFA Traralgon	1 x Tanker	3000
	1 x Pumper	1500
CFA Moe	1 x Tanker	2000
	1 x Pumper	1400
CFA Morwell East		
CFA Driffield		
Australian Paper Mills	8 x Tankers	
	1 x Helicopter	
Department Conservation, Forest and Lands	3 x Helicopters through CFA	

DRAFT

- (v) the predominant winds are directed from the south-west and west across the mine towards the key vulnerabilities on the southern and eastern batters. Appendix 2 summarises wind details.

3.2 CURRENT STATUS OF THE FIRE PROTECTION AVAILABLE TO THE WORKED-OUT AREAS

Similarly, figures 15-20 inclusive generally indicate the present nature and scope of the fire protection, and the fire water service system in particular.

A detailed appraisal of this system's state of readiness was not made, this being outside our terms of reference.

The performance of the fire water service for the worked-out area was assessed however in terms of the policy, and details are given in Appendix 3. In summary, our findings are that the water supply to the worked-out areas appears satisfactory at present. In fact, our limited calculations suggest water supply could be, a little greater (perhaps 20% more) than policy requirement for the worked-out areas and batters. This water requirement is for the exposed coal (see 3.1 iii previous).

Table 2 opposite summarises our understanding of the fire/water tanker resources available to M.O.C. for fire control.

3.3 FIRE HISTORY AND THE LIKELIHOOD OF FIRES

3.3.1 General Overview

The broad history of fires in the Latrobe Valley and at the open cuts in particular, places SECV, and thus M.O.C., in a position of high public and political profile where fire is concerned. This context must be considered a risk factor. We have briefly summarised the outcomes of the 1944 Yallourn and 1977 M.O.C. fires and compared these with M.O.C. fire protection status as at present. This summary is given in Table 1 and "profiles" current risk in these historical/political terms. It would appear that the potential effectiveness of current fire countermeasures is somewhat greater than in 1977, based on improved communications and coordination (Displan), fire fighting technology and techniques.

Other implications from our table would appear self-evident.

Morwell Open Cut Fire Report

Cause of Fires in the Worked Out Area




Figure 21

Morwell Open Cut Fire Report

Burning Source for Fires in the Worked Out Area




Figure 22

DRAFT

3.3.2 Fire History of the M.O.C. Worked-out Areas

The results of analysis of all M.O.C. fire reports for the period 11/89 to 4/92 inclusive are illustrated in figures 21 and 22 (opposite page), figure 23 overleaf.

Summarising these results:

- (i) there have been 28 fires reported in the worked-out areas in this period. This suggests occurrence of around 20 fires per year.
- (ii) primary causes are motor vehicles and burning/welding. "Unknown" causes could include bushfire spotting, lightning, electrical causes like conductor clashing on power feeders, falling power poles, etc. These have occurred in the worked-out areas.
- (iii) loose coal was primarily the material burnt.
- (iv) piped water was the major means of fire suppression.
- (v) in terms of manhours and equipment hours reported for extinguishment, the fires in the worked-out areas are of similar severity on average to those occurring in the working areas of the mine.
- (vi) the fires are most frequently located in the dirty coal dump and the coal production operation in the North East corner of the pit. Figure 24 overleaf shows locations of all fires and also indicates their relative severity.

Appendix 4 provides a summary of the fires in the worked-out areas.

3.3.3 Fire Trends

Data analysis shows -

- (i) the number of fires per year increased through 1984 - 1989. Fires in 1990/91 were substantially fewer than for 87/88 and 88/89, though this may be an artefact of reporting.
- (ii) as could be expected, fires are most numerous in summer (January).

Figures 25 and 26 opposite illustrate these trends.

Morwell Open Cut Fire Report

Method Used for Fires in the Worked Out Area




Figure 23

DRAFT

Morwell Open Cut Fire Report

Number of Fire Incidents




Figure 25

Morwell Open Cut Fire Report

Monthly Number of Reported Fires




Figure 26




Figure 24

MORWELL OPEN CUT FIRE INCIDENCE
 WORKED OUT AREA
 FOR THE PERIOD NOV '89 TO APR '92
 SIZE OF 'FIRE' SYMBOL INDICATES
 ELAPSED EXTINGUISHMENT TIME

- LEGEND
- ROUTE 1
 - ROUTE 2
 - ROUTE 3
 - ROUTE 4
 - ROUTE 5
 - ROUTE 6
 - ROUTE 7
 - AMBULANCE PILOT POINT

DRAFT

3.4 EXPOSURES AND VULNERABILITIES

3.4.1 Personnel Safety

This would appear a minimal risk. We understand fires at M.O.C. have not caused loss of life previously. This would not be anticipated from fire in worked-out areas.

3.4.2 Loss of Assets and Business Interruptions

As previously indicated, conveyors are vulnerable to spread of fire from the worked-out areas.

Loss of power to pumping stations or 20 series conveyor, through damage to feeders 4, 5, 15 and 16, is an evident exposure as are electrical cubicles, transformers and associated power supply cables linked to bores located in the worked-out areas.

Fire could possibly progress along the northern batters into operating levels or more likely be blown into working areas, but this would seem less likely than the abovementioned risk exposures.

3.4.3 Spread of Fire

3.4.3.1 From or Through the Worked-Out Areas

With all but about 8% of the plan area of the worked out areas and batters covered by water or clay, significant general spread of fire through the worked-out areas does not appear to be a key threat.

Rather, spread of fire may be:

- i quite localised. Thus, fire immediately adjacent the conveyors, at or near pump or pole locations is relatively the greatest exposure.
- ii through the worked-out batters. The policy addresses this.
- iii from embers of coal or foliage fires blown by the wind.
- iv from mechanical means like vehicle traffic or other work activity.

DRAFT

3.4.3.2 Vulnerabilities Outside the Pit

Again, the risk here is for fire to potentially spread to grass level from its initiation within the worked-out areas of the pit.

However there is substantial combustible foliage within the worked-out area and this could possibly "spot" a grass level fire. Relative to 3.4.2 above, risk of this seems less as we are led to believe fire progress from within to outside the pit has never occurred.

3.5 POTENTIAL CONSEQUENCES OF SEVERITY

3.5.1 Normal Loss Expectancy

From the results of analysis of fire reports available to this study, normal loss expectancy from fire in the worked-out areas would appear to be of order:

- average 2 manhours, 1 equipment hour per fire; maximum 18 manhours, 5 equipment hours per fire.

These averages are similar to those for fires in the operating areas of the mine. However, for perspective, maxima reported there are 154 and 23 "hours" respectively.

- no reported asset \$ loss. No reports of actual cost were found in our analysis.

On average, fire report data indicates total duration (elapsed time) of all fires at M.O.C. could be expected to be around 75 hours per year. This duration represents the time from initial attendance at the fire through to its extinction.

Some 255 fires per annum can also be expected on average.

3.5.2 Maximum Foreseeable Loss

An initial simulation from the available data for the whole mine suggests there is -

- about a 1% chance of fire severity around 3 times greater than usually experienced in recent years (1989-1992).

DRAFT

- a less than 0.5% chance of fire severity around 5 times greater than usual.

Furthermore, this chance represents the likelihood of at least one such fire per year. That is, there is a feasible possibility of a fire of major severity occurring each year.

Figure 27 opposite illustrates this simulation. Note however that the simulation should be regarded as preliminary.

Such a simulation for the much smaller fire data of the worked-out areas would be therefore meaningless. For the worked-out areas, our simulation at this stage simply then suggests it is important to maintain the LVOFCPP as an effective protection policy in light of possible, not necessarily probable, severity of loss from any fire initiated in and spreading from the worked-out areas or through the batters.

Should power supply be lost to critical bore pumps (e.g. M 2055 say) located in the worked-out areas as a result of fire, then SECV research suggests the theoretical possibility of heave of the mine floor after about 3 days of loss of mine dewatering. Discussion with mine hydrogeology indicated this possibility has however been contradicted in practice.

3.6 MANDATORY REQUIREMENTS AND LEGAL LIABILITY

The SECV is bound by Section 43(1)(a) of the Country Fire Authority Act to "prevent the occurrence of fires on and to minimise the danger of the spread of fires on or from any land vested in it or under its control or management

The legal implications of any change - exemption and/or modification - to LVOCFPP sections 1.1.4 and 1.1.5 are appraised in detail in Appendix 5. In summary, key findings for M.O.C. are :

- (i) the statutory requirement (CFA Act) is more strict than a duty of care, and thus own policy like LVOFCPP.
- (ii) M.O.C. must take all practicable steps to prevent and suppress its fires. Because what it has been doing in applying LVOFCPP is practicable by definition, any change in that policy to reduce stringency of precautions would increase SECV liability. That is, the proposed exemption would increase liability (risk).

Therefore, any policy modification should aim to enhance prevention and/or suppression unless SECV (and M.O.C.) is willing to accept increased risk/liability.

DRAFT

(iii) questions of cost (and thus cost-benefit) are not relevant.

3.7 SECV INSURANCES

It is understood that any implications of possible exemption from LVOCFPP in this case are to be determined by SECV Risk Management and Claims Division, for example, by way of their review of the results of this report.

We would therefore simply note, further to 3.4⁶ above, that any policy change that would be likely to increase the material risk to SECV insurers would need to be advised to those insurers for their deliberations otherwise the possibility could arise that they may void their present responsibility in event of any insured loss.

4. CONCLUSIONS

4.1 Risk of Fire in the Worked-out Areas and Batters

The risk of fire in the worked-out areas is not minimal, because:

- there are about 20 fires a year in these areas.
- on average, their severity is similar to those fires in working areas of the mine in terms of usual extinction effort.
- these fires are located near key vulnerabilities, mostly in the dirty coal dump near the 200 series conveyors and around the production area in the North-East corner of the pit where a critical bore pump (M 2055) is placed.

4.2 Legal Liability

The CFA Act overshadows LVOCFPP, imposing a stringent requirement upon M.O.C. to adhere to practicable fire prevention and control measures. LVOCFPP is practicable.

Issues of cost and cost-benefit are not relevant to M.O.C. considerations of its fire protection responsibilities. Practicability is.

4.3 Policy Exemption

Exemption from sections 1.1.4 and 1.1.5 would increase fire risk in the worked-out areas and would increase SECV, and M.O.C., liability in this regard. Presently this risk is not minimal. These issues do not support an exemption.

4.4 Improvement to Fire Protection

DRAFT

Our inspections and calculations indicate the present fire water service system is quite adequate for the worked-out areas, in accordance with the policy.

M.O.C. are correct in directing their thinking towards restricting vehicle access to worked-out areas, removing assets, increasing the number of tanker filling points and so on. These strategies do focus on the fire exposures of the worked-out areas.

This suggests implementation of these preventative and control measures, reinforced where necessary by addition or modification to LVOCFPP accordingly, is the appropriate strategy.

Policy development can thus proceed in line with risk reduction.

5. RECOMMENDATIONS

5.1 Fire Protection Systems

We would suggest the following recommendations based on this study:

- i. Undertake a detailed engineering survey of the fire water system, and include assessment of the North-East corner coal production area in this.
- ii. Update reticulation drawing and hydraulic analysis using computer modelling.
- iii. Use both old clean water tanks for fire water storage and fit a tanker filling point to these (refer Figure 14).

5.2 Fire Prevention

- i. Keep all M.O.C. fire reports on a P.C. data base for regular review. Note that we have provided the 1989-1992 data on diskette with this report.
- ii. Examine restrictions to roadways in the worked-out areas. For example, a permit system could be adopted to control access to specified roads and incorporate a check or control upon vehicle exhaust systems.
- iii. Stop dumping of dirty coal adjacent to the 200 series conveyors. Look to relocate such dumping. *

DRAFT

- iv. Relocate power feeders 15 and 16. We understand a relocation to near the 200 series conveyors is already proposed.
- v. Commence a pole replacement programme for the 4, 5 and 16 power feeders, replacing timber poles with concrete ones.

5.3 Policy Revision

Suggested revisions to LVOCFPP would be:

- (i) 6 mm/hour precipitation rate seems to be based on 1964 report of 0.25 inch/hour. Check appropriateness.
- (ii) Specify number, distance, capacity requirements for Tanker Filling Points.
- (iii) Remote monitoring for fire pumps and other critical fire protection equipment, audible and visual.

REFERENCES

DRAFT

1. ENGINEERING DRAWINGS

1. Morwell open cut division 6.6 kV distribution feeders single line diagram (reference LV43/102/007 DRG1-AR), 20 November 1991.
2. Morwell Open Cut Fire and Water Service - General Layout as at 8 August 1990 (DRG No. MS 12-2-1/5/3z).

2. SECV REPORTS AND MEMORANDA

1. Third International Mine Water Congress Excursion E2, Latrobe Valley Victoria
Aquifer Dewatering Operations at Morwell Open Cut pp. 1-20, G. Sherlock 1988.
2. Morwell Open Cut North Eastern Batters - Road Closures and Fire Service Pipe Removal.
R. Supplitt (part of a value management study) 1991, 8pp.
3. Golder Associates Pty Ltd, Review of Aquifer Dewatering at Morwell Open Cut 6, July 1990.
Report to State Electricity Commission of Victoria (report no. 90612241).
4. Memorandum 27 March 1992, Review of 1991/2
Summer Bushfire Mitigation Performance for 1991/2 (from General Manager Production) 6 pp.
5. Morwell Open Cut Fire Protection Report by Investigating Committee, June 1964. (at 15 December 1964), 8 pp.
6. Issues Paper - Protection of SECV Latrobe Valley Assets from Rural Wildfire. R. Incoll (updated - post 1984) 54 pp.
7. SECV Production Group. Bushfire Mitigation Action Plan 1991/2 28 pp.
8. SECV - Liability Insurance Underwriting Submissions for 1989/90 and 1991/2.

DRAFT

9. Delaney WA. Morwell Open Cut Fire Risk Analysis. Research and Development Department Report, 30 November 1990. 33 pp.
10. Morwell Open Cut Fire 4-6 November 1977. Summary report by Review Committee, 30 June 1978. 19 pp plus appendices.

3. OTHER REPORTS

1. L.E.B. Stretton. Report of the Royal Commission to inquire into Yallourn Fires of 14 February 1944. 13 pp.
2. Von Rothkirch, B. Water Supply system for Fire Control at Garzweiler Open-Cut Mine. in Braunkohle, 1986, 38(9), pp. 268-273.

4. POLICY REPORTS

1. Latrobe Valley Open Cuts Fire Protection Policy (revised) November 1984. plus review of section 1.4.3 Timbered Area, December 1990.
2. Policy for the Protection of SECV Latrobe Valley Assets from Rural Fires, July 1986, 8 pp. plus attachments.
3. Draft Policy, October 1985 for Protection of SECV Latrobe Valley Assets from the Rural Fire Threat. Includes Fire Issues paper.

5. GENERAL

1. Hall, J.R. and Sekizawa, A. Fire Risk Analysis-General Conceptual Framework for Describing Models. Fire Technology, February 1991, pp 33 - 53.




FIGURE 1: General view of the worked-out area of Morwell Open Cut (M.O.C.), looking at the eastern batters over No. 4 groyne in the foreground.




FIGURE 2: General view of the right hand portion of the worked-out area, looking east along the southern batters and the "200 series" conveyors. No. 4 groyne and the start of the present working area of the mine are in the lower half of the picture.



FIGURE 3: Coal winning operation using mobile plant and haul trucks located in north-east corner of the worked-out area.




FIGURE 4: Dirty coal dump in worked-out area (looking south).




FIGURE 5: Looking north across the worked-out area along No. 3 groyne and across the dirty water reservoir.




FIGURE 6: Looking north-east to the northern batters across the worked-out area (from same location as for Figure 5 above). Note foliage, vehicular traffic and the 1050 mm diameter dirty water main in mid-picture.




FIGURE 7: Looking generally north along the eastern batters, "20 series" conveyor in mid-picture. Note 6.6 kV power distribution feeder lines no's 15 and 16 coming down the batters on concrete poles.




FIGURE 8: Looking north-north-east down onto "20 series" conveyor, showing their power feed lines (feeders 5, 16 and 4).




FIGURE 9: Looking north over "20 series" conveyor and along feeder lines 16 and 4 crossing the worked-out area, predominantly on timber poles.



FIGURE 10:
Feeders 15 and 16
coming down the
eastern batters
and across the
worked-out area
(looking west).




FIGURE 11: Feeders 15 and 16 crossing nearly through the middle of the worked-out area on timber poles, looking east.




FIGURE 12: Electrical cubicle for switchgear, etc. (at left) and 300 kVA transformer (at right) to power artesian bore pump, located near southern pivot in the worked-out area.




FIGURE 13: Artesian bore pump (per reference in Figure 12). Note electrical cubicle at right; foliage.



FIGURE 14: Two 100,000 gallon steel tanks, previously used for clean water storage, located on level 2 at the eastern end of the worked-out area. Viewed across "20 series" conveyor in the foreground.




FIGURE 15: Fire detection capability indicated by view from eastern batters fire tower (extreme upper left) and control centre. Top of the two old clean water tanks (reference Figure 14) visible in mid-picture.




FIGURE 16: 100,000 gallon clean and dirty water tanks located near Hazelwood power station, for fire water storage and pressure control of the M.O.C. fire protection system.




FIGURE 17: "H Section" located on grass level above the mine for valve control and mixing of clean and dirty water. Looking along the clean water line towards the mine, dirty water main on the right.




FIGURE 18: View from northern batters down onto dirty water reservoir and dirty water pumping station in mid-picture. Note clay and gravel on the bench/roadway in the foreground.

FIGURE 19:
Dirty water main at
northern end of No.3
groyne adjacent dirty
water pumping station.
Note reinforcement
of pipe elbow against
water hammer and
momentum.





FIGURE 20: Clean water pumping station (looking towards southern pivot); three of five pumps out for repair.

Table 1(a) RELEVANCE OF PREVIOUS MAJOR OPEN-CUT FIRES TO THE PRESENT RISK EXPOSURES OF M.O.C. WORKED-OUT AREAS

FROM 1977 MORWELL OPEN CUT FIRE REPORT	1992 - MORWELL WORKED-OUT AREAS
1. Obtaining assistance from outside organisations: Call to CFA initiated approx. 3 hours after fire was first noticed, and had spread significantly.	Call out is now initiated by Fire Services officer upon spread of fire from point of ignition.
2. Other SECV resources deployed from Yallourn Open Cut Fire Services and Engineering Services Forestry Group.	
3. External services: CFA - CFA control vehicle, APM, CMF, RAAF, Regional Office of SES, Gippsland District Police.	
4. Five large capacity water tankers obtained from various sources. Vehicle patrols used to combat spot fires, especially along southern and eastern batters.	Now have increased - refer to attached mobile equipment inventory (Table 3).
5. 600-700 personnel directly involved in fire fighting activity.	Are available in 1992.
6. Elevating platform vehicle units used to control fires on high batters. Delay in their availability.	Are available in 1992.
7. Interruption to power supplies for pumps and other equipment occurred due to burning cables.	Possible.
8. Standardisation and compatibility of fire fighting equipment between SEC and those used from external sources.	Are available in 1992.
9. Dredger fire protection required a great deal of supplementary fire fighting activity.	Possible.
10. Coal bunker reserves were initially low - total capacity of Hazelwood Slot Bunkers was 25,000 t (had 9,400 tonnes coal). Morwell Raw Coal Bunker capacity 3,600 tonnes (had 400 tonnes coal).	Possible.
11. Fire initiated by burning coal particles falling from vehicle exhaust.	Possible - remains a significant cause of ignition of fires in the worked-out areas.
12. Fire initiated in a location outside the effective range of the water spray system, in a dry area.	Possible.
13. Ring main had not been formed, less pressure than normal being available.	Possible.
14. Shortage of effective hose application on site.	Improved.
15. Pre-warming alerts achieved by declaring Total Fire Ban days or CFA Declared Fire Danger Period. Neither had been declared on the day of the fire.	Now use BYRAM-KEETCH DROUGHT index in addition to these indicators.
16. Fire Service installations up to date and in line with open cut fire protection policy and progressive development plans.	LVOCFPP has been reviewed since.
17. Difficulties in effective management and deployment of equipment and inexperienced personnel.	Fire training for SECV employees improved.
18. Difficulty in contending with fires in high batters and for working under night conditions.	Possible. Improved fire protection equipment for extended reach hoses and reems.
19. Road transport used to continue coal supply to Morwell Power Station.	Remains a viable alternative to coal transport by conveyor.

Table 1(n) RELEVANCE OF PREVIOUS MAJOR OPEN-CUT FIRES TO THE PRESENT RISK EXPOSURES OF M.O.C. WORKED-OUT AREAS

FROM 1977 MORWELL OPEN CUT FIRE REPORT		1992 - MORWELL WORKED-OUT AREAS
20. All welding and flame cutting activities carried out under a permit system.		Are available in 1992.
21. Average of 92 fires per year over previous five years from various causes.		Changed "trigger levels" for fire reports - annual average is now 300.
22. Difficult fire suppression since: a) distance from pipelines/multiple hoses & b) reduced pressure/union bans.		Possible.
23. Strong 75 km/h winds/direction changes.		Possible.
24. Fire threat to: conveyors, cables, dredgers, mobile plant.		Possible.
25. Reduced maintenance on reticulation system since work was diverted.		Possible.
26. Appropriate check valve for LVW & SB connections for back-up water supply.		Not known.
27. Convert critical valves to remote control and/or motorised operation.		Not done.
28. Monitoring of operational status of critical valves (open/closed) at Open Cut Control and Fire Service Control Centres.		Not done. <i>Attempted - not successful</i>
29. Enable greater use of Hazelwood Cooling Pond as a source of fire service supply.		Possible. <i>Done</i>
30. Working party specifically and continuously allocated to maintenance and extension of fire service installations.		<i>Not done-to-date. Done but since changed work</i>
31. Additional water filling points for tankers. Extra hydrant manifolds near dredgers. Signposting system in the open cut.		Additional Tanker Filling Points are recommended by this report.

Table 1(b). RELEVANCE OF PREVIOUS MAJOR OPEN-CUT FIRES TO THE PRESENT RISK EXPOSURE OF M.O.C. WORKED-OUT AREAS

FROM 1944 ROYAL COMMISSION REPORT INTO THE FIRES AT YALLOURN	1992 - MORWELL
1. The fire was initiated external to the mine. It spread to the mine by spotting from nearby bushfire.	Still possible - is a focus of the prevention campaign. Open cut area is increasing.
2. Unbroken tract of timber between origin of fire and Yallourn.	Not applicable.
3. No overall co-ordinating plan to handle the state of emergency of such magnitude.	Displan is now in place.
4. Vaguely defined organisational structure of the general fire services.	Improved organisation within SECV and via Displan with other agencies.
5. Separate departments were responsible for their own fire service (power station, open cut and briquette works).	
6. Lack of co-ordination of volunteers.	Displan is now in place.
7. Bush fire likely to originate from north or west of Yallourn.	Not applicable to this study.
8. Engineer responsible for fire precaution not expert in the field, able to afford the role only part time attention, and used out of date techniques.	Fire prevention is now with trained firemen and Land Service personnel.
9. Large quantities of char exhausted from stacks of power station and briquette factory and deposited upon surrounding country side. Provides additional fuel for an existing fire.	No longer takes place.
10. Fire suppression/protection measures in the mine were not reasonably adequate.	Reticulation and pumping capacity increased from 1944 levels.
11. Measures taken for protection during the last two or three hours before the fire started (in the mine) were not adequate; due to erroneous assumptions of winds maintaining prevailing direction.	Improved state of preparedness and improved monitoring of meteorological conditions.
12. Water sprinklers on each berm at separation distances of 150 feet, to contain fire within compartments.	Same.
13. Rely on use of hoses to extinguish fires.	Same. Improved design of equipment and more extensive capability.
14. Unable to adequately fight fire on the faces of the berms: water pressure and flow rate inadequate.	Specially designed monitors are now provided.
15. Provision for better tactical distribution of equipment to the various parts of the mine during a time of emergency.	Done.
16. Ongoing revision of the water main and sprinkler system be made to reflect the changing needs of the mine.	Significant design reviews resulted in fact, various reviews in 1962, 1964, culminating in the LVOCFPP of 1977 and its revision in 1984.
17. Upgrade available water pressure.	Design standard is LVOCFPP? No further information available to this study.
18. SEC Personnel be trained in the use of equipment and fire fighting techniques.	Done.
19. External assistance; Country Fire Brigade, Air Raids Precaution Body?, The Forest Gang, Volunteers	External agencies now co-ordinated via DISPLAN and Emergency Response plans.
20. Improve marginal protection.	Part of Land Services fire protection.

Table 1(b). RELEVANCE OF PREVIOUS MAJOR OPEN-CUT FIRES TO THE PRESENT RISK EXPOSURE OF M.O.C. WORKED-OUT AREAS

FROM 1944 ROYAL COMMISSION REPORT INTO THE FIRES AT YALLOURN	1992 - MORWELL
21. Engage the services of an adviser on Forest fire protection and suppression who has direct access to the board of commissioners.	Not known. Statutory authority with Dave Francis
22. Key utility for State of Victoria.	Now a number of other power stations on the state grid - Morwell Power Station is strategically important.
23. Several fires - multiple ignition sources.	Possible.
24. Ignition by bushfires/flying embers.	Possible.
25. "Wanton and illegal behaviour by persons outside SEC control."	Possible.
26. "Fire is an almost unavoidable concomitant of brown coal open cut mining."	Possible.

RICHARD OLIVER

APPENDICES

DRAFT

APPENDIX 1

People contacted during the course of this project are indicated below:

NAME	POSITION/SECTION
John Bohan	Mine Planning & Technology - Engineer
Alan Brown	Scientific & Environmental Services
Bill Brown	Fire Services Officer M.O.C.
Rob Curtis	<i>- Safety Officer, MOC</i>
Graham Dave	Fire Services Officer M.O.C.
Wal Delaney	Engineer, Applied Science Section HRL
Dave Francis	Land Services Officer
Graeme Freshwater	M.O.C. Mine Manager
Rob Gaulton	Regional Geologist
Rob Hutchings	<i>Manager, Production Technology</i>
Bob Joynt	Head, Applied Science Section HRL
Ian Kruse	Manager, Risk Management & Claims Division
Ted Kuklinsky	M.O.C. Electrical Services
Peter Mackay	<i>Engineer</i> M.O.C.
David Murray	Mine Planning & Technology - Engineer
Alf Ottrey	Head, Coal Evaluation Section HRL
Darryl Patching	Scientific & Environmental Services - Applied Technology
Richard Polmear	M.O.C. Production Scheduling Supt.
Chris Salter	Latrobe Valley Systems Protection <i>Officer</i>
Jim Somerville	(Land Services, Manager)
Rob Supplitt	Geotechnology Services
Phil Taylor	<i>Engineer</i> M.O.C.
Andy Teggart	M.O.C. Electrical Services - Area Lines Manager
Colin Young	(Loy Yang) Latrobe Valley Essential Services Manager
	Fire Services Officer M.O.C.
	<i>Employee</i>

APPENDIX 2

PREVAILING WINDS DURING SPRING AND SUMMER
AT MORWELL OPEN CUT

Based upon data from air quality monitoring stations located at Thoms Bridge (situated to the north of the mine) and Yinnar South (situated approximately south of the mine), the predominant winds in Spring and Summer prevail from the West and South Westerly directions and are at or above speeds of 5 m/s.

Whilst the wind information examined from these stations related only to readings taken over Spring and Summer periods, it highlights that the most common prevailing winds during the period of greatest fire danger would tend to spread a fire within the mine toward the eastern and southern batters.

Therefore, given the occurrence of a fire within the open cut, critical coal transport conveyors and equipment located along the Southern and Eastern batters of the mine becomes vulnerable to the spread of any fire under the influence of winds prevailing from the West and South Westerly directions.

Such fire could possibly initiate in, or progress through, the worked-out areas.

RECORDED DATA OF WINDS PREVAILING FROM WESTERLY AND SOUTH-WESTERLY DIRECTIONS
AT THOMS BRIDGE AND YINNAR SOUTH AIR QUALITY MONITORING STATIONS.

RICHARD OLIVER

THOMS BRIDGE

SOUTH - WEST		FREQUENCY					
		Year		Spring		Summer	
Winds Equal to or in excess of 5m/s.	Averages	1987/88	1988/89	1989/90	1990/91	All Hours	All Hours
		19.5%	12.4%	14.1%	9.4%	6.1%	9.2%
		31.3%	40.4%	30.6%	27.1%	5.5%	6.7%
		4.8%	4.2%	5.2%	13.9%	4.8%	7.7%
		14.8%	15.8%	7.6%			

WEST		FREQUENCY					
		Year		Spring		Summer	
Winds Equal to or in excess of 5m/s.	Averages	1987/88	1988/89	1989/90	1990/91	All Hours	All Hours
		31.3%	40.4%	30.6%	27.1%	24.3%	9.7%
		13.4%	19.8%	19.0%	29.7%	31.1%	10.2%
		24.0%	18.9%	24.6%	20.5%	19.0%	8.9%
		19.7%	12.1%				

Over ALL SPEEDS,
wind prevailing from the WESTERLY direction were most dominant.
(Also significant were winds prevailing from South Westerly direction.)

WEST		FREQUENCY					
		Year		Spring		Summer	
ALL SPEEDS	Averages	1987/88	1988/89	1989/90	1990/91	All Hours	All Hours
		36.3%	46.1%	38.8%	37.6%	40.3%	22.3%
		21.7%	22.1%	25.3%	32.1%	45.8%	22.5%
		21.7%	22.1%	25.3%	32.1%	38.3%	19.6%
		25.3%	31.7%	24.0%		37.2%	

YINNAR SOUTH


SOUTH - WEST		FREQUENCY					
		Year		Spring		Summer	
Winds Equal to or in excess of 5m/s.	Averages	1989/90	1990/91	3pm	All Hours	3pm	All Hours
		12.9%	13.3%		4.6%	13.0%	3.4%
		13.1%	4.3%	15.7%	4.3%	18.4%	6.4%

WEST		FREQUENCY					
		Year		Spring		Summer	
Winds Equal to or in excess of 5m/s.	Averages	1989/90	1990/91	3pm	All Hours	3pm	All Hours
		22.6%	7.2%		14.8%	3.7%	0.9%
		7.7%	5.3%	3.1%	4.4%	4.6%	3.3%

Over ALL SPEEDS,
wind prevailing from the SOUTH WESTERLY direction
were most dominant. (Also significant were winds
prevailing from Westerly direction.)


SOUTH - WEST		FREQUENCY					
		Year		Spring		Summer	
ALL SPEEDS	Averages	1989/90	1990/91	3pm	All Hours	3pm	All Hours
		29.0%	39.8%		36.6%	33.3%	40.2%
		34.4%	41.8%	42.0%	46.9%	50.6%	46.8%

3 AM





SPRING (SEP TO NOV)
1990



3 PM



ALL HOURS



SUMMER (DEC TO FEB)
1990/91



SEASONAL WIND ROSES


STATION: 9 THOMS BRIDGE
 SEASONS: SPRING & SUMMER
 YEAR: 1990/91

CALMS %
 OP. %

WIND SPEED CLASSES (M/S)




FREQUENCIES (%)




CALM: WIND SPEED LESS THAN OR EQUAL TO 0.3 M/S
 NOTE: DATA SOURCE RECORDS WIND SPEEDS TO THE NEAREST 0.1 M/S





3 AM



3 PM



ALL HOURS



SEASONAL WIND ROSES

STATION: 9 THOMS BRIDGE
 SEASONS: SPRING & SUMMER
 YEAR: 1989/90

CALMS %
 OP. %

WIND SPEED CLASSES (M/S)




FREQUENCIES (%)




CALM: WIND SPEED LESS THAN OR EQUAL TO 0.3 M/S
 NOTE: DATA SOURCE RECORDS WIND SPEEDS TO THE NEAREST 0.1 M/S

3 AM





SPRING (SEP TO NOV)
1987



3 PM



ALL HOURS




SUMMER (DEC TO FEB)
1987/88



SEASONAL WIND ROSES


STATION: 9 THOMS BRIDGE
 SEASONS: SPRING & SUMMER
 YEAR: 1987/88



CALMS %
 OP. %


CALM: WIND SPEED LESS THAN OR EQUAL TO 0.3 M/S
 NOTE: DATA SOURCE RECORDS WIND SPEEDS TO THE NEAREST 0.1 M/S

3 AM





SPRING (SEP TO NOV)
1988



3 PM



ALL HOURS




SUMMER (DEC TO FEB)
1988/89



SEASONAL WIND ROSES

STATION: 9 THOMS BRIDGE
 SEASONS: SPRING & SUMMER
 YEAR: 1988/89


CALMS %
OP. %




CALM: WIND SPEED LESS THAN OR EQUAL TO 0.3 M/S
 NOTE: DATA SOURCE RECORDS WIND SPEEDS TO THE NEAREST 0.1 M/S

3 AM



SPRING (SEP TO NOV)
1989





3 PM



ALL HOURS




SUMMER (DEC TO FEB)
1989/90




SEASONAL WIND ROSES

STATION: 31 YINNAR SOUTH
 SEASONS: SPRING & SUMMER
 YEAR: 1989/90




CALM: WIND SPEED LESS THAN OR EQUAL TO 0.3 M/S
 NOTE: DATA SOURCE RECORDS WIND SPEEDS TO THE NEAREST 0.1 M/S


ALL HOURS





3 PM




3 AM



SPRING (SEP TO NOV)
1990



SUMMER (DEC TO FEB)
1990/91



SEASONAL WIND ROSES

STATION: 31 YINNAR SOUTH
SEASONS: SPRING & SUMMER
YEAR: 1990/91

WIND SPEED CLASSES (M/S)

< 2 2-5 5-10 > 10

FREQUENCIES (%)

30 60 90

CALMS %
OP. %

CAUTION: WIND SPEED LESS THAN OR EQUAL TO 0.3 M/S
NOTE: DATA SOURCE RECORDS WIND SPEEDS TO THE NEAREST 0.1 M/S

APPENDIX 31. HYDRAULIC APPRAISAL OF FIRE WATER DEMAND FOR WORKED-OUT AREAS

1.1 BACKGROUND

The Latrobe Valley Open Cuts Fire Policy details the method for determination of fire water demand in the worked-out areas. Water is required:

- (i) for water spray on exposed coal, prior to the application of clay covering (Section 1.1.5 refers).
- (ii) for fire protection (Section 2.1.2 refers).

The following brief analysis seeks to determine the best estimate of the maximum demand for fire water in worked-out areas, in accordance with the policy.

(i) Exposed Coal in Worked-Out Areas

From site visits and after review of an aerial photograph (scale 1:2500 approx.) there appear to be several sections of the worked-out area where clay covering has not been applied. These sections measure:

400m x 200	=	80,000
250m x 200	=	50,000
200m x 375	=	84,375
250m x 250	=	62,500
200m x 300	=	<u>60,000</u>

TOTAL 336,875m²

The extent of water spray coverage is 50%, leaving alternating corridors of wet coal and dry coal of 50 metres width. The design precipitation is given as 6mm/hour.

$$\begin{aligned} \text{Spray Rate} &= 336,875\text{m}^2 \times 50\% \times 6\text{mm/h} \\ &= 280 \text{ L/second} \end{aligned}$$

An allowance for hydraulic balancing of friction losses should provide for up to 15% flow in addition to the minimum. i.e. design for 325 L/second for coal spraying.

(ii) Fire Protection

Section 2.1.2 of the LVOCFP policy outlines the methodology for determination of flow rates as follows, using the greater of design method A or B.

OPTION A		Required Rate L/Second
(i)	all rotary sprays and all machine protection	Nil
(ii)	three hydrants on each header on working levels	Nil
(iii)	rotary and birdsmouth sprays, for quarter length of trunk conveyor	Nil
OPTION B		Required Rate L/Second
(i)	one half rotary sprays and all machine protection on working levels	Nil
(ii)	three hydrants per header for half headers on working face	Nil
(iii)	rotary and birdsmouth sprays for half length trunk conveyor	Nil
(iv)	three hydrants per header for half trunk conveyor	Nil

It is instructive to note that the policy presumes that the exposed coal surfaces will be clay covered - hence there is no perceived need for an allowance for hosestreams in such areas.

(iii) Other Design Considerations

The remaining sections of Clause 2 in the policy relate to requirements for the fire protection water supplies. These include:

- dual sources; minimum supply to provide 50% of calculated demand.
- adequate capacity for 24 hours plus make-up.
- maximum system pressure of 115m.
- remote system monitoring of critical functions.

1.2 HYDRAULIC CALCULATION METHODS

A precise analysis of the hydraulic performance of the various fire water systems is beyond the immediate scope of this study. There are severe limitations regarding the available data, including the currency of reticulation drawings (discrepancies exist), pipe leakage rates, and details on equivalent pipe-roughness co-efficients. The collection of this data has not yet been undertaken by SECV - the following methodology is therefore limited.

Important design constraints are:

- (i) duplicated water supply; minimum to provide 50% of calculated demand (LVOCFPP)
- (ii) duplicated Main Supply Lines (LVOCFPP)
- (iii) calculation based on worst case flow path. (AS 2419)

Friction loss in pipes can be given by the Hazen Williams equation (refer AS 2118, ϕ 12-9)

$$P = \frac{6.05 \times Q^{1.85} \times 10^7}{C^{1.85} \times d^{4.87}}$$

Where

- P = pressure loss (kPa/metre)
- Q = Water flow rate (L/min)
- d = mean internal pipe diameter (mm)
- C = pipe roughness coeff. 120 (mild steel)

This can be simplified as $P = kQ^{1.85}$, for various pipe diameters.

d (mm)	k
1400	4.11×10^{-12}
1000	2.11×10^{-11}
760	8.05×10^{-11}
600	2.54×10^{-10}
450	1.03×10^{-9}
300	7.44×10^{-9}
200	5.36×10^{-8}

Pipe layout is given by SECV drawings LV61/1-3/26F and MS 12-2-1/5/3 and amendments given by Mr W. Brown. The water supply should be adequate for the worst case i.e. the hydraulically most remote location in the worked-out area. A variety of locations were considered as possible supply/demand locations. Valve 303 was selected as the notional 'most remote location' due to its hydraulic disadvantage (highest of the low pressure zone), and its being most distant from the water supplies. Valve 303 is located adjacent to a coal production area (refer to figure 3), but is otherwise considered to represent the 'most remote location' in the worked-out area.

The following trial calculations indicate that a satisfactory supply is available based on the calculation methods discussed above. With the reduced reticulation (as described by W. Brown) the available pressure is reduced by 22% to 580 kPa. This is still considered to be satisfactory.

A trial calculation on losses to valve OB01 has been made. This valve is located at level 0 adjacent to the conveyor transfer point - a vulnerable area. At the nominated flow demand of 325 L/sec, adequate pressure would be available.

75 m x 610 mm (407-404)
 225 m x 450 mm (404-402)
 250 m x 200 mm (402-303)

Total equivalent parallel feed losses = 230 kPa.

Total Friction Loss = 320 kPa
 Available Static Head on Level 3 = 900 kPa
 Computed Residual Pressure @ = 325 L/sec is 580 kPa; is satisfactory.

Refer also to attached calculation sheets/gradient sheets.

1.2.2 DW Pumps/Northern Batters/Valve 303
 (complete reticulation - refer dwg No. MS 12-2-1/5/3)

Flow rate = 325 L/second

Pipe Run (m x mm)	Friction Loss (kPa)
325 m x 1000 mm	0.6
1000 m x 450 mm	89.0
750 m x 610 mm	16.5
550 m x 450 mm	<u>49.0</u>
Total Friction Loss	<u>155.0</u> kPa

Available static head on level 3 = 900 kPa
 Computised minimum residual pressure @ 325 L/sec is 745 kPa; is satisfactory. Note: this is considerably greater than scenario 1.2.1.

1.2.3 D Tank/Southern Batters/Valve 0B01

Flow rate = 325 L/second

Pipe Run (m x mm)	Friction Loss (kPa)
1250 m x 1050 mm	2.3
100 m x 760 mm	0.7
625 m x 450 mm	55.6
175 m x 300 mm	<u>112.5</u>
	<u>169.5</u> kPa

Total Friction Loss = 170.0 say.

Available static head on level 1 = 800 kPa
 Computed Residual Pressure @ 325 L/sec is 630 kPa; is satisfactory.

2. FIRE FUNDAMENTALS

2.1 Mechanism of Fire

The mechanism of fire development should be considered when any review of the LVOCFPP is undertaken. The following aspects of fire development are interdependent:

- effect of fire prevention.
- time for detection of fire.
- time for suppression of fire.

2.2 Morwell Open Cut Mine Brown Coal Characteristics

There is a higher incidence of fires in the Morwell open cut mine, in comparison to Yallourn. Possible reasons for this difference could lie in comparison of the spontaneous ignition properties, ability of the coal to oxidise and the effectiveness of fire suppressants.

A brief consideration of the ignition characteristics of the Morwell and Yallourn coal indicates that, although there is some difference in the ignition temperatures of the coal, these differences are believed to be insignificant with respect to the higher fire incidence rate at the Morwell open cut mine. The Morwell coal has a higher concentration of cations than the Yallourn coal, which leads to slightly lower ignition temperatures. The presence of cations in coal has been identified as a catalyst for the coal oxidation process.

There is some qualitative evidence to suggest that Yallourn coal has a greater tendency to oxidise and spontaneously combust. The Yallourn coal is a younger coal with greater porosity and so presents a greater effective surface area for oxidation.

It may be concluded that the higher incidence of fires at the Morwell open cut mine is possibly then due to factors other than the inherent properties of the coal itself. Geophysical site conditions, work practices, ignition sources, levels of activity and surface area of exposed coal may be more significant influences on the fire risk.

The state of the coal on site may also be an important factor. Brown coal in the weathered state undergoes oxidation with the atmosphere. Where the rate of heat dissipation is less than the heat generation from the oxidation process, combustion can occur. The locality of the exposed coal in the open cut can effect the rate of heat dissipation. Cracks and fissures in the coal, for example in weathered batters, allow oxidation to occur deep in the coal seam with no effective mechanism to dissipate the generated heat, resulting in potential fire sources. Also, loose coal that has been piled or deposited around roads or train lines are another significant ignition source as the coal is aerated and oxidises throughout the coal pile.

The use of water as an effective fire suppressant for brown coal is also limited. As water is used to extinguish a coal fire, the immediate effect is to quench the fire by cooling the coal site and restriction of available oxygen. Due to the fine porosity of the coal, there is little or no penetration of the water into the interior of the coal particles. Once the water has drained from the coal, the interior of the coal is then able to oxidise and dependant on the rate of heat dissipation, combustion can then recur. Wetting agents added to the water can improve the ability of the water to penetrate the coal pores, and so improve the effectiveness of the fire suppression. Localised fires that occur in the coal seam are more effectively dug out and removed.

3. RECOMMENDATIONS

- 3.1 Update reticulation drawing and hydraulic analysis using computer modelling.
- 3.2 Suggest revisions to LVOCFPP:
- (i) 6 mm/hour precipitation rate seems to be based on 1964 report of 0.25 inch/hour. Check appropriateness.
 - (ii) Specify number, distance, capacity requirements for Tanker Filling Points.
 - (iii) Remote monitoring for fire pumps and other critical fire protection equipment.

4. EVALUATION OF APPLICABLE CODES AND STANDARDS.

In addition to the in-house Latrobe Valley Open Cuts Fire Protection Policy (LVOCFPP), there are other codes and standards which may apply. A comparison of these has not been undertaken for this report. It is important to note that the winning of coal by open-cut methods is not the subject of statutory control by Mines Regulations. A large part of the control has been via internal documentation prepared specifically for the conditions in the Latrobe Valley. Comparison with codes prepared in other countries, or for other bodies of coal deposits, may not necessarily be compared with SECV policies.

Other Australian Standards which may apply are:


- AS 1221 Fire Hose Reels
- AS 1603 Automatic Fire Detection and Alarm Systems
- AS 1674 SAA Cutting and Welding Safety Code
- AS 1768 Lightning Protection
- AS 2118 Automatic Fire Sprinkler Systems
- AS 2419 Fire Hydrant Installations
- AS 2441 Installation of Fire Hose Reels
- AS 2444 Portable Fire Extinguishers - Selection and Location
- AS 2941 Fixed Fire Protection Installations - Pumpset Installations

American NFPA Standards which may apply:

- NFPA 121 Standard on Fire Protection for Self-Propelled and Mobile Surface Mining Equipment
- NFPA 123 Standard for Fire Protection and Control in Underground Bituminous Coal Mines
- NFPA 30 Centrifugal Fire Pumps

TOTAL LOSSES ARE
 DW PUMPS → 407: 89.6 kPa
 407 → 303 : 230
319.6 say 320 kPa

355m/1000mm 0.59 kPa
 1000m/450mm 89 kPa
89.6 kPa



@3000 L/min
 FL = 0.05 kPa
 + 0.63
 + 36.29
36.97

FOR 407-303
 FROM CHART 2/2
 @ 40 kPa lost:

Q = 3200
 + 4400
7600 L/min


FL(a) = 58.1 kPa
 FL(b) = 65.3 kPa

Balance @ 50 kPa lost:
 2550 L/min
 2750 " "
5300

M Juncovic 10.6.92

VALVE SUPPLY ANALYSIS GRAPH

NAME OF INSURED SECV / MOC	DATE 6/92	ENGINEER RUNLEVIE	INDEX No. 1 OF 2
--------------------------------------	---------------------	-----------------------------	----------------------------



FLOW - L.P.M.

Estimated Total Water Demand _____ L.P.M. @ _____ kPa. Duration _____ Minutes


Estimated Water Demand for Sprinklers _____ L.P.M. @ _____ kPa. + _____ L.P.M. Hose Streams

AIR SUPPLY ANALYSIS GR.,PH

NAME OF INSURED SECV/MOC	DATE 6/92	ENGINEER DUNLEVIE	INDEX No. 2 of 2
------------------------------------	---------------------	-----------------------------	----------------------------

RICHARD OLIVER

HYDRAULIC GRADIENTS
DW PUMPS / NORTHERN BATTERS / VALVE 303
(REDUCED RETICULATION)



FLOW - L.P.M. @ 400

Estimated Total Water Demand _____ L.P.M. @ _____ kPa. Duration _____ Minutes

Estimated Water Demand for Sprinklers _____ L.P.M. @ _____ kPa. + _____ L.P.M. Hose Streams

RICHARD OLIVER

APPENDIX 4

SUMMARY OF REPORTED FIRES IN WORKED-OUT AREAS OF M.O.C.

SECV MORWELL OPENCUT COALMINE
 FIRE REPORT EXTRACT
 (Nov. '89 to April '92.)

RICHARD OLIVER
 11.06.92
 Page 1.

RELATING TO THE WORKED OUT AREA OF THE MINE

 Report No: A0083 Date: 15.12.89 Time Extinguished: 11.25 Time Completed: 11.25 Alarm time: 11.05
 Location Item No: 24 OTHER (SPECIFY)
 Burning Item No: 25 COAL/PF
 Prob Cause Item A: 37 Prob Cause Item B: HOT WORK(WELD,CUT Description Burning: OLD TRAILING FRAME
 Damage Y/N: N Damage Description: BURNING & WELDING Prob Cause Description: BURNING & WELDING
 Contrib Factor Desc: BURNING & WELDING Contrib Item No: 50 HUMAN INACTION

How Extinguished: PIPED WATER Support ManHours: Equipment Hours: Actual Cost: Cosmos No:

 Report No: A0918 Date: 18.01.90 Time Extinguished: 14.20 Time Completed: 14.25 Alarm time: 14.10
 Location Item No: 24 OTHER (SPECIFY)
 Burning Item No: 31 RUBBISH
 Prob Cause Item A: 37 Prob Cause Item B: HOT WORK(WELD,CUT Description Burning: LARGE RUBBISH BIN
 Damage Y/N: N Damage Description: SPARKS FROM BURNING & WELDING DROPPED IN BIN Prob Cause Description: SPARKS FROM BURNING & WELDING DROPPED IN BIN
 Contrib Factor Desc: HUMAN ACTION Contrib Item No: 49 HUMAN ACTION

How Extinguished: PIPED WATER Support ManHours: Equipment Hours: Actual Cost: Cosmos No:

 Report No: A0938 Date: 14.02.90 Time Extinguished: 9.20 Time Completed: 9.20 Alarm time: 8.45
 Location Item No: 21 ON OR NEAR ROADWAY
 Burning Item No: 25 COAL/PF
 Prob Cause Item A: 37 Prob Cause Item B: HOT WORK(WELD,CUT Description Burning: COAL
 Damage Y/N: N Damage Description: BURNING & WELDING Prob Cause Description: BURNING & WELDING
 Contrib Factor Desc: BURNING & WELDING Contrib Item No: 49 HUMAN ACTION

How Extinguished: WATER TANKER Support ManHours: Equipment Hours: Actual Cost: Cosmos No:

 Report No: A1152 Date: 24.02.90 Time Extinguished: 14.45 Time Completed: 14.40 Alarm time: 14.40
 Location Item No: 22 VEHICLE OR MOBILE PLANT
 Burning Item No: 25 COAL/PF
 Prob Cause Item A: 39 Prob Cause Item B: HOT ENGINE OR EXH Description Burning: 11D64 DOZER
 Damage Y/N: N Damage Description: ENGINE OVERHEATING COAL DUST Prob Cause Description: ENGINE OVERHEATING COAL DUST
 Contrib Factor Desc: FIRE FOUND @ EXHAUST & MOTOR Contrib Item No: 52 DESIGN

How Extinguished: WATER Support ManHours: Equipment Hours: Actual Cost: Cosmos No:

 Report No: A1155 Date: 25.02.90 Time Extinguished: 14.45 Time Completed: 14.45 Alarm time: 14.30
 Location Item No: 21 ON OR NEAR ROADWAY
 Burning Item No: 35 GRASS/SCRUB
 Prob Cause Item A: 47 Prob Cause Item B: UNKNOWN Description Burning: DRY GRASS
 Damage Y/N: N Damage Description: UNKNOWN Prob Cause Description: UNKNOWN
 Contrib Factor Desc: CAUSE UNKNOWN Contrib Item No:

How Extinguished: WATER Support ManHours: 1.00 Equipment Hours: 1.00 Actual Cost: Cosmos No:

SECV MORWELL OPENCUT COALMINE
 FIRE REPORT EXTRACT
 (Nov. '89 to April '92.)

RICHARD OLIVER

11.06.92
 Page 2.

RELATING TO THE WORKED OUT AREA OF THE MINE

Report No: A132? Date: 9.07.90 Time Attend: 9.25 Time Extinguished: 9.25 Time Completed: 9.35 Alarm time: 9.25
 Location Item No: 21 ON OR NEAR ROADWAY
 Burning Item No: 25 COAL/PF Plant Description: 5 LEVEL S/EAST CORNER
 Prob Cause Item A: 37 Prob Cause Item B: HOT WORK(WELD,CUT Description Burning: LOOSE COAL
 Damage Y/N: N Damage Description: Prob Cause Description: BURNING & WELDING
 Contrib Factor Desc: BURNING & WELDING Contrib Item No: 49 HUMAN ACTION

How Extinguished: PIPED WATER Support ManHours: .25 Equipment Hours: Actual Cost: Cosmos No:

Report No: A1530 Date: 29.10.90 Time Attend: 8.30 Time Extinguished: 9.00 Time Completed: 9.00 Alarm time: 8.30
 Location Item No: 21 ON OR NEAR ROADWAY Plant Description: 7 LEVEL NTH EAST CORNER
 Burning Item No: 25 COAL/PF Description Burning: COAL ON SIDE OF ROAD
 Prob Cause Item A: 48 Prob Cause Item B: OTHER (SPECIFY) Prob Cause Description: HOT COAL OFF DUMP TRUCK
 Damage Y/N: N Damage Description: Contrib Item No:

How Extinguished: Support ManHours: .50 Equipment Hours: Actual Cost: Cosmos No:

Report No: A1534 Date: 31.10.90 Time Attend: 11.35 Time Extinguished: 11.40 Time Completed: 11.40 Alarm time: 11.35
 Location Item No: 21 ON OR NEAR ROADWAY Plant Description: 8 LEVEL DUMP DOZER 11G135
 Burning Item No: 25 COAL/PF Description Burning: LOOSE COAL
 Prob Cause Item A: 39 Prob Cause Item B: HOT ENGINE OR EXH Prob Cause Description: LOOSE COAL AROUND EXHAUST
 Damage Y/N: N Damage Description: Contrib Item No: 52 DESIGN

How Extinguished: PIPED WATER Support ManHours: .25 Equipment Hours: Actual Cost: Cosmos No:

Report No: A1539 Date: 6.11.90 Time Attend: 10.50 Time Extinguished: 10.59 Time Completed: 10.59 Alarm time: 10.50
 Location Item No: 22 VEHICLE OR MOBILE PLANT Plant Description: EXCAVATOR 6F23 3 LEVEL N/SIDE
 Burning Item No: 25 COAL/PF Description Burning: LOOSE FINE COAL
 Prob Cause Item A: 39 Prob Cause Item B: HOT ENGINE OR EXH Prob Cause Description: COAL AROUND EXHAUST AREA
 Damage Y/N: N Damage Description: Contrib Item No: 52 DESIGN

How Extinguished: MAN TANKER, 1 DRY POWD.EXTING. Support ManHours: .30 Equipment Hours: Actual Cost: Cosmos No:

Report No: A1571 Date: 2.12.90 Time Attend: 14.00 Time Extinguished: 14.25 Time Completed: 14.25 Alarm time: 14.00
 Location Item No: 3 RAW COAL BUNKER Plant Description: DBL BUNKER HALF WAY ALONG M52 CONVEYOR
 Burning Item No: 25 COAL/PF Description Burning: LOOSE COAL AND GRASS
 Prob Cause Item A: 47 Prob Cause Item B: UNKNOWN Prob Cause Description: UNKNOWN
 Damage Y/N: Y Damage Description: 1 X 64 FIRE HOSE Contrib Item No: 53 ENVIRONMENTAL(WIND,RAIN,S/C)

How Extinguished: PIPED WATER Support ManHours: .75 Equipment Hours: .20 Actual Cost: Cosmos No:

SECV MORWELL OPENCUT COALMINE
FIRE REPORT EXTRACT
(Nov. '89 to April '92.)

RICHARD OLIVER

11.06.92
Page 3.

RELATING TO THE WORKED OUT AREA OF THE MINE

Report No: A1590 Date: 13.12.90 Time Attend: 14.45 Time Extinguished: 14.50 Time Completed: 14.50 Alarm time: 14.45
Location Item No: 21 ON OR NEAR ROADWAY
Burning Item No: 25 COAL/PF
Plant Description: 1 LEVEL A/SIDE
Prob Cause Item A: 39 Prob Cause Item B: HOT ENGINE OR EXH Description Burning: FINE COAL
Damage Y/N: N Damage Description: BUILDUP OF COAL AROUND EXHAUST AREA
Contrib Factor Desc: ENGINE EXHAUST Contrib Item No: 52 DESIGN

How Extinguished: PIPED WATER Support ManHours: .16 Equipment Hours: Actual Cost: Cosmos No:

Report No: A1603 Date: 31.12.90 Time Attend: 12.00 Time Extinguished: 12.25 Time Completed: 12.30 Alarm time: 12.00
Location Item No: 21 ON OR NEAR ROADWAY
Burning Item No: 25 COAL/PF
Plant Description: ON SIDE OF ROADWAY BELOW DBL
Prob Cause Item A: 47 Prob Cause Item B: UNKNOWN Description Burning: COAL AND GRASS
Damage Y/N: N Damage Description: UNKNOWN
Contrib Factor Desc: UNKNOWN Contrib Item No:

How Extinguished: PIPED WATER Support ManHours: 1.50 Equipment Hours: Actual Cost: Cosmos No:

Report No: A1604 Date: 31.12.90 Time Attend: 14.15 Time Extinguished: 14.30 Time Completed: 14.35 Alarm time: 14.15
Location Item No: 21 ON OR NEAR ROADWAY
Burning Item No: 25 COAL/PF
Plant Description: ON SIDE OF ROAD AT DBL
Prob Cause Item A: 47 Prob Cause Item B: UNKNOWN Description Burning: COAL
Damage Y/N: N Damage Description: UNKNOWN
Contrib Factor Desc: UNKNOWN Contrib Item No:

How Extinguished: Support ManHours: 1.00 Equipment Hours: .33 Actual Cost: Cosmos No:

Report No: A1612 Date: 4.01.91 Time Attend: 8.20 Time Extinguished: Time Completed: Alarm time: 8.20
Location Item No: 11 POWER POLE NO./LINE NO.
Burning Item No: 33 ELECT EQUIP
Plant Description:
Prob Cause Item A: 43 Prob Cause Item B: ELECT FAULT-SHORT Description Burning:
Damage Y/N: N Damage Description: EQUIPMENT MALFUNCTION
Contrib Factor Desc: POWER POLE Contrib Item No: 51

How Extinguished: PIPED WATER Support ManHours: 3.00 Equipment Hours: Actual Cost: Cosmos No:

Report No: A1702 Date: 19.02.91 Time Attend: 14.40 Time Extinguished: 14.55 Time Completed: 14.55 Alarm time: 14.40
Location Item No: 22 VEHICLE OR MOBILE PLANT
Burning Item No: 25 COAL/PF
Plant Description: DOZER 11G135 1 LEVEL NORTH SIDE
Prob Cause Item A: 41 Prob Cause Item B: FRICTION(BELT/MAC Description Burning: COAL BUILD UP AROUND BOTTOM OF RADIATOR & FAN B
Damage Y/N: N Damage Description: COAL AROUND BOTTOM OF FAN BELT
Contrib Factor Desc: COAL DUST AROUND FAN BELT Contrib Item No: 52 DESIGN

How Extinguished: PIPED WATER Support ManHours: Equipment Hours: Actual Cost: Cosmos No:

SECV MORWELL OPENCUT COALMINE
FIRE REPORT EXTRACT
(Nov. '89 to April '92.)

RICHARD OLIVER

11.06.92
Page 4.

RELATING TO THE WORKED OUT AREA OF THE MINE

Report No: A1708 Date: 25.02.91 Time Extinguished: .05 Time Completed: .05 Alarm time: 23.45
 Location Item No: 24 OTHER (SPECIFY)
 Burning Item No: 25 COAL/PF
 Prob Cause Item A: 47 Prob Cause Item B:
 Damage Y/N: Y Damage Description: CABLES DAMAGED IN ELE
 Contrib Factor Desc: UNKNOWN
 Plant Description: M24 CONVEYOR H/E 6.6KV ELECTRICAL CUBICLE
 Description Burning: CABLES IN CUBICLES COALDUST IN CUBICLE & ON WALK
 Prob Cause Description: UNKNOWN
 Contrib Item No:

How Extinguished: PIPED WATER Support ManHours: 1.33 Equipment Hours: Actual Cost: Cosmos No:

Report No: A1724 Date: 13.03.91 Time Extinguished: 17.80 Time Completed: 18.00 Alarm time: 17.50
 Location Item No: 21 ON OR NEAR ROADWAY
 Burning Item No: 25 COAL/PF
 Prob Cause Item A: 47 Prob Cause Item B:
 Damage Y/N: NA Damage Description:
 Contrib Factor Desc: UNKNOWN
 Plant Description: LOOSE COAL ON ROAD, LVL 2 METAL BINS
 Description Burning: LOOSE COAL IGNITED ON ROADWAY
 Prob Cause Description: UNKNOWN
 Contrib Item No: 53 ENVIRONMENTAL(WIND,RAIN,S/C)

How Extinguished: PIPED WATER Support ManHours: Equipment Hours: Actual Cost: Cosmos No:

Report No: A1901 Date: 5.08.91 Time Extinguished: 12.45 Time Completed: 12.45 Alarm time: 12.30
 Location Item No: 22 VEHICLE OR MOBILE PLANT
 Burning Item No: 25 COAL/PF
 Prob Cause Item A: 43 Prob Cause Item B:
 Damage Y/N: N Damage Description:
 Contrib Factor Desc: WIRING FROM STARTER MOTOR
 Plant Description: DOZER 11 G134 COAL CARTING AREA NO 2 LVL EAS
 Description Burning: LOOSE COAL IN BELLY PLATE & WIR'G FRM START MTR
 Prob Cause Description: WIRES FROM STARTER MOTOR
 Contrib Item No: 51 EQUIPMENT MALFUNCTION

How Extinguished: 2 DRY POWDER EXTINGUISHERS Support ManHours: 1.00 Equipment Hours: Actual Cost: Cosmos No:

Report No: A1927 Date: 10.09.91 Time Extinguished: 8.10 Time Completed: 8.45 Alarm time: 8.30
 Location Item No: 22 VEHICLE OR MOBILE PLANT
 Burning Item No: 25 COAL/PF
 Prob Cause Item A: 39 Prob Cause Item B:
 Damage Y/N: N Damage Description:
 Contrib Factor Desc: LOOSE COAL AROUND EXHAUST
 Plant Description: DOZER 11G135
 Description Burning: COAL IN AROUND EXHAUST
 Prob Cause Description: COAL ON EXHAUST
 Contrib Item No: 52 DESIGN

How Extinguished: PIPED WATER Support ManHours: 1.00 Equipment Hours: Actual Cost: Cosmos No:

Report No: A1987 Date: 9.12.91 Time Extinguished: 9.55 Time Completed: 9.55 Alarm time: 9.25
 Location Item No: 21 ON OR NEAR ROADWAY
 Burning Item No: 25 COAL/PF
 Prob Cause Item A: 37 Prob Cause Item B:
 Damage Y/N: N Damage Description:
 Contrib Factor Desc: BURNING AND WELDING
 Plant Description: 5 LEVEL SOUTH EAST CORNER
 Description Burning: LOOSE COAL
 Prob Cause Description: BURNING & WELDING
 Contrib Item No: 49 HUMAN ACTION

How Extinguished: MAN TANKER Support ManHours: 1.00 Equipment Hours: .50 Actual Cost: Cosmos No:

SECV MORWELL OPENCUT COALMINE
FIRE REPORT EXTRACT
(Nov. '89 to April '92.)

RICHARD OLIVER
11.06.92
Page 5.

RELATING TO THE WORKED OUT AREA OF THE MINE

=====
Report No: A2065 Date: 7.01.91 Time Attend: 14.35 Time Extinguished: 15.10 Time Completed: 15.10 Alarm time: 14.35
Location Item No: 21 ON OR NEAR ROADWAY Plant Description: 8 LEVEL DUMP
Burning Item No: 25 COAL/PF Description Burning: LOOSE COAL
Prob Cause Item A: 39 Prob Cause Item B: HOT ENGINE OR EXH Prob Cause Description: ENGINE EXHAUST ON UNIDENT
Damage Y/N: N Damage Description: Contrib Item No: 52 DESIGN
Contrib Factor Desc: UNIDENTIFIED VEHICLE EXHAUST

How Extinguished: MAN TANKER Support ManHours: 2.00 Equipment Hours: Actual Cost: Cosmos No:
=====
Report No: A2066 Date: 10.01.92 Time Attend: 8.10 Time Extinguished: 8.40 Time Completed: 8.40 Alarm time: 8.10
Location Item No: 21 ON OR NEAR ROADWAY Plant Description: 8 LEVEL DUMP
Burning Item No: 25 COAL/PF Description Burning: LOOSE COAL
Prob Cause Item A: 44 Prob Cause Item B: SPONTANEOUS COMBU Prob Cause Description: HOT SPOT IN COAL
Damage Y/N: N Damage Description: Contrib Item No: 53 ENVIRONMENTAL(WIND, RAIN, S/C)Contrib Factor Desc: HOT SPOT IN COAL

How Extinguished: MAN TANKER Support ManHours: 2.00 Equipment Hours: Actual Cost: Cosmos No:
=====
Report No: A2078 Date: 17.01.92 Time Attend: 12.00 Time Extinguished: 12.20 Time Completed: 12.20 Alarm time: 12.00
Location Item No: 21 ON OR NEAR ROADWAY Plant Description: 8 LEVEL DUMP
Burning Item No: 25 COAL/PF Description Burning: LOOSE COAL ON DUMP
Prob Cause Item A: 39 Prob Cause Item B: HOT ENGINE OR EXH Prob Cause Description: SUSPECTED VOLVO DUMP TRUC
Damage Y/N: N Damage Description: Contrib Item No: 52 DESIGN
Contrib Factor Desc: SUSPECTED VOLVO DUMP TRUCK

How Extinguished: MAN TANKER Support ManHours: 1.00 Equipment Hours: Actual Cost: Cosmos No:
=====
Report No: A2088 Date: 21.01.92 Time Attend: 11.45 Time Extinguished: 12.10 Time Completed: 12.10 Alarm time: 11.45
Location Item No: 24 OTHER (SPECIFY) Plant Description: M24 CONVEYOR FUSE BOX
Burning Item No: 25 COAL/PF Description Burning: LOOSE COAL ON LEVEL
Prob Cause Item A: 43 Prob Cause Item B: ELECT FAULT-SHORT Prob Cause Description: FUSE BLEW
Damage Y/N: N Damage Description: Contrib Item No: 51 EQUIPMENT MALFUNCTION
Contrib Factor Desc: FUSE BLOWN IN BOX

How Extinguished: PIPED WATER Support ManHours: 1.66 Equipment Hours: Actual Cost: Cosmos No:
=====
Report No: A2254 Date: 1.02.92 Time Attend: 7.50 Time Extinguished: 8.50 Time Completed: 8.50 Alarm time: 7.50
Location Item No: 21 ON OR NEAR ROADWAY Plant Description: BELOW M22 CONV. ON 4 LEVEL EAST SIDE
Burning Item No: 25 COAL/PF Description Burning: LOOSE COAL AT BOTTOM OF COAL BATTER
Prob Cause Item A: 37 Prob Cause Item B: HOT WORK(WELD,CUT Prob Cause Description: BURNING AND WELDING
Damage Y/N: N Damage Description: Contrib Item No: 49 HUMAN ACTION
Contrib Factor Desc: BURNING AND WELDING

How Extinguished: MAN TANKER Support ManHours: 4.00 Equipment Hours: 1.00 Actual Cost: Cosmos No:

SECV MORWELL OPENCUT COALMINE
 FIRE REPORT EXTRACT
 (Nov. 199 to April '92.)

RICHARD OLIVER

11.06.92
 Page 6.

RELATING TO THE WORKED OUT AREA OF THE MINE

Report No: A2256 Date: 31.01.92 Time Attend: 17.10 Time Extinguished: 17.40 Time Completed: 17.40 Alarm time: 17.10
 Location Item No: 21 ON OR NEAR ROADWAY
 Burning Item No: 25 COAL/PF
 Plant Description: BELOW M22 CONV. 4 LEVEL EAST SIDE
 Prob Cause Item A: 37 Prob Cause Item B: HOT WORK(WELD,CUT Description Burning: LOOSE COAL AT BOTTOM OF COAL BATTER.
 Damage Y/N: N Damage Description: BURNING & WELDING
 Contrib Factor Desc: SPARKS FROM BURNING & WELDING Prob Cause Description: BURNING & WELDING
 Contrib Item No: 49 HUMAN ACTION

How Extinguished: TANKER Support ManHours: 1.00 Equipment Hours: .50 Actual Cost: Cosmos No:

Report No: A2257 Date: 5.02.92 Time Attend: 14.00 Time Extinguished: 18.00 Time Completed: 18.00 Alarm time: 14.00
 Location Item No: 21 ON OR NEAR ROADWAY
 Burning Item No: 25 COAL/PF
 Plant Description: 5 Level South East corner
 Prob Cause Item A: 37 Prob Cause Item B: HOT WORK(WELD,CUT Description Burning: loose coal & grass
 Damage Y/N: N Damage Description: BURNING & WELDING
 Contrib Factor Desc: BURNING & WELDING SPARKS Prob Cause Description: Burning & Welding
 Contrib Item No: 49 HUMAN ACTION

How Extinguished: MAN TANKERS Support ManHours: 18.00 Equipment Hours: 5.00 Actual Cost: Cosmos No:

Report No: A2260 Date: 7.02.92 Time Attend: 19.20 Time Extinguished: 19.50 Time Completed: 19.50 Alarm time: 19.20
 Location Item No: 21 ON OR NEAR ROADWAY
 Burning Item No: 25 COAL/PF
 Plant Description: 7 LEVEL EAST SIDE
 Prob Cause Item A: 37 Prob Cause Item B: HOT WORK(WELD,CUT Description Burning: LOOSE COAL UNDER PIPE
 Damage Y/N: N Damage Description: CUTTING 450 DEG. PIPE
 Contrib Factor Desc: CUTTING 450 DEG. PIPE Prob Cause Description: CUTTING 450 DEG. PIPE
 Contrib Item No: 49 HUMAN ACTION

How Extinguished: MAN TANKER Support ManHours: 1.50 Equipment Hours: .50 Actual Cost: Cosmos No:

SUMMARY

Manhours required to extinguish a fire;	Equipment hours required to extinguish a fire;
Average = 2.01 HOURS	Average = 1.13 HOURS
Maximum = 18.00 HOURS	Maximum = 5.00 HOURS
Minimum = .16 HOURS	Minimum = .20 HOURS
Count = 22	Count = 8

Total No. of Fire reports
 for the Worked Out Area = 28

SECV MORWELL OPENCUT COALMINE
FIRE REPORT SUMMARY
(Nov. 189 to April '92)

11.06.92
Page 1.

RELATING TO THE WORKING AREA OF THE MINE

Manhours required to extinguish a fire;

Average = 1.77 Hours Count = 419
Maximum = 154.50 Hours
Minimum = .05 Hours

Total No. of Fire reports
for the Working Area = 534

Equipment hours required to extinguish a fire;

Average = .97 Hours Count = 101
Maximum = 23.00 Hours
Minimum = .08 Hours

RICHARD OLIVER


APPENDIX 5

INITIAL APPRAISAL OF LEGAL RISKS OF CHANGES TO LVOCFPP

PHILLIPS FOX
SOLICITORS

461 BOURKE STREET MELBOURNE 3000 AUSTRALIA
G.P.O. BOX 4301 PP MELBOURNE 3001 AUSTRALIA
TELEPHONE: NATIONAL (03) 604 5555 INTERNATIONAL +613 604 5555 TELEX: AA31931
FACSIMILE: (03) 602 3100 DX 147 MELBOURNE

OUR REF: GRM:OLIV
WRITER'S DIRECT LINE: 604 5693
ENQUIRIES: Geoff Masel
YOUR REF:



4 June, 1992

Mr C Teniswood
Richard Oliver
International Pty Ltd
Box 956G GPO
MELBOURNE 3001

Dear Chris,

Initial Appraisal of Liability -
Risk of Changes to SECV Morwell Fire Policy

I have considered your letter of 2 June, 1992 together with enclosures.

The State Electricity Commission of Victoria is a public authority as defined by Section 3 of the Country Fire Authority Act and it is accordingly bound by Section 43(1)(a) of that Act which provides that "it shall be the duty of.... every public authority to take all practicable steps (including burning) to prevent the occurrence of fires on and to minimise the danger of the spread of fires on or from any land vested in it or under its control or management..."

A duty cast by statute to take all practicable steps has been held to impose a stricter standard than a duty to take all reasonably practicable steps. However, the steps must be possible in the light of current knowledge and invention - Adsett v. K & L Steel Founders & Engineers Ltd (1953) 1 All ER 97; affirmed (1953) 2 All ER 320; Gregson v. Hick Hargreaves & Co Ltd (1955) 3 All ER 507. Steps are practicable if they are precautions which can be taken without

Partners:
Donald Salter
Ian Kirchner
Michael Salter
John Nason
Judith Fairly
Peter Rutherford
Gordon
Brian Magennis
John Nathan
Stephen Newer
Michael Pava
Christina Pridmore
Andrew J. Cosh

Peter Black
John Bolitho
Michael Cain
Steven Smith
Don Magzone
Pamela Moxey-Nairn
Andrew Large Smith
Ewa Peto
John Morrison
Gregory Claxton
Max Anne Harth
Glen Robinson
Richard Hara

Colin Hiley
Paul Duggan
Norman Abrams
Alec Marzoc
Lore Boland
Garry Banks
Christopher Charles
Peter Kenny
Kathleen Howden
S. Rosenzweig

Senior Associates:
Craig Terrill
Phillip Sweeney
Gerard Ryan
Geoffrey Leys
Carolyn Fox
Julie Armstrong
John Molnar
Selwyn Black
Mark Butler
Ray Steddy
Helen O'Brien
Robert Weinstein
Graham Armstrong

Michael Regos
Mark Huntington
Jonathan Officer
Paul Freeman
Michael Holmes
Ian Gilbert
Shane Hird
David Sulverson
Olivia Warren
Lore Bloomer
Giselle Halpin
Sharon Handoo

Consultants:
William Lister
Geoffrey Masel
Jaginder Singh-Pasricha
Margaret Latham
Alan Neister
Alan Russell

Avalon: 255 Elizabeth Street, Sydney 2000 Telephone: (02) 286 8884 Facsimile: (02) 285 4144 Telex: AA24008 DX 107
Perth: The Quadrant 1 William Street Perth WA Telephone: (09) 324 8811 Facsimile: (09) 324 8801 DX 130
Brisbane: 145 Launceston Street Brisbane 4000 Telephone: (07) 851 5033 Facsimile: (07) 859 2086 DX 289
Canberra: London Court 15 London Circuit Canberra 2601 Telephone: (06) 201 8787 Facsimile: (06) 201 8755 DX 5724
Cairns: 15 Lake Street Cairns 4870 Telephone: (070) 31 0036 Facsimile: (070) 31 5587 DX 41296
Auckland: Cur Customs & Albert Streets Auckland, New Zealand Telephone: (649) 303 2019 Facsimile: (649) 303 2311
Wellington: Customhouse Quay, Wellington, New Zealand Telephone: (04) 472 6289 Facsimile: (04) 472 7429
Associated with:
Adelaide: Ross & McCarthy, 19-29 Young Street, Adelaide 5000 Telephone: (08) 210 5811 Facsimile: (08) 231 0014
Port Moresby: Ryan White & Assoc. (P.O. Box 698 Port Moresby, Papua New Guinea) Telephone: (675) 211 788 Facsimile: (675) 211 788

TO: Mr Chris Tenniswood
Richard Oliver International Pty Ltd

Date:

4 June, 1992

practical difficulty - Brooks v. JMP Coats (1984) 1 All ER 702. Because of the high duty cast by a statutory obligation to take all practicable steps it is probable that questions of cost are not relevant to practicability but the test of practicability might otherwise be concerned with available resources - Adsett v. K & L Steel Founders & Engineers Ltd (supra).

It is further provided by Section 47 of the Country Fire Authority Act 1958 that the provisions of sections, including Section 43, "shall be read and construed as in aid of and not in derogation from the provisions of any other Act or law relating to fires or to the careless negligent or criminal use of fire."

There are no relevant specific provisions in the State Electricity Commission Act 1958. Section 43 must not be read in derogation from the common law of negligence casting a duty of care on public authorities to prevent the occurrence of fires and to minimise the danger of the spread of fires on or from any land vested in it or under its control or management. However, the common law duty of care is only to take all reasonably practicable steps and accordingly Section 43 of the Country Fire Authority Act imposes a more stringent obligation. It is the more stringent obligation which must be complied with in respect of any changes to the SECV Morwell fire policy.

In this context it is necessary to consider whether it is practicable to retain Sections 1.04 and 1.05 of the SECV Latrobe Valley Fire Protection Policy for worked out areas and batters. To determine the issue of practicality your analysis will have to determine whether it has been practical in the above sense to apply the policy to worked out areas and batters in the past and, if not, what are the minimum amendments necessary to enable the formulation of a policy which is practicable in the sense that it can be carried out without practical difficulty. If your analysis shows that Sections 1.04 and 1.05 of the policy have been successfully applied in the past to worked out areas and batters this probably proves that the application of the policy to these areas is practicable, even if it may not be reasonably practicable.

In the result, any amendment of the Policy to reduce the stringency of precautions has a potential for an increase in liability for the SECV. This is not to say that such increase in liability may in fact eventuate as legal liability ultimately will depend, not only on the existence of a duty and breach of the duty, but proof of causation of loss by breach of the duty. Your appraisal may well show that the risk of loss caused by amendment of Sections 1.04 and 1.05 in respect to worked out areas and batters is minimal. Nevertheless, even if a fire was not caused by a breach of the duty, evidence of breach of the duty will undoubtedly be undesirable because of its effect on the public and political profile of the SECV.

It does not seem to me that the principles to be applied in determining practicability will vary between an option of exempting worked out areas and batters from Section 1.04 and 1.05 as distinct from an option of modification of the sections.

PHILLIPS FOX.

Continuation sheet no: 3

TO: Mr Chris Tenniswood
Richard Oliver International Pty Ltd

Date: 4 June, 1992

It may be that a risk analysis would show that it has not been practicable to apply Sections 1.04 and 1.05 to worked out areas and batters in the past but if it is practicable to modify the policy that will carry less risk of breach of the legal obligation than an outright exemption from the policy.

I hope this initial appraisal assists you in the drafting of your report. I would be glad to discuss any aspect of it with you at your convenience.

Yours faithfully,



GEOFF MASEL

RICHARD OLIVER

2nd June, 1992

Mr Geoff Masel
Phillips Fox, Solicitors
461 Bourke Street
MELBOURNE VIC 3001

COPY

Dear Geoff,

**RE: INITIAL APPRAISAL OF LIABILITY/RISK OF
CHANGES TO SECV MORWELL FIRE POLICY**

Thank you for your time spent in discussion of this matter. I am very pleased that you can examine the issues and provide an initial appraisal to me by June 11. I am required to submit a draft report on June 12.

The circumstances are this. Morwell Open Cut wants an exemption from the SECV Latrobe Valley Fire Protection Policy, sections 1.1.4 and 1.1.5, for its "worked out" areas and "batters". We are carrying out a risk analysis to see if such exemption is justifiable.

However, the CFA Act (section 43) requires SECV to take steps to prevent and suppress fires. I also understand that the SECV's own Act makes reference(s) to fire mitigation.

Moreover, SECV has a high public and political profile where fire, especially bushfire, is concerned. A fire at Yallourn Open Cut led to a Royal Commission in 1944. A fire at Morwell Open Cut in 1977 was the foundation for the Latrobe Valley Fire Protection Policy (revised in 1984).

Against this background and under these circumstances, I am therefore interested in your views on the increased liability and/or risk of exemption from part of SECV policy, from a legal perspective. Secondly, if a modification (rather than exemption) to the policy with regard to worked-out areas and batters was to be made, what would the key issues be in developing any modification?

I attach a copy of the SECV policy, and also the Royal Commission and Morwell fire reports as general information should you require.

.../2

RICHARD OLIVER INTERNATIONAL PTY. LTD.
A.C.N. 006 256 908

71 Queens Road, Melbourne 3004, Australia
Telephone: (03) 529 5122 Toll Free: 008 335 014 Fax: (03) 521 1634
Correspondence to: Box 956G, GPO Melbourne 3001

Sydney • Adelaide • Perth • Auckland • Wellington • Chicago • Singapore • London

COPY

RICHARD OLIVER

-2-

I appreciate your assistance, Geoff and look forward to your report.

Yours sincerely,

CHRIS TENISWOOD

encl/-

CTSECVPHILFOX.LTR:mg