

Visit Nbr: V00039402266L - AUSTRALIAN POWER PART

Date: 20/06/2012



ENTRY REPORT

WorkSafe Victoria is a division of the Victorian WorkCover Authority

Date: ♦ 20/06/2012 Visit Number: V00039402266L

Issued by Inspector: Marnie Pamela Ross

Phone: 9641 1193

Fax: 9641 1201

Service Method: ♦ Left for a person

Entry Time: 20/06/2012 09:00 AM Departure Time: 20/06/2012 10:30 AM

PLACE ENTERED

ABN: AUSTRALIAN POWER PARTNERS B V & OTHERS
40924759557

Tenement No: MIN5004
BRODBRIBB ROAD
HAZELWOOD 3840
HAZELWOOD POWER

Phone No: 5135 5700 Fax No: 5135 5758

This report given to: ♦ Luc Dietvorst Position: ♦ Employer Representative

Copies to: ♦ John Robinson Position: ♦ Employee

Other people who attended as part of the inspection:

WorkSafe Staff:

Other Persons: Chris Rowe, Graham Matthews (Lend Lease); Darren Grieves

Purpose for entry:

I entered this place to follow up on matters dealt with at a previous visit.

Under section 98(1) of the Occupational Health and Safety Act 2004, I entered your workplace during working hours.

Observations and Actions of the Inspector

1. OHS-0274 : Follow up notice

I visited the workplace to follow up on a visit I conducted on the 05/03/12.

The employer has made some progress in moving towards the moving and repair of the D11 dredger.

Visit Nbr: V00039402256L - AUSTRALIAN POWER PART

Date: 20/06/2012

At the time of this visit the Action Plan that has been developed for removing the discharge boom from the dredger were provided. Lend Lease is the contractor that is managing this process.

Lend Lease has developed Safe Work Method Statements (SWMS) for the shoring up off the tower structure, erecting scaffolding and inserting 20t pins underneath the discharge boom structure to assist with the removal of the boom from the dredger. SWMS 009 has been revised to include all hazards associated with scaffold works. The contractor has also revised the Incident Reporting Procedure to ensure that the reporting process is defined. The structural integrity of these structures has been assessed and is sufficient for this work to commence. The work will commence next week.

Once the discharge boom has been removed further assessment of the structure will be undertaken to ensure that it is stable for moving the dredger to the pad for repair works to commence. The employer has agreed to provide continuous updates to WorkSafe Victoria at each stage of this process.

The continued progress of the employer in the management of this issue will be monitored as the process progresses.

2. **OHS-02752-1 : Follow up notice**
AUSTRALIAN POWER PARTNERS B V & OTHERS is a partnership that is listed as **AUSTRALIAN POWER PARTNERS B V & CISL (HAZELWOOD) PTY LIMITED & HAZELWOOD INVESTMENT COMPANY PTY LIMITED & HAZELWOOD PACIFIC PTY LTD & NATIONAL POWER AUSTRALIA INVESTMENTS LIMITED** under the ABN 40924759557, also trading as **IPR-GDF SUEZ HAZELWOOD**.
3. **OHS-0659 : Follow up notice**
 You are hereby notified that under Section 99(a) of the Occupational Health and Safety Act 2004, during an inspection at **BRIDGEBRIDGE ROAD HAZELWOOD 3840**, I inspected, examined and made enquiries.
4. **OHS-0660 : Follow up notice**
 You are hereby notified that under Section 99(b) of the Occupational Health and Safety Act 2004, during an inspection at this workplace I examined and inspected those documents referenced in the body of this Entry Report or as follows:
 - SWMS 009;
 - Incident Reporting Procedure;
 - Inspection and Test Plan - Demolition and securing of discharge boom document 84A412-001; and
 - D11 Fire Recovery 2012 Preparatory Work For Transfer to Maintenance Site document.

During my visit at the above workplace **AUSTRALIAN POWER PARTNERS B V & OTHERS** voluntarily provided to me the following document: 'D11 Fire Recovery 2012 Preparatory Work For Transfer to Maintenance Site document', which I have taken away from site.

Inspectors proposed follow up action:

Visit Nbr: V00039402266L - AUSTRALIAN POWER PART

Date: 20/06/2012

Other actions taken:

Status of Notices that were monitored during this entry:

Additional Details:

I gave you these documents:

Additional Details:

INTERNAL REVIEW OF CERTAIN INSPECTOR DECISIONS

If you want to apply for internal review of a decision made by an Inspector during this visit, you must lodge the approved application form with the Internal Review Unit within 14 days of the date the decision came to your notice. WorkSafe Victoria (WorkSafe) must conduct the internal review within legislated time frame of either 7 or 14 days depending on the category of reviewable decision. If WorkSafe does not notify you of the internal review decision within the required time, WorkSafe is taken to have made a decision to affirm the reviewable decision. Not all decisions can be internally reviewed and in order to seek internal review of a decision you must be an eligible person.

Application forms for internal review, a list of reviewable decisions and a list of eligible persons are available upon request from a WorkSafe Inspector, WorkSafe Advisory Service on 1800 136089 or they can be downloaded from the website worksafe.vic.gov.au

All applications are to be in approved form and must be received by WorkSafe's Internal Review Unit, Ground Floor, 222 Exhibition Street, Melbourne 3000 in order to be considered.

If you lodge an application for internal review and you do not receive a decision within the required time frame or you receive an Internal Review decision that you are not happy with, you can then apply to Victorian Civil and Administrative Tribunal for external review within 14 days of the date the Internal Review decision or non-decision first came to your attention. Applicants seeking external review must be an eligible person.

You can contact the Internal Review Unit on telephone (03) 8663 5450, fax (03) 8663 5451 or by email at internalreviewunit@worksafe.vic.gov.au

OFFENCE

The following Acts, including any regulations made under them carry varying offences such as failure to meet duties and obligations, non compliance with a notice or direction issued or made by an inspector and hindering or obstructing an inspector in the exercise of their powers:

- * Occupational Health and Safety Act 2004
- * Dangerous Goods Act 1985
- * Equipment (Public Safety) Act 1994

For specific details about offences and subsequent penalties refer to the specific Act or regulation.

FEEDBACK

If you want to contact WorkSafe in relation to this entry by our Inspector other than for Internal Review purposes (see above), please use the following guide:

- * to clarify any matter that is covered by the Entry Report and any associated Notices or Directions contact the issuing Inspector, whose name and contact details appear at the top of this Entry Report.
- * to make comment about any aspect of how this inspection was conducted, contact the inspector's senior management on telephone 9841 1759, fax 9841 1201 or by