

Level 50 Bourke Place 600 Bourke Street Melbourne VIC 3000 Australia

**T** +61 3 9643 4000 **F** +61 3 9643 5999

www.kwm.com

9 May 2014

Dr Elizabeth Lanyon Head of Secretariat Hazelwood Mine Fire Inquiry GPO Box 3460 Gippsland MC Vic 3841 Chris Fox Partner T +61 3 9643 4116

Emily Heffernan Senior Associate T +61 3 9643 4208

#### By courier

Dear Madam.

# Summons for Production of Documents dated 28 April 2014

We refer to the Summons for Production of Documents dated 28 April 2014 ("Summons"), the signed copy of which was provided to us on 29 April 2014.

Enclosed with this letter is a USB containing electronic copies of the documents located by our clients which are responsive to the Summons.

As you will appreciate, the Summons is broad and our clients have only had a limited period in which to search out documents in response to it. The documents provided on the enclosed USB represent our clients' best efforts at responding to the Summons in a timely fashion.

As you will see, a substantial volume of documentation is being provided.

In the interests of providing the documentation to the Board of Inquiry as quickly as possible, our clients have not had an opportunity to identify and mark information in the documents which is confidential or commercially sensitive. Our clients reserve the right to raise any confidentiality, commercial sensitivity or related concerns in respect of any documents or parts thereof, including during the course of the public hearings of the Board of Inquiry, should any of the documents be sought to be tendered.

An index of the documents on the enclosed USB is attached.

In relation to the specific paragraphs of the Summons, we make the following comments (using the numbering used therein):

#### Paragraph 1

Enclosed are reports dated 4 August 1996 or later reviewing or assessing fires at the Hazelwood Coal Mine ("Mine"). The enclosed reports concern:

- major outbreaks of fire;
- operational fires; and
- recommendations arising from fires at the Mine.



9 May 2014

	A Country Fire Authority ("CFA") produced report within our clients' records, has also been supplied. Please note that the redactions within this report were by the CFA.		
Paragraph 2	This category is particularly broad and potentially covers many records, the vast majority of which cannot be relevant to the Inquiry, and which would take a considerable time to locate and supply.		
	The category is also vague and uncertain in a number of respects, for example, by virtue of what is meant by "inspection reports" and "test results".		
	As regards "test results" there are a multitude of things which may fall within this description e.g. movement surveys, data from inclinometers, extensometers, piezometers and standpipes, dewatering records and test results regarding the properties of overburden and coal within the Mine. We do not understand how these sorts of "test results" could be relevant to the Inquiry.		
	In an effort to provide a meaningful response for the purposes of Paragraph 2, enclosed are a series of documents which depict in the 12 months prior to 9 February 2014 the condition of the parts of the Mine in relation to which fire activity occurred on and from 9 February 2014. The documents include:		
	<ul> <li>reports of various geotechnical inspections undertaken within the Mine licence area, containing maps, photographs and descriptions of relevant features; and</li> </ul>		
	<ul> <li>records of grass slashing and other fire preparedness measures undertaken within the Mine throughout the 2013/2014 fire season.</li> </ul>		
	In order to provide an overview of the available data sets within the period of interest, we have provided the following high-level geotechnical reports which include a range of technical data:		
	an annual batter stability report; and		
	a 6 monthly batter performance report.		
	If any specific data sets summarised in these reports which are of interest to the Board of Inquiry, further materials can be supplied.		
	Please refer also to the Environmental Review Committee ("ERC") reports and fortnightly/monthly Environmental Compliance Reports provided in response to Paragraph 6 below. These reports contain further "test results" relevant to the Mine.		
Paragraph 3	The current approved Work Plan in relation to the Mine, being a Work Plan Variation approved on 11 May 2009 has previously been supplied in the volume of materials supplied to the Board on 2 May 2014 at Tab 6.		
	The initial approved Work Plan in relation to the Mine has previously been supplied in the volume of materials supplied to the Board on 2 May 2014 at Tab 1.		
Paragraph 4	Enclosed are records in relation to the following Work Plan Variations:		
	• May 2007;		
	• October 2007;		
	December 2000;		
	February 2001; and		

11828240\_1



Hazelwood	Mine	Fire	Inquiry	1
-----------	------	------	---------	---

	• July 2006.		
	As noted above, the Work Plan Variation approved in May 2009 has previously been supplied in the volume of materials supplied to the Board on 2 May 2014 at Tab 6.		
Paragraph 5	The approved rehabilitation plan for the Mine under Part 7 of the <i>Mineral Resources</i> (Sustainable Development) Act 1990 (Vic) is contained within the Work Plan Variation approved in May 2009, previously supplied to the Board in the volume of materials provided on 2 May 2014 at Tab 6.		
Paragraph 6	No relevant records located.		
Paragraph 7	This category is particularly broad, and covers many records which would take a considerable time to search out and locate.		
	Enclosed are the following reports which have been located describing rehabilitation works undertaken within the Mine, including in the areas that experienced fire activity on and from 9 February 2014:		
	<ul> <li>statistics regarding progressive mine rehabilitation since 1992/1993;</li> </ul>		
	<ul> <li>statutory reports on expenditure and activities under MIN 5004 dated July 2012 and July 2013;</li> </ul>		
	<ul> <li>Hazelwood Mine ERC reports from 2009-2014;</li> </ul>		
	<ul> <li>Monthly Environmental Compliance Reports from 2012-2013;</li> </ul>		
	<ul> <li>Fortnightly Environmental Compliance Reports from 2013-2014; and</li> </ul>		
	<ul> <li>Various plans, drawings and photographs of rehabilitated areas on the southern and northern batters.</li> </ul>		
Paragraph 8	A record of a notifiable incident report made to DSDBI on 9 February 2014 is enclosed.		
Paragraph 9	Enclosed are records of notifiable incidents reported to Worksafe involving mine fire, dated:		
	• 1 August 2011;		
	• 21 January 2012;		
	• 15 May 2012; and		
	9 February 2014.		
Paragraph 10	Enclosed is a record of a risk assessment carried out in relation to the mining hazard of mine fire dated January 2004.		
	A further risk assessment in relation to the mining hazard of mine fire completed in October 2012 was previously supplied to the Board in the volume of materials provided of 2 May 2014, as follows:		
	Tab 26 - OHS Assessment Major Mining Hazard 7 - Mine Fire (Major Fire) — Part 1 of 2		
	Please also refer to Appendix A of the GHD Report provided in response to paragraph 14		



Paragraph 11	Records of the risk control measures adopted in relation to the mining hazard of mine fire were previously supplied to the Board in the volume of materials provided on 2 May 2014, as follows:
	<ul> <li>Tab 26 - OHS Assessment Major Mining Hazard 7 - Mine Fire (Major Fire) – Part 2 of 2.</li> </ul>
Paragraph 12	Enclosed are records of the following reviews conducted in relation to the identification of the mining hazard of mine fire, the assessment of risks to health and safety of that hazard, and the risk control measures adopted:
	<ul> <li>A GHD Interim Report dated 2009 entitled Major Mining Hazards Assessment; and</li> </ul>
	<ul> <li>Minutes of a Working Party review of MMH Mine Fire dated October 2012.</li> </ul>
Paragraph 13	The Safety Management System for the Mine in so far as it relates to the hazard of mine fire comprises:
	<ul> <li>the risk assessment carried out in relation to the mining hazard of mine fire in October 2012, referred to under Paragraph 10 above and previously supplied to the Board; and</li> </ul>
	<ul> <li>the risk control measures adopted in relation to the mining hazard of mine fire, referred to under Paragraph 11 above and previously supplied to the Board.</li> </ul>
	Copies of four reports concerning reviews of the Safety Management System as regards the hazard of mine fire are enclosed.
Paragraph 14	In addition to the documents supplied in response to Paragraphs 10 to 13 above, enclosed are four reports of safety assessments of major mining hazards, including mine fire, conducted in 2004.
Paragraph 15	Please refer to the following document previously supplied to the Board of Inquiry on 2 May 2014:
	Tab 7 - Emergency Response Plan - Hazelwood Mine - revised May 2013.
Paragraph 16	Enclosed are two versions of the plan of the Mine prepared under regulation 5.3.36 of the OHS Regulations.
Paragraph 17	Please refer to the following documents previously supplied to the Board of Inquiry on 2 May 2014:
	Tab 7 - Emergency Response Plan - Hazelwood Mine - revised May 2013;
	Tab 8 - Mine Fire Service Policy and Code of Practice revised July 2013;
	Tab 9 - Hazelwood Mine Fire Instructions issued 27 July 2011;
	Tab 10 - Internal Grass Slashing Specification issued 17 October 2011;
	<ul> <li>Tab 11 - Guidelines For Season &amp; Period Specific Fire Preparedness &amp; Mitigation Planning issued 13 September 2007;</li> </ul>
	<ul> <li>Tab 12 - Check List for Fire Fighting Equipment Annual Inspection issued 18 January 2013;</li> </ul>

un la



9 May 2014

		Planning issued 24 November 2008;
	•	Tab 14 - Check List for Hazelwood Slot Bunker Fire Services Wash Down & Routine Inspection issued 18 January 2013;
	•	Tab 15 - Mine Fireman Assessment issued 24 February 2012;
	•	Tab 16 - Fire Person Duties Training Manual issued 23 August 2012; and
	•	Tab 28 - GDF Suez Hazelwood Electricity Safety - Bushfire Mitigation Plan for period commencing 1 July 2013.
Paragraph 18	Enclos	ed are:
	•	Standing Operating Procedures in relation to CFA District 10 (included in Appendix 1 of the Emergency Response Plan for the Mine);
	•	Central Gippsland Essential Industry Group (CGEIG) Mutual Aid Guidelines dated December 2010; and
	•	Two CFA permits concerning fires on total fire ban days, issued in December 2012 and 2013.

Yours faithfully

Kin Dul



## **INDEX OF MATERIALS**

Description of Document
Paragraph 1 – Materials
01.01 IPH Interim Investigation Report regarding Bunker Fire on 17 October 1997
01.02 IPH Report regarding Mine Fire on 30 Dec 2005
01.03 GHD Report regarding October 2006 Mine Fire
01.04 IPH Report regarding Slot Bunker Fire on 3 April 2005
01.05 IPH 11 Dredger Fire Incident ICAM Final Report (Level 4)
01.06 IPH June 2012 Audit of recommendations arising from previous fires
01.07 Internal Audit Report GHD Mine Fire Recommendations Review
01.08 GHD Mine Fire Recommendations Follow-up Review Jan 2008
01.09 Email dated 6 December 2007 regarding implementation of GHD recommendations
01.10 GHD Report regarding Sept 2008 Mine Fire
01.11 IPH report regarding 2006 Mine fire action plans
01.12 Operational fire reports VOL 1
01.13 Operational fire reports VOL 2
01.14 Operational fire reports VOL 3 (part 1 of 3)
01.15 Operational fire reports VOL 3 (part 2 of 3)
01.16 Operational fire reports VOL 3 (part 3 of 3)
01.17 Operational fire reports VOL 4
01.18 Operational fire reports VOL 5
01.19 Operational fire reports VOL 6
01.20 Operational fire reports VOL 7
01.21 Operational fire reports VOL 8
01.22 Operational fire reports VOL 9



9 May 2014

D----

Description of Document
01.23 Operational fire reports VOL 10
01.24 Operational fire reports VOL 11
01.25 Operational fire reports VOL 12
01.26 Operational fire reports VOL 13
01.27 Operational fire reports VOL 14 (part 1 of 2)
01.28 Operational fire reports VOL 14 (part 2 of 2)
01.29 Operational fire reports VOL 15
01.30 Operational fire reports VOL 16
01.31 Operational fire reports VOL 17 (part 1 of 2)
01.32 Operational fire reports VOL 17 (part 2 of 2)
01.33 Operational fire reports VOL 18 (part 1 of 2)
01.34 Operational fire reports VOL 18 (part 2 of 2)
01.35 Operational fire reports VOL 19 (part 1 of 2)
01.36 Operational fire reports VOL 19 (part 2 of 2)
01.37 Operational fire reports VOL 20 (part 1 of 2)
01.38 Operational fire reports VOL 20 (part 2 of 2)
01.39 Operational fire reports VOL 21 (part 1 of 3)
01.40 Operational fire reports VOL 21 (part 2 of 3)
01.41 Operational fire reports VOL 21 (part 3 of 3)
01.42 Operational fire reports VOL 22 (part 1 of 5)
01.43 Operational fire reports VOL 22 (part 2 of 5)
01.44 Operational fire reports VOL 22 (part 3 of 5)
01.45 Operational fire reports VOL 22 (part 4 of 5)
01.46 Operational fire reports VOL 22 (part 5 of 5)



Description of Document
Paragraph 2 – Materials
02.01 Slashing for Fire Season 2013 2014 -Annexure B - Scope of Works
02.02 Fire prevention slashing and mulch mowing 2013 2014 Layout Plan
02.03 Report on Slashing Progress Week End 07_12_14
02.04 Report on Slashing Progress Week End 12_01_14
02.05 Report on Slashing Progress Week End 05_01_14
02.06 Report on Slashing Progress Week End 15_12_13
02.07 Report on Slashing Progress Week End 29_12_13
02.08 Geotechnical Report - Hazelwood Mine 6 Monthly Batter Reporting November 2013
02.09 Geotechnical Report - Annual Batter Stability Report GDFSuez 26_03_2014
02.10 HWD_040- Geotechnical inspection - Northern Batter Level 1- Road crack and sinkholes
02.11 GH329_R Hazelwood Mine - Geotechnical inspection - Batter instability investigation
02.12 HWD_009 - Geotechnical inspection - Northern Batters-Level 3-Hole in the road
02.13 HWD_010 - Geotechnical inspection - Northern Batters-area above Level 1 road 16 08 2013
02.14 Geotechnical - Morwell Main Drain inspection 20140117
02.15 Geotechnical - Morwell Main Drain inspection 20130808
02.16 Geotechnical - Morwell Main Drain inspection 20130822
02.17 Geotechnical - Morwell Main Drain inspection 20140207
02.18 Geotechnical - Morwell Main Drain inspection 20130905
02.19 Geotechnical - Morwell Main Drain inspection 20130925
02.20 Geotechnical - Morwell Main Drain inspection 20131025
02.21 Geotechnical - Morwell Main Drain inspection 20131107
02.22 Geotechnical - Morwell Main Drain inspection 20131122
02.23 Geotechnical - Morwell Main Drain inspection 20131206



Description of Document
02.24 HWD_044 - Geotechnical inspection Level 5 - Blocked drain
02.25 HWD_011 - Geotechnical inspection Northern Batters-Ramp between Level 1 and grass level
02.26 HWD_017 - Geotechnical inspection Northern Batter Level 1-Drain
02.27 HWD_018- Geotechnical inspection Northern Batter Level 1- Road cracks
02.28 HWD_035- Geotechnical inspection Northern Batter Level 1- Road cracks
02.29 HWD_043 - Geotechnical inspection Northern Batter Level 1-Crack in drain
02.30 HWD_043 - Geotechnical inspection Northern Batter Level 1-Crack in drainV2
02.31 Weekly Geotech report 30.12.2013
02.32 Weekly Geotech Report 30-5-13
02.33 Regular Geotech report 2.08.2013
02.34 Regular Geotech report 6.9.2013
02.35 Regular Geotech report 8.07.2013
02.36 Regular Geotech report 9.08.2013
02.37 Regular Geotech report 11.10.2013
02.38 Regular Geotech report 11.11.2013
02.39 Regular Geotech report 18.07.2013
02.40 Regular Geotech report 20.9.2013
02.41 Regular Geotech report 21.11.2013
02.42 Regular Geotech report 26.07.2013
02.43 Regular Geotech report 30.8.2013
02.44 Weekly Geotech Report 5-4-13
02.45 Weekly Geotech report 6.1.2014
02.46 Weekly Geotech Report 6-6-13
02.47 Weekly Geotech Report 9-5-13



9 May 2014

Description of Document
02.48 Weekly Geotech report 13.1.2014
02.49 Weekly Geotech report 13.12.2013
02.50 Weekly Geotech Report 13-3-13
02.51 Weekly Geotech Report 15-5-13
02.52 Weekly Geotech Report 17-4-13
02.53 Weekly Geotech report 20.1.2014
02.54 Weekly Geotech report 20.12.2013
02.55 Weekly Geotech Report 20-3-13
02.56 Weekly Geotech Report 22-3-13
02.57 Weekly Geotech Report 23-5-13
02.58 Weekly Geotech Report 26-4-13
02.59 Weekly Geotech Report 28-29.1.2014
02.60 Weekly Geotech Report 29.11.2013
Paragraph 4 – Materials
04.01 Approved Work Plan Variation 5 May 1997 - certificate
04.02 Work Plan Variation 20 May 1997 submission stamped
04.03 Approved Work Plan Variation 20 May 1997 certificate
04.04 Work Plan Variation submission 1 October 1997 stamped
04.05 Work Plan Variation 1 October 1997 certificate
04.06 Work Plan Variation 9 October 1997 certificate
04.07 Work Plan Variation 6 December 2000 Body stamped
04.08 Work Plan Variation 6 December 2000 certificate
04.09 WPVar EMP approved 22 February 2001
04.10 WPVar approved 22Feb 2001 certificate



Description of Document
04.11 Instrument of Variation 12 july 2006 5449, 5450, 5451, 5452
Paragraph 7 – Materials
07.01 ERC Performance Report August 2009
07.02 ERC Performance Report for August 2010
07.03 ERC Performance Report for February 2010
07.04 ERC Performance Report for February 2011
07.05 ERC Performance Report for May 2010
07.06 ERC Performance Report for May 2011
07.07 ERC Performance Report for November 2010
07.08 ERC quarterly report Nov 2011
07.09 ERC Report - 2011 Aug Part A
07.10 ERC Report - 2011 Aug Part B
07.11 ERC Report - 2012 Aug Part A
07.12 ERC Report - 2012 Aug Part B
07.13 ERC Report - 2012 Feb Part A
07.14 ERC Report - 2012 Feb Part B
07.15 ERC Report - 2012 May Part A
07.16 ERC Report - 2012 May Part B
07.17 ERC Report - 2012 Nov Part A
07.18 ERC Report - 2012 Nov 12 Part B
07.19 ERC Report - 2013 Aug Part A
07.20 ERC Report - 2013 Aug Part B
07.21 ERC Report - 2014 Feb Part A
07.22 ERC Report - 2014 Feb Part B



Description of Document
07.23 ERC Report May 2013
07.24 ERC Performance Report for February 2009 meeting
07.25 ERC Performance Report for May 2009 meeting
07.26 ERC Performance Report for November 2009 meeting
07.27 ERC Report - 2013 Nov
07.28 Progressive rehabilitation statistics
07.29 2012 MIN5004 Royalty info and Schedule 15 Report
07.30 2013 MIN 5004 Royalty info and Schedule 15 Report
07.31 Mine Environmental Compliance Report Sept 2012
07.32 Hazelwood Mine Environmental Compliance Report April 2012
07.33 Hazelwood Mine Environmental Compliance Report August 2012
07.34 Hazelwood Mine Environmental Compliance Report February 2012
07.35 Hazelwood Mine Environmental Compliance Report January 2012
07.36 Hazelwood Mine Environmental Compliance Report July 2012
07.37 Hazelwood Mine Environmental Compliance Report June 2012
07.38 Hazelwood Mine Environmental Compliance Report March 2012
07.39 Hazelwood Mine Environmental Compliance Report May 2012
07.40 Hazelwood Mine Environmental Compliance Report - Apr 2013
07.41 Hazelwood Mine Environmental Compliance Report- Dec 2012
07.42 Hazelwood Mine Environmental Compliance Report- Feb 2013
07.43 Hazelwood Mine Environmental Compliance Report- Jan 2013
07.44 Hazelwood Mine Environmental Compliance Report - Jun 2013
07.45 Hazelwood Mine Environmental Compliance Report- Mar 2013
07.46 Hazelwood Mine Environmental Compliance Report - May 2013



Description of Document
07.47 Hazelwood Mine Environmental Compliance Report - Nov 2012
07.48 Hazelwood Mine Environmental Compliance Report - Oct 2012
07.49 Fortnightly Enviro Report - Thurs 3 Oct 2013
07.50 Weekly Enviro Report - Thurs 31 Jan 2013
07.51 Weekly Enviro Report - Thurs 28 Mar 2013
07.52 Weekly Enviro Report - Thurs 28 Feb 2013
07.53 Weekly Enviro Report - Thurs 25 Apr 2013
07.54 Weekly Enviro Report - Thurs 24 Jan 2013
07.55 Weekly Enviro Report - Thurs 21 Mar 2013
07.56 Weekly Enviro Report - Thurs 21 Feb 2013
07.57 Weekly Enviro Report - Thurs 18 Apr 2013
07.58 Weekly Enviro Report - Thurs 17 Jan 2013
07.59 Weekly Enviro Report - Thurs 16 May 2013
07.60 Weekly Enviro Report - Thurs 14 Mar 2013
07.61 Weekly Enviro Report - Thurs 14 Feb 2013
07.62 Weekly Enviro Report - Thurs 11 Apr 2013
07.63 Weekly Enviro Report - Thurs 10 Jan 2013
07.64 Weekly Enviro Report - Thurs 9 May 2013
07.65 Weekly Enviro Report - Thurs 7 Mar 2013
07.66 Weekly Enviro Report - Thurs 7 Feb 2013
07.67 Weekly Enviro Report - Thurs 4 Apr 2013
07.68 Weekly Enviro Report - Thurs 3 Jan 2013
07.69 Fortnightly Enviro Report - Thurs 31 Oct 2013
07.70 Fortnightly Enviro Report - Thurs 30 May 2013



Description of Document
07.71 Fortnightly Enviro Report - Thurs 28 Nov 2013
07.72 Fortnightly Enviro Report - Thurs 27 Jun 2013
07.73 Fortnightly Enviro Report - Thurs 25 Jul 2013
07.74 Fortnightly Enviro Report - Thurs 22 Aug 2013
07.75 Fortnightly Enviro Report - Thurs 19 Sept 2013
07.76 Fortnightly Enviro Report - Thurs 17 Oct 2013
07.77 Fortnightly Enviro Report - Thurs 14 Nov 2013
07.78 Fortnightly Enviro Report - Thurs 14 Jun 2013
07.79 Fortnightly Enviro Report - Thurs 11 Jul 2013
07.80 Fortnightly Enviro Report - Thurs 8 Aug 2013
07.81 Fortnightly Enviro Report - Thurs 5 Sept 2013
07.82 Fortnightly Enviro Report - Thurs 23 Jan 2014
07.83 Fortnightly Enviro Report - Thurs 01 May 2014
07.84 Fortnightly Enviro Report - Thurs 3 Apr 2014
07.85 Fortnightly Enviro Report - Thurs 6 Feb 2014
07.86 Fortnightly Enviro Report - Thurs 9 Jan 2014
07.87 Fortnightly Enviro Report - Thurs 12 Dec 2013
07.88 Fortnightly Enviro Report - Thurs 17 Apr 2014
07.89 Fortnightly Enviro Report - Thurs 20 Mar 2014
07.90 Southern Batters Rehab 01_02_2005 DSCF0018
07.91 - Southern Batters Rehab 01_02_2005 DSCF0017
07.92 2013 Rehabilitation Drawing - Southern Batters above 540 conveyors
07.93 Hazelwood Mine - Plans of Rehabilitated Areas
07.94 Rehab 2008_02_11 NE Batters DSCF0002



Description of Document
07.95 Rehab 2008_02_11 NE Batters DSCF0003
07.96 Rehab 2008_02_11 NE Batters DSCF0004
07.97 Rehab 2008_05_13 N BATTERS
07.98 Rehab 2008_08_13 N Batters DSCF0008
07.99 Rehab 2008_08_13 N Batters DSCF0007
07.100 Rehab 2012_05_08 N Batters DSCF1107
07.101 Rehab 2010_10_19 N Batters DSCF0177
07.102 Rehab 2010_10_19 N Batters DSCF0178
07.103 Rehab 2010_10_19 N Batters DSCF0179
Paragraph 8 – Materials
08.01 Notifiable Incident Report - Hazelwood Mine - 9 February 2014
Paragraph 9 – Materials
09.01 WorkSafe Incident Notification Form 1.8.11
09.02 Incident Notification D11 Fire 21.1.12
09.03 Incident Notification Utility Fire 15.5.12
09.04 WorkSafe Incident Notification Mine Fire 9.2.2014
Paragraph 10 – Materials
10.01 Bowtie MMH 7 Mine Fire 2004
10.02 Bowtie MMH 7 Mine Fire 2012 page 1
10.03 Bowtie MMH 7 Mine Fire 2012 page 2
Paragraph 11 – Materials
11.01 0001 Competent Maintenance Personnel
11.02 0005 Emergency Response Plan 2895
11.03 0006 First Aiders on all Shifts

Daga 10



Description of Document
11.04 0007 PPE
11.05 0008 Onsite Emergency Response Provider
11.06 0009 First Aid Room on Site
11.07 0014 Mine Site Induction
11.08 0019 Electrical drawings
11.09 0049 Equip Control Devices limit switches sensors etc
11.10 0052 Standard - Works Management System
11.11 0057 Site Design Standard for Plant
11.12 0058 Site Engineering standard for introduction or removal of plant
11.13 0061 Inspection - Safety Walks
11.14 0062 Maintenance - daily cleaning or on request
11.15 0063 Design to prevent spillage
11.16 0064 Procedure - Permit System Hot Work - Fire Training Manual
11.17 0065 Inspection - Follow-up Inspections
11.18 0066 Procedure - Fireman spotter for hotwork
11.19 0068 Policy - Prohibited items on site
11.20 0069 Procedure - Mine Fire Reporting Fire Instructions
11.21 0070 Maintenance - Grass Cutting
11.22 0071 Design - Fire Breaks (Fire Services Policy & Code of
11.23 0072 Designated Fuel Storage Area
11.24 0073 Procedure - Weather monitoring fire hazard
11.25 Maintenance - Housekeeping Audit Program
11.26 0075 Procedure Covering of waste coal on the overburden dump coal
11.27 0079 Aust Stands and Codes for Storage Handling of Flammable



Description of Document
11.28 0080 Guideline - Material Safety Data Sheets
11.29 0082 Design - Earthing Systems
11.30 0086 Design - IP rated electrical equipment
11.31 0087 Standard - Australian Standards Regulation
11.32 0088 Standard - Site Standard for Cable Management
11.33 0089 Standard - Site Design Standard for Electrical Equipment
11.34 0099 Pre start Checks and recording
11.35 Contractor Management Process
11.36 Maintenance - Plant Preventative Maintenance Program
11.37 0132 Lubrication
11.38 0151 Shiftly Fault Inspections
11.39 0167 Fire Suppression Systems
11.40 0184 Design - Conveyor systems
11.41 0218 Access to Emergency Services
11.42 0232 Safety Device Testing Program
11.43 0270 Electrical Protection Systems
11.44 0283 Fire Kits in all Vehicles Plant
11.45 0284 Fire Hydrants Sprays located near all plant
11.46 0285 SDT of machine fire system
11.47 0287 CITEC Fire Alert System
11.48 0288 Annual Fire Safety Audits
11.49 0289 Fire Preparedness Plan
11.50 0290 Daily Preparedness Plan
11.51 0291 Training - annual Fire

Pane 12 I I . A



Description of Document
11.52 0294 Fire Suppression in cubicles
11.53 0301 Environmental Audits
11.54 0302 Thermal Imaging
11.55 0303 Visual Hot Spot Monitoring
11.56 0305 Modified Exhaust Policy
11.57 0306 Water Washers and Underbody Wash
11.58 0307 Policy - Mine Smoking
11.59 0308 Procedure - Bunker Wash
11.60 0309 Temperature Monitoring Trips of Critical Components
11.61 0312 Steel Structures Electrical Earthed. was oh earthing conductors on above ground 6.6 feeders
11.62 0313 Surge Diverters Lightning arrestors on plant
11.63 0314 Electricians on site 24 July for defect repair isolation
11.64 0330 Fault Reporting and Recording System
11.65 0330 Procedure - Defect Reporting
11.66 0341 Competent and or licensed operators
11.67 0351 Supervision
11.68 0354 Plant Modification System
11.69 0381 JSA comp
11.70 0395 Licenced Electricians
11.71 0403 Operational Cleaning
11.72 0415 Condition Monitoring
11.73 0444 CO Monitoring as part of Emergency Response Plan
11.74 0445 Fire Tankers on Site
11.75 0446 Specialised equipment for fighting mine fires on batters

Page 13 V.h.



Description of Document
11.76 0447 Fire Response Provider
11.77 0468 Fire Policy and Procedure
11.78 0468 Mine Fire Services Policy and Code of Practice
11.79 0470 Fire Instructions
11.80 xxxx Belt alignment & tracking
11.81 xxxx Bunker mist sprays
11.82 xxxx Incorrect wiring of devices
11.83 xxxxx Dredger Dig Load Limiter
11.84 XXXXX Small petrol engines in mine refuelling procedure
11.85 xxxxxx Anchor points moving
11.86 xxxxxx Fixed monitors at transfer points of high spill areas
Paragraph 12 – Materials
12.01 GHD Interim Report 20091222 Major Mining Hazards Assessment- GHD176180
12.02 Minutes of WP review of MMH Mine Fire
Paragraph 13 – Materials
13.01 Worksafe Verification Findings Report Hazelwood Mine MIN5004 June 2012
13.02 Worksafe Improvement Notice MMH Safety Assessment 21.6.12
13.03 IPH Action Plan dated 24 September 2012 re Worksafe Verification Report
13.04 Worksafe Entry Report MMH Fire Sign Off 8.10.2012
Paragraph 14 – Materials
14.01 IPRH MMH Safety Assessment - Stage 1 HAZID Report
14.02 IPRH MMH Safety Assessment - Stage 2 SQRA Report
14.03 IRPH MMH Safety Assessment - Stage 3 Report
14.04 Executive Summary - IPRH MMH Safety Assessment



9 May 2014

Description of Document
Paragraph 16 – Materials
16.01 Plan of Mine OHS Regulations M134D018
16.02 Plan of Mine OHS Regulations M134D018B
Paragraph 17 – Materials
17.01 GDF Suez Hazelwood - Electricity Safety Bushfire Mitigation Plan for period commencing 1 July 2013
Paragraph 18 – Materials
18.01 Standing Operating Procedure Region 10 - Appendix 1 of ERP - version reviewed 20 August 2007
18.02 CGEIG Mutual Aid Guidelines 2010

18.03 GDF Suez Energy Australia-Hazelwood CFA Permit dated 1 December 2013

18.04 GDF Suez Energy Australia - Hazelwood CFA Permit dated 6 December 2012

Dans 15 Vill