

J.M.C. → G.M.C.

DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENT
MINERALS AND PETROLEUM REGULATION

Instruction Notice/Inspection Report
MRDA 1990 Section 110 EIDA 1995 Section 48

0031

To: ALCOA ANGLESEA
(Name of Owner/Manager)

An inspection of the Mine/Quarry:-Licence/Work Authority No _____ located at ANGLESEA

As a result of this inspection the following report is made/directive/s-is/are issued and is/are to be complied with by the _____

AS A RESULT OF THE INCIDENT INVOLVING THE CAT 775 REAR DUMPER ON 4/3/05 THE FOLLOWING DIRECTIVES ARE ISSUED:

1. RECOVER OF REAR DUMPER

A JSA MUST BE DEVELOPED TO ENABLE
i/ THE SAFE UNLOADING AND REMOVAL OF OVERBURDEN FROM THE TRAY.
THIS WORK CAN BE UNDERTAKEN EFFECTIVE IMMEDIATELY.

ii/ THE PROPOSED SAFE RELOCATION OF THE TRUCK BY CRANE ON OR AFTER 7 MARCH 2005 AND WHEN WEATHER CONDITIONS PERMIT.

2. SPEED LIMITS

i/ APPROPRIATE SPEED LIMITS ARE TO BE DETERMINED FOR ALL TRAFFICABLE AREAS AND ARE TO BE ENFORCED EFFECTIVE IMMEDIATELY AND COMMUNICATED TO ALL RELEVANT PERSONNEL

ii/ SPEED LIMITS ARE TO BE SIGNPOSTED

NOTE SPEED LIMITS MUST CONSIDER ALL RELEVANT FACTORS INCLUDING CAMBER, SURFACING, WIDTH, SLOPE, CURVATURE ETC.

ADDITIONAL INSTRUCTIONS MAY BE ISSUED WHEN INVESTIGATION HAS BEEN COMPLETED

INSPECTOR
PRINT NAME JAN M'LEOD
SIGNATURE [Signature]

OWNER/MANAGER
PRINT NAME _____
SIGNATURE _____

DATE 5/3/05

TIME _____ AM/PM