		KG	IVI-0	)								
Victoria		Field Report										
Earth Resources Regulation Victoria		Report No:	В	Α	0	1	1	4	0	0	3	9
			(Inspector User ID) (Year 00)				(Number)					
Visit Date:	02/06/2014	Tenement No:	MI	N	ļ		)A		Dist	rict:	S	W
			(Тур	e)		(Numbe	er)				•	I
Site Details												
Site Name:		Alcoa of Australia										
Site Address:		Coalmine Road/Camp Road Anglesea										
Tenement Holder / Site Operator Name/Address:												
Contacts:	_											
Tenement Ho Representativ		Stewart Esdale (Power Station Manager), Chris Rolland (Mine Manager), Lisa Malis (Environmental Scientist), Kate Betts (Communications Relations)										
Other Persons: Community (Helen - Angair, Chris, Peter, David, Andrew)												

## Observations;

On 02/06/2014 I attended the Anglesea Community Consultation Nework Meeting at the Anglesea Community House.

EPA Steve Landsell, Surf Coast Shire

The following was noted;

Safety – 1 recordable injury this year to date

**Environment** – SO2 6 sites no exceedences. Community concern was raised in relation to levels and requested data. It was explained that they are within their EPA licence limits which are also NATA accredited. It was advised monthly data is available on the website once validated. A human health assessment was also undertaken last year.

Ambient particulate monitoring program (July 2012-March 2014) – no exceedence of PM10. Elevated levels of PM10 and PM2.5 during isolated evens (burns.fires). Rated good and very good in the EPA Air Quality Index at 3 sites.

**Spontaneous combustion event** discovered this morning (started overnight). Detected, dog out and extinguished within 2 hours. Fog this morning caused an increase in community complaints. Have a management plan to deal with occurrences.

**Fire planning** meeting undertaken with Alcoa, Surf Coast and CGA on 13/05/2014 to look at potential impacts. Discussed differences between Alcoa and Morwell. CFA has copy of the Emergency plan for review to ensure fire components are addressed. Training exercise is planned for this year to coincide with the updated plan.

**EPA desktop compliance audit** on Annual Performance Statement 2013/2014 – focus on monitoring appropriate for the level of risk, well documented and meet EPA requirements. 1 recommended action to increase procedure.

**National Pollutant Inventory** (2012/2013) – sources identified include coal, fuel combustion and vehicle movements. Added additional sources post internal review (no expected fugitive emissions to leave site). All results available on NPI website. **Social update** – BATA clean up April event. Community grants available now.

Business – Generation licence granted – generate 160 MW/year. Point Henry wind down June and to be closed by July. Licence will be able to sell into national grid. Sale process ongoing and EOI commenced.

SC Shire advised put a motion to the Federal Minister for the Environment to look at decommissioning and clean up of site – serious SO2 issues.

## Report Issued By:

Inspector / Authorised Officer:		Bessie Abbott		Elaboat						
Address: 402-406 Mair Street BALLARAT VIC 3350										
Telephone:	03 5336 6804	Mobile: 0447 391 274	E-mail:	Bessie.abbott@dsdbi.vic.gov.au						
Service method: File										